

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/2023/WZ/EH/ 53

Dated: 07/0 1/2023

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Jannat The Heaven (A Unit of Shree Shyam Enterprises) Unit No.202 to 217, 2<sup>nd</sup> floor, Manglam Place Manglam Paradise Mall, Sector-3, Rohini, Delhi-110085, is running at in a mall 2<sup>th</sup> floor comprised of Basement + Ground + 05 upper floors, has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/WZ/2020/16 dated 13.01.2020. The premises was re-inspected by the officer concerned of this department on 01.02.2023 in the presence of Mr. Rajbir Singh (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group D "Assembly" (Eating House) for Unit No.202 to 217, 2<sup>nd</sup> floor with effect from 07/09/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(Dhrampat Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

ON

Conditions for the validity of fire safety certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

1	200	address of the building	INSPECT	TON REPORT				
N	anie	and of the building	· Jannat I	Jannat The Heaven (A II )				
1			No.202 t	o 217, 2 <sup>nd</sup> floor Manglam	e Snyam Enterp	rises) Unit		
Tu	me of (	Decupancy	Mall, Sec	ctor-3 Robini Dalbi 11000				
E .	pe of C	Pace	: Group D	Assembly Building (Fait	J.			
		f Previous NOC		Assembly Building (Eating House) [Restaurant is running at Unit No.202 to 217, 2 <sup>nd</sup> floor				
4. De	Safat	ty directions NOC	: F.6/DFS/	MS/EH/WZ/2020/16 dated 13.01.2020				
Fir	to of in	ty directives letter No	: F6/DFS/N	MS/BP/2008/1100 dated 16	113.01.2020			
. Da . Na	mo of	nspection	: 01.02.202	23	0/04/2008			
. Na	me or	Inspecting Officer		rma ADO (Rohini)				
. Na	me and	d designation of officers		(Rollin)				
Va	on the	building side	: Mr. Raibi	ir Singh (Manager)				
. 16	ar or C	Construction	: 2015	origin (manager)				
U. A	ppiica	nt's letter No.	: Online ap	plication No 20230116006	50 datad 17.01.20	000		
5. No.				UBBL/NBC Provided at Remarks				
	anu	ire safety U/R 33		D. ·	Provided at	Remarks		
1.	Acc	ess to building[Manglam	Place Mano	lam Davadias Mall C	site	MR/NMI		
	No.		2 dated 24.06.	2022]	or-3, issued FS	C vide let		
		<ul> <li>Road width</li> </ul>						
		<ul> <li>Gate width</li> </ul>		Restaurant within Mall	As Above	MR		
		<ul> <li>Width of internal road</li> </ul>			110110010	IVIIC		
	Number, Width, Type & Arrangement of Exits[Provided & Maintained by Mall management]							
	a. 1	lumber of staircases	8	- I TO TIAGE & ITAMINAN	Va by Mail mailag	zementj		
		<ul> <li>Upper Floors</li> </ul>		Restaurant within mall	As Above	MR		
		Basements		Restaurant within mall	As Above	MR		
	b. Width of staircases			restaurant within man	ASAUOVC	IVIX		
	• Upper Floor			Restaurant within mall	As Above	MR		
	Basements			Restaurant within mall				
	c. Protection of exits			Restaurant within mail	As Above	MR		
				D		1.00		
	Fire check door			Restaurant within mall	As Above	MR		
		Pressurization		Restaurant within mall	As Above	MR		
		No. of continuous staircases	to terrace	Restaurant within mall	As Above	MR		
	e.	Width of Corridor		Restaurant within mall	As Above	MR		
	f.	Door Size		2m & 1.5m	Provided	MR		
,	Compartmentation							
		Fire check door		Restaurant within mall	As Above	MR		
		Sealing of electrical shafts		Restaurant within mall	As Above	MR		
		Fire Rating of shaft door	•	Restaurant within mall	As Above	MR		
	١,	Water Curtain		Restaurant within mall	As Above	MR		
		Fire Dampers		Restaurant within mall	As Above	MR		
	Smo	ke Management System[P	rovided & Ma					
		Basements		Restaurant within mall	As Above	MR		
				12 a/c per hour	As Above	MR		
	• Upper floors		12 w o p o s a a a a					
	Fire Extinguishers			05nos.	05nos.	MR		
	Total numbers		ABC/CO2	ABC-05nos.	MR			
	Types		ISI marked	Yes	MR			
		IS marking		151 marked	103			
	First-Aid Hose Reels  Total numbers on each floor			01 near to restaurant	As Above	MR		
	•		001	30mm	As Above	MR		
	•	Length of hose reel hose		5m	As Above	MR		
	•	Nozzle diameter	larming system	m[Provided & Maintained b	y Mall managem	ent]		
	Nozzle diameter  Automatic fire detection and alarming system  There of detectors				Provided	MR		
•	Auto	Type of detectors		Required	11011464	MR		

	Location of Repeater Panel	Restaurant within mall	As Above				
	Alternate source of power     Hooters' Location	Restaurant within mall	As Above	W 50.			
8.	Hooters' Location     MOEFA	Restaurant within mall	As Above	MR			
9.		Required	Provided	MR			
10.	Public Address System		Provided	MR			
	Automatic Sprinkler System [Provided & Ma  Basement	MR					
		Restaurant within mall	As Above				
	ordand & Opper Floors	Restaurant within mall	As Above	MR			
11.	Sprinkler above false ceiling     Internal Hydroxet IP.	<b>D</b>	As Above	MR			
	Internal Hydrants [Provided & Maintained by  • Size of riser/down-comer	713 7100VC	MR				
	113el/down-comer	100mm	As Above	100			
	<ul><li>Number of hydrants per floor</li><li>Hose Box</li></ul>	One(near to Restaurant)	As Above	MR			
12.	Vard Hydranta[Drawit 1 1 0 2 4	0	As Above	MR			
	Yard Hydrants[Provided & Maintained by Ma	all management]	110070	MR			
	rotal number of nydrants	Restaurant within mall	As Above	1 10			
13.		D .	As Above	MR			
	Pumping Arrangements [Provided & Maintain  Ground Level	ned by Mall management	As Above	MR			
	Devel	Restaurant within mall	As Above				
	<ul><li>Discharge of main Pump</li></ul>	Restaurant within mall	As Above As Above	MR			
	Head of Main pump	Restaurant within mall		MR			
	Number of main pumps	Restaurant within mall	As Above	MR			
	> Jockey Pump out put		As Above	MR			
	> Jockey pump head	Restaurant within mall	As Above	MR			
	Standby Pump out put	Restaurant within mall	As Above	MR			
	Standby Pump Head	Restaurant within mall	As Above	MR			
	Auto Starting/Manual Start	Restaurant within mall	As Above	MR			
	vialiual Stopping	Restaurant within mall	As Above	MR			
	➤ Pump House Access	Restaurant within mall					
	Terrace level	within man	As Above	MR			
	Discharge of pump	NA					
	Head of the pump	NA NA	As Above	MR			
	Power Supply	Required	As Above	MR			
	Auto Starting of pump	2	As Above	MR			
14.	Captive Water Storage for fire fighting [Prov	vided & Maintained by Mai	As Above	MR			
	Underground tank capacity	Doots with intended by Mai					
	Draw-off connection	Restaurant within mall	As Above	MR			
	Fire service inlet	Restaurant within mall	As Above	MR			
	Access to tank	Restaurant within mall	As Above	MR			
	Overhead Tank capacity	Restaurant within mall	As Above	MR			
15.		Restaurant within mall	As Above	MR			
	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts. [Provided & Maintained by Mall management]						
	to race a maintained by	anagement					
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> </ul>	Restaurant within mall Restaurant within mall	As Above	MR MR			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> </ul>	Restaurant within mall Restaurant within mall					
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> </ul>	Restaurant within mall Restaurant within mall	As Above	MR MR			
1.5	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	Restaurant within mall Restaurant within mall Restaurant within mall Restaurant within mall	As Above As Above As Above	MR MR MR			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul> Standby power supply	Restaurant within mall	As Above As Above As Above	MR MR MR MR			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul> Standby power supply	Restaurant within mall	As Above As Above As Above	MR MR MR			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	Restaurant within mall Required management]	As Above As Above As Above Provided	MR MR MR MR			
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> <li>Standby power supply</li> <li>Refuge Area. [Provided &amp; Maintained by Mall</li> <li>Total Area</li> <li>Location</li> </ul>	Restaurant within mall Required management] NA	As Above As Above As Above Provided	MR MR MR MR			
18.	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> <li>Standby power supply</li> <li>Refuge Area. [Provided &amp; Maintained by Mall</li> <li>Total Area</li> <li>Location</li> </ul>	Restaurant within mall Required management] NA	As Above As Above As Above Provided	MR MR MR MR MR			
18.	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> <li>Standby power supply</li> <li>Refuge Area. [Provided &amp; Maintained by Mall</li> <li>Total Area</li> <li>Location</li> <li>Fire Control Room[Provided &amp; Maintained by</li> </ul>	Restaurant within mall Required management] NA	As Above As Above As Above Provided	MR MR MR MR MR			
18.	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> <li>Standby power supply</li> <li>Refuge Area. [Provided &amp; Maintained by Mall</li> <li>Total Area</li> <li>Location</li> <li>Fire Control Room[Provided &amp; Maintained by</li> <li>Detector System Panel</li> </ul>	Restaurant within mall Required management] NA	As Above As Above As Above Provided	MR MR MR MR MR MR NA			
17. 18.	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> <li>Standby power supply</li> <li>Refuge Area. [Provided &amp; Maintained by Mall</li> <li>Total Area</li> <li>Location</li> <li>Fire Control Room[Provided &amp; Maintained by</li> <li>Detector System Panel</li> <li>Flow Switch Panel</li> </ul>	Restaurant within mall Required management]  NA NA Mall management]	As Above As Above As Above As Above Provided  NA NA	MR MR MR MR MR MR NA NA			
18.	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> <li>Standby power supply</li> <li>Refuge Area. [Provided &amp; Maintained by Mall</li> <li>Total Area</li> <li>Location</li> <li>Fire Control Room[Provided &amp; Maintained by</li> <li>Detector System Panel</li> </ul>	Restaurant within mall Required management]  NA NA Mall management]  NA	As Above As Above As Above As Above Provided  NA NA	MR MR MR MR MR MR NA			

Restaurant within mall As Above Battery backup MR **Building Floor Plans** Special Fire Protection System for NA NA NA Protection of special Risks, if any:

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/EH/WZ/2020/16 dated 13.01.2020 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

bove

re

e

Fi Letter 6 put up for Kind perus and and Degration Blease.

ALDI Rohimi

ploceled hahr