GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI AZAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2023/WZ/EH/ 256

Dated: 11 08 2023

FIRE SAFETY CERTIFICATE

Certified that the M/s Chandrabadani, Shop No. GA-09, Metro Walk, Rohini, Sector-10, Delhi-110085, restaurant is running at ground floor in a mall building comprised of AB & C blocks, Basement + Ground + one upper floor & D Block Basement + ground floor was inspected by the officer concerned of this department on 27.07.2023 in the presence of Sh. B. L. Raju (Manager) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premise is fit for occupancy Group D "Assembly" (Eating House) for GA-09, ground floor for with effect from 11 08 2023 for a period of 03 (Three) years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... [1 | 08 | 2023. at New Delhi by

DIRECTOR Ph; 011-23414000

1. Copy to: MHA Id- 2023071612617

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management/occupier.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building: M/s ChandraBadani, Shop No. GA-09, Metro Walk, Rohini,

Sector-10, Delhi-110085

: Assembly (Restaurant is running GA-09 ground floor)

 Type of Occupancy
 Type of Case : New Case 4. Details of Previous NOC : NA

5. Fire Safety directives letter No : NBC Part-IV 6. Date of inspection :7. Name of Inspecting Officer :8. Name and designation of officers : 27.07.2023

: A.K.Sharma ADO (Rohini)

From the building side : Sh. B. L. Raju (Manager)

9. Year of Construction

S. No.	Minimum Standards on fire prevention	Deswinsment	Provided at site	MR/NMR			
	Access to building [Amusement Park Adventure island metro walk issued FSC vide l No.F.6/DFS/MS/WZ/2022/427 dated 22.11.2020]						
	 Road width Gate width Width of internal road 	Restaurant within	Mall As Above	e i MR			
2.	Number, Width, Type & Arrangement of E	exits	Transport of the	2 年 日			
147	d. Number of staircases	The second secon	NA NA	MR			
	Upper Floors	Restaurant within		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
	Basements	Restaurant within	NA AS AUGV	112311-1			
	e. Width of staircases	Restaurant within	mall As Abov	e MR			
	• Upper Floor			1 (2) 46次 []			
	Basements	Restaurant within	mall As Abov	e IVIK			
	f. Protection of exits	-	NA As Abov	e MR			
	Fire check door	Restaurant within		1.3 [20]			
	Pressurization	Restaurant within					
	d. No. of continuous staircases to terrace	Restaurant within					
	e. Width of Corridor	1.50m	2 x 1.5	3 5 5 5			
	f. Door Size	1.50m	2 X 1.3	IVIIC			
3.	Compartmentation			July 255. *			
	Fire check door	Required	Provide	1 9 9			
	Sealing of electrical shafts	Restaurant within	NA As Abov	ve MR			
	Fire Rating of shaft door	Restaurant withir	NA As Abov	ve MR			
	Water Curtain	Restaurant within		ve MR			
	Fire Dampers	Restaurant within	NA As Abov	ve MR			
4.	Smoke Management System						
	Basements	Restaurant within	mall As Abo	ve MR			
	Upper floors	Restaurant within	mall As Abo	ve MR			
5.	Fire Extinguishers						
J.	Total numbers	04nos.	048nos	s. MR			
	Types	ABC/CO2	ABC-0				
	IS marking	ISI marked	Yes	MR			
6.	First-Aid Hose Reels	X 27 16 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
1.7	Total numbers on each floor	01 near to restar					
	Length of hose reel hose	30mm	As Abo	ve MR			
	Nozzle diameter	5m	As Abo	ove MF			
7.	Automatic fire detection and alarming system						
	Type of detectors	Required	Provid				
	Location of Main Panel	NA	As Abo	ove NA			
	Location of Repeater Panel	NA	As Abo	ove NA			



1-	1 All-		111.11					
	Alternate source of power Hooters' Location	NA	As Above	NA				
8.	MOEFA	NA	As Above	NA				
9.	Public Address System	Required	Provided	MR				
10.	Automatic Sprinkler System[Provided & M	Required	Provided	MR				
	Automatic Sprinkler System[Provided & Maintained by Mall management] Basement NA As Above NA							
-	Ground & Upper Floors	NA		NA				
	 Sprinkler above false ceiling 	NA	As Above	NA				
11.	Internal Hydrants[Provided & Maintained b	y Mall management	As Above	NA				
	Size of riser/down-comer	100mm	As Above	MD				
	 Number of hydrants per floor 	One(near to Restaurant)	As Above	MR MR				
	Hose Box	One(near to Restaurant)		MR				
12.	Yard Hydrants[Provided & Maintained by Mall management]							
	Total number of hydrants	Restaurant within mall	As Above	MR				
13.	Hose Box	Restaurant within mall	As Above	MR				
15.	Pumping Arrangements Provided & Maintained by Mall management							
		Restaurant within mall	As Above	MR				
	Discharge of main Pump	Restaurant within mall	As Above	MR				
	> Head of Main pump	Restaurant within mall	As Above	MR				
	Number of main pumps	Restaurant within mall	As Above	MR				
	> Jockey Pump out put	Restaurant within mall	As Above	MR				
	> Jockey pump head	Restaurant within mall	As Above	MR				
	Standby Pump out put	Restaurant within mall	As Above	MR				
	Standby Pump Head	Restaurant within mall	As Above	MR				
	➤ Auto Starting/Manual Stopping	Restaurant within mall	As Above	MR				
IV .	Pump House Access	Restaurant within mall	and the second s	- FORWARD				
	Ierrace level Provided & Maintained by Mall							
	Discharge of pump	NA						
	Head of the pump	NA	As Above	MR				
	> Power Supply > Auto Starting of pump	Required	As Above As Above	MR				
14.	or pump	Required	As Above	MR MR				
	Captive Water Storage for fire fighting		110110010	MIK				
	Underground tank capacity	Restaurant within mall	As Above) (D				
	Draw-off connection	Restaurant within mall	As Above	MR				
	The service inlet	Restaurant within mall		MR				
	riccess to talk	Restaurant within mall	As Above	MR				
5.	Overhead Tank capacity	Restaurant within mall	As Above	MR				
6.	Exit Signage.	Required	As Above Provided	MR				
J.	Provision of Lifts. [Provided & Mainta	ined by Mall management]	riovidea	MR				
	• Pressurization of Lift Shaft		The second second	1				
	Pressurization of Lift lobby	NA NA	NA	NA				
	Communication In lift Car	NA NA	NA	NA				
	• Fireman's Grounding Switch	1.30,000	NA	NA				
Ź	Lift Signage	NA	NA	NA				
7.	Standby power supply	NA	NA	NA				
8.	Refuge Area. [Provided & Maintain 11	NA	NA	NA				
	Refuge Area. [Provided & Maintained by Mall management] NA NA NA NA NA							
	> Location	NA	NA	NA				
).	Fire Control Room[Provided 8 34	NA	NA	NA NA				
1	Fire Control Room[Provided & Maintained b	y Mall management]	- 11.	INA				
	 Detector System Panel Flow Switch Panel 	NA	NA	NI 4				
10	• PA System P.	NA	NA NA	NA				
- 1	PA System Panel Pattern had	NA	NA NA	NA NA				
				INI A				
W.	Battery backupBuilding Floor Plans	NA NA	NA	NA				

Chy Ka

-		7.14	4						
0.000	cial Fire Protection System for	NA	NA	NA.					
he fir	Protection of special Risks, if any: e fire protection systems provided in the building were test checked and found function of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevalence of the minimu								
ire sai	Keeping in view the substantial com cety required under the rules it is reconorated in Fire Service Rule 2010.	mmended to grant Fire Sa	fety Certificate un	der rule 35 of					
he De	mi File Service Rule 2010.		Chine	J2123					
		Si	gnature of the Insp	ecting Officer (umar Sharma					
	my 02/08/20 33	N	ame Ajay A Designation	ADO(Rohini)					
			# ()						
	Mukherjee V (NW)								
	1 2 to 11 0		3						
	Ster Mugh								
	1 181 8023								
	Denetay	M							
	//1(0"1"								
	An	yRAM FT	litty 6 / rind f	my up					
	1)97	T FT	ind k	seunsal					
		for	· O. a. a tu	u please					
		au	id signici						
	,	10		$\bigcap_{i=1}^{n}$					
				Lux 19181					
	Director W	\mathcal{O}		1 4 7 1					
	35.7	<i>y</i> *							
				# 1 st					
	Muse								
	· Constitution of the cons	U Blocked							
		14/8/53							