

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/70

Dated: 06/03/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Pings Café Orient situated at Shop No 170-A, Ground Floor, DLF Avenue Mall, Saket New Delhi -110017 in the building comprised of 03 tiers Basement, Ground plus Seven Upper floors owned/occupied by Unit of Primoris Hospitality Pvt Ltd was issued FSC by this department vide letter F6/DFS/MS/EH/2021/SZ/60 dated 08/03/2021. The restaurant premise was re-inspected by the officers concerned of this department on 28/02/2024 in the presence of Mr. Rajiv Ranjan and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D "Assembly Building" and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 06/03/2024 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2024021901818 dated 19/02/2024)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



| 1 | Name & Address of the Building | ION REPORT | | 7 1 | | |
|-----------|--|--|--------------------------------|-------------------|--|--|
| | at tracess of the Building | M/s Pings Café Orient (Unit of Primoris Hospitality I | | | | |
| 4 | a fulfille appealing where to | Ltd) at Shop No 170A, Ground Floor, DLF Avenue | | | | |
| 2 | Type of Occurre | Mall, Saket New Delhi -110017 | | | | |
| 3 | Type of Occupancy | (Restaurant is running at Ground floor only) | | | | |
| | Building Comprised of | 03 tier Basements, Ground + 07 Upper Floors | | | | |
| 1 | Type of Case | Renewal Property III | | | | |
| 5 | Details of Previous NOC | F6/DFS/MS/EH/2021/SZ/60 dated 08/03/2021 | | | | |
| 6 | Fire Safety Directives Letter No | DLF Place Mall,- F.6/MS/DFS/BP/2005/2073 dated 04/10/2005 & F.6/MS/DFS/BP/2019/135 dated 01/04/2019 | | | | |
| 7 | Date of Inspection | 28/02/2024 | | | | |
| 8 | Name of the Inspecting Officers | DO (South) & ADO (BCP) | | | | |
| 9 | Name & Designation of Officers | Sh. Rajiv Ranjan | | | | |
| | from the building side | | | 100 | | |
| 10 | Year of construction | 2005 | | | | |
| 11 | Applicant letter No. | MHA Portal ID 2024021901818 dated 19/02/2024 | | | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Requirement/ Existing Fire Protection | Provided at Site | Remarks MR/NMI | | |
| 1 | Acces to Building (DLF Ave | nue Mall - F.6/DFS/M | S/2022/Mall/SZ/266 Dt. 15/ | 06/2022) | | |
| 1 | • Road width | 12 m | Provided | 17.2.4.4 | | |
| | Gate width | 7m | Provided* | MR | | |
| | Width of internal road | 6m | Provided* | MR | | |
| 2 | Number, width, type & arrangement of exi | ts. mmont/ see | au Vierpretz (Ital) 5 | Calcat | | |
| - | a) Number of Staircase | Provided & | Maintained by DLF Place | MR | | |
| Hb/ | > Upper floors. | 02 Nos | 16 Nos Provided* | N/A | | |
| | > Basement floor. | N/A | N/A Maintained by DLF Place | 2000 | | |
| 3),[4 | b) Width of Staircase | | 9 x 1.50m & 7 x 2m | MR | | |
| | > Upper floors | 1.50 mtr & 2m N/A | N/A | N/A | | |
| | ➤ Basement floor | N/A Provided & | Maintained by DLF Place | Saket | | |
| | c) Protection of exits | Restt within Mall | Provided* | MR | | |
| | Fire check door Pressurization | Restt within Mall | Provided* | MR | | |
| | a di continuento terrore | Restt within Mall | -NA- | MR | | |
| | | N/A | N/A | N/A | | |
| | THE RESERVE OF THE PROPERTY OF | 1.50 mtr each | 2 m & 1.50 m | MR | | |
| 3 | Ompartmentation. | | Maintained by DLF Place | Saket | | |
| 3 | Fire check door. | Restt within Mall | Provided* | MR | | |
| | Casting of electrical shafts | Restt within Mall | Provided* | N/A | | |
| | Fire rating of shaft door. | N/A | N/A N/A | N/A | | |
| | Water curtain | N/A | N/A N/A | N/A | | |
| | Fire dampers. | N/A | | 100-000-000 | | |
| 4 | Smoke Management system. | | Maintained by DLF Place N/A | N/A | | |
| AD | Basement | 30 ACPH | Exhaust Fans Provided | MR | | |
| 10 | Upper floors | 12 ACPH | LAndust I dils I lovided | | | |
| 5 | Fire Extinguishers. | Required | 08 Nos | MR | | |
| Fix | | ABC/CO ₂ | ABC & CO ₂ | MR | | |
| | • Types | Required | Provided | MR | | |
| | ISI Marking | Provided & | Maintained by DLF Place | e, Saket | | |
| 6 | First Aid Hose Reels. Total numbers on each floor. | One near Restt | Provided* | MR | | |
| | Total numbers on each noor. Length of hose-reel hose. | 30m | Provided* | MR | | |
| | | 5mm | Provided* | MR | | |
| _ | Nozzle Diameter Nozzle Diameter Provided & Maintained by DLF Place, Sake | | | | | |
| 7 | Type of detectors | Required | Smoke & heat | MR | | |
| | Location of Main Panel | Required | Provided* | MR | | |
| | Location of Repeater Panel | Required | Provided* | MR | | |
| | A TOOMTON OF 122 Land | | | 100 | | |
| 1 | Alternate source of power | Required | Provided* | MR | | |

| 8 | MOEFA | Daguisad | Decade | | |
|--------|--|---|-----------------------|-----------|--|
| 9 | Public Address System | Required N/A | Provided | MR | |
| 10 | Automatic Sprinkler System | 12/11/2/17 | As above | MR | |
| -11 | Basement | Provided & Maintained by DLF Place, Saket | | | |
| | Ground floor. | Required | Provided* | MR | |
| | | Required | Provided* | MR | |
| 11 | Sprinkler above false ceiling Internal Hydronete | N/A | N/A | N/A | |
| 11 | Internal Hydrants. | Provided & Maintained by DLF Place, Saket | | | |
| | Size of Riser/Down-comer | Required | Provided* | MR | |
| | Number of Hydrant per floor | One near Restt | Provided* | MR | |
| 12 | Hose box. Vond Hydronese | One near Restt | Provided* | MR | |
| 12 | Yard Hydrants. | | aintained by DLF Pla | ce, Saket | |
| | Total number of hydrants. | N/A | As above | N/A | |
| 13 | Hose box. | N/A | As above | N/A | |
| 13 | Pumping arrangements. | Provided & M | aintained by DLF Pla | ce, Saket | |
| | • Ground Level | Common pumping arrangements for entire bldg | | | |
| | Discharge of main pump. | 4500 LPM | 4500 LPM | MR | |
| | Head of main pump. | 70m | 70m | MR | |
| | Number of main pumps. Number of main pumps. | 02 Nos. | 02 Nos. | MR | |
| 12.5 | roomey rump output. | 180 LPM | 180 LPM | MR | |
| | Jockey Pump head.Standby Pump output. | 70m | 70m | MR | |
| | > Standby Pump output. > Standby Pump head. | 4500 LPM | 2 X 4500 LPM | MR | |
| | Auto Starting/Manual Stopping. | 70m | 70m | MR | |
| | Pump house access. | Required | Provided | MR | |
| | | Required | Provided | MR | |
| | Terrace Level Discharge of pump. | | | | |
| | Head of pump. | 450 LPM | Provided* | MR | |
| | Power supply. | 40 m | Provided* | MR | |
| | > Auto starting of pump. | Required | Provided* | MR | |
| 14 | Captive water storage for fire fighting. | Required | Provided* | MP | |
| | Underground tank capacity. | Provided & Ma | intained by DLF Place | , Saket | |
| | > Draw-off connection. | Required | 3,70,000 Ltrs | MR | |
| | Fire Service Inlet. | Required | Provided | MR | |
| | > Access to tank. | Required | Provided | MR | |
| | Overhead tank capacity. | Required | Provided | MR | |
| 15 | Exit Signage. | 20,000 ltr | 30,000 Ltrs | MR | |
| 16 | Provision of Lifts. | Required | Provided | MR | |
| 11000 | Pressurization of lift shaft. | Provided & Mai | intained by DLF Place | , Saket | |
| | Pressurization of lift lobby. | Required | Provided* | MR | |
| | Communication in lift car. | Required | Provided* | MR | |
| | Fireman's switch. | Required | Provided* | MR | |
| ls. | Lift signage. | Required | Provided* | MR | |
| 17 | Standby Power Supply | Required | Provided* | MR | |
| 18 ` | Refuge Area | Required | Provided | MR | |
| 136 | Total area | 27/4 | Thirt is | | |
| | Location | N/A | N/A | N/A | |
| 19 | Fire Control Room. | N/A | N/A | N/A | |
| | Detector system panel. | Provided & Maintained by DLF Place, Saket | | | |
| | Flow switch panel. | N/A | Provided* | N/A | |
| a Gran | PA system panel. | N/A | Provided* | N/A | |
| - | Battery backup. | N/A | Provided* | N/A | |
| 1 | Building floor plan. | N/A | Provided* | N/A | |
| 20 | Special Fire Protection System for the | N/A | Provided* | N/A | |
| 18/67 | Protection of special Risk, if any. | N/A | Provided* | N/A | |



The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/60 dated 08/03/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ)

08/03/24

9