

C-64

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI -110001**

No.F6/DFS/MS/NDZ/2021/ 398

Dated:- 05/08/2021

To

The Principal,  
Rajkiya Sarvodaya Bal Vidyalaya,  
Block-27, Trilokpuri, Delhi-91.

**Sub:- Regarding issuance of Fire Safety Certificate in r/o Rajkiya Sarvodaya Bal Vidyalaya at Block-27, Trilokpuri, Delhi-91.**

Sir,

This has reference to your email dated 16/07/2021 on the subject cited above. In this regard, it is to inform you that the site was re-inspected by the officer concerned of this department on 27/07/2021 in the presence of Mr. Manvir Singh (H.O.S) and observed that the shortcomings already communicated by this department vide letter No. F6/DFS/MS/2019/2213 dated 22/04/2019 (photocopy enclosed) has not been rectified yet.

Hence, the Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under the intimation to this department for further necessary action in this regard.

Yours faithfully

  
4/8/21

(Dr. S.K. Tomar)  
Dy. Chief Fire Officer  
Delhi Fire Service



Encl: as above

C-57

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F6/DHS/MS/2019/606  
To,

Dated: 31/1/19

The Principal,  
Rajkiya Sarvodaya Kanya Vidyalaya,  
Block- 27, Trilokpuri, Delhi-91.

**Sub:** - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o  
Rajkiya Sarvodaya Kanya Vidyalaya, Block- 27, Trilokpuri, Delhi-

Madam,

Please refer to your letter RSKV/698 Dated 05/12/18 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the Circular no. F.16/Estate/CC/FS/2011/3298 to 3398 dated-1.3.11. At the time of inspection Mrs. Manju Khati (Principal) & Dilip Bist (Estate Manager) was present and it was observed that the school building is comprised of A & B block ground plus two upper and C & Primary blocks ground plus one upper floor and have following shortcomings:-

1. An additional staircase having width of 1.5 m shall be required in A, B & C block.
2. First Aid Hose reels not provided A & B block.
3. Fire pump having 450 LPM output at 40 m head not provided in A & B block at terrace.
4. Over head tank capacity of 10,000 liters not provided in A & B block.
5. Exit signage's not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

30/1  
(Vipin Kental)  
Chief Fire Officer

9/13