## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.

F.6/DFS/MS/School/2021/SZ/418

Dated: 16/08/2021

To

The Principal,

Govt. Girls Senior Secondary School,

Harkesh Nagar, New Delhi 110020

**Sub:** Regarding issue of Fire Safety Certificate (FSC) in r/o Govt. Girls Senior Secondary School, Harkesh Nagar, New Delhi 110020

Sir,

This is in reference to with Gmail dated 28/07/2021 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department and observed that the shortcoming intimated vide letter of even no. 195 dated 07/04/2021 has yet not been complied. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

0/22

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/SZ/ 195

Dated: 67.04/2021

To

The HOS / Vice Principal, Govt. Girls Senior Secondary School, Harkesh Nager, New Delhi 110020

Sub: Reg. renewal of Fire Safety Certificate in r/o Govt. Girls Senior Secondary School, Harkesh Nager, New Delhi (ID 1925341)

Sir,

This is in reference with your Gmail dated 11/03/2021 on the subject cited above. In this regard, school premises have been inspected by officer concerned of this department on dated 25.03.2021 in presence of Sh. Birender Singh (Manager) to verify the status of existing fire prevention and fire safety measures. During the course of inspection, the shortcomings observed are as below;

1. Hose reel found non-functional in ground plus three blocks and not provided in ground plus two upper floor blocks.

2. Terrace pumps found non-functional in ground plus three blocks and not provided in ground

plus two upper floor blocks.

3. Overhead tank capacity 10,000 ltrs not provided in ground plus two upper floor blocks.

In view of above shortcomings, renewal of Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further action in the matter.

Yours faithfully,

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ)

Delhi Fire Service

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat Delhi 110054