## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI** HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI – 110001

1837 No.F.6/DFS/MS/2021/

Dated: 10/09/201

To,

The Estate Manager Statesman House 148, Barakhamba Road New Delhi

## Sub:-Regarding issuance of FSC in r/o Statesman house at 148, Barakhamba Road, New Delhi

Sir.

This has a reference to your e-mail < FM.Statesman@compass-group.co.in dated 14.08.21 on the subject cited above. In this connection it is to inform you that the site was inspected by officers concerned of this department on 27/08/2021 in the presence of Sh. Alamgir Ansari and the following shortcomings were observed: -

- Electrical shafts and opening horizontally /vertically are not sealed properly.
  Fire detection system found nonfunctional at 14<sup>th</sup> floor & Axis Bank.
- 3. Hose reel is not provided at ground & mezzanine floor floor in Axis Bank.
- 4. Sprinklers are required to be extended in left out areas in basement.

In view of above shortcomings, request for renewal of fire FSC is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statuary/licensing authority may take suitable action as deemed fit.

Youns faithf 01123414000

Copy To The Chief Architect, NDMC Palika Kendra, New Delhi.