GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. 66 Dfs ms school 2021 512

Dated: 23/09/2021

To,

Sh. R. K. Sharma (Principal), Kendriya Vidyalaya, Andrews Ganj, New Delhi-110024.

Subject: Inspection Report of Kendriya Vidyalaya located at Andrews Ganj, New Delhi-24.

Sir,

Please refer to your letter received through email ID kvandrewsganj1404@gmail.com dated 13/08/2021 on the subject cited above. In this connection it is to inform you that the premises was visited by officer of this deptt. on dated 13/09/2021 in presence of Sh. R.K. Sharma (Principal) and observed that management has still not complied the office letter issued by this department vide letter No. F6/DFS/MS/School/2020/SZ/461 dated 11/05/2020. (Copy Enclosed).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER(SZ).

c-25

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHITTRE SERVICE, NEW DELHI 110001

No. F.6/DFS/MS/School/2020/S7/ 461

Dated 11/5/2020

To

The Principal. Kendriya Vidyalaya. Andrews Ganj. New Delhi-110024

DEA/ET

Sub: Renewal of Fire Safety Certificate.

Sir.

This has reference to your letter No. Nil dated Nil received through outdoor diary No. 3292 dated 08/02/2020, on the subject cited above. In this connection, the school premise was inspected by the officer concerned of this department in the presence of Mr. R.K. Sharma (Principal). During the course of inspection, it was observed that school building is comprised of ground plus two upper floors.

The following shortcomings were observed: -

- 1. Fire extinguishers found empty.
- 2. First aid hose reel provided but non functional.
- 3. Terrace level pump capacity 450 LPM with 40m head found non-functional.
- 4. Overhead water tank of 10,000 liters capacity for firefighting provided but non-functional.
- 5. Exit signage found removed at every floor.

In view of above shortcomings, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under intimation to this department for further action in the matter.

Yours faithfully,

(S S Tuli) Dy. Chief Fire Officer Delhi Fire Service

M. OL