GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.

f6 Df3 ms school 2021 523

Dated: 29 09 202)

To,

Mrs. Reena Chakravorty (Principal) Kendriya Vidyalaya, INA Colony, New Delhi-110023.

Subject: Inspection Report of Kendriya Vidyalaya, INA Colony, New Delhi-110023.

Sir,

Please refer to your letter received through email <u>ID-kvina23@gmail.com</u> dated 16/09/2021 on the subject cited above. In this connection it is to inform you that the premises was visited by officer of this deptt. on dated 20/09/2021 in presence of Mr. R. M. Chitranshi (HOS) and observed that management has still not complied the office letter issued by this department vide letter No. F6/DFS/MS/2015/School/2720 dated 29/12/2015. (Copy Enclosed).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (S.Z.).

Copy to :-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

or

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110001**

No.

FGDFSIMS/2015 Schul 2720

Dated:

29/12/15

To.

The Principal,

Kendriya Vidyalaya,

INA Colony, New Delhi-110023.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Kendriya Vidyalaya, INA Colony, New Delhi-110023.

Sir.

Please refer to your letter No. F.KVINA/2015-16/589, dated 09.11.2015 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school building on 09.12.2015 to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection you were also present.

It was observed that the school building comprised of ground plus one upper floor (one block) and ground floor only (one block). Fire fighting systems such as fire extinguishers were found provided and following shortcoming was observed :-

1. An additional staircase is required for first floor to meet the requirement of travel distance.

In view of above, the fire safety certificate cannot be issued at this stage.

Yours faithfully

Dy.Chief Fire Officer T.No.011-26189168 OC