GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/MS/2022/SZ/ Cans/ 7 ()

Dated: ⁹7 / ³/2022

To,-

The President Shree Badrinath CGHS Ltd. Plot No. 18, Sector -04, Dwarka, New Delhi – 110078.

Subject: Renewal of Fire Safety Certificate in r/o Shree Badrinath CGHS Ltd. Located at Plot No. 18, Sector – 04, Dwarka, New Delhi – 110078.

Sir,

Please refer to legal notice Dated-09/02/2022 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 16/03/2022 to see the compliance of the shortcomings communicated vide this office letter no. F6/DFS/MS/CGHS/2019/SZ/5824 dated 26/09/2019 (copy enclosed) and found that the shortcomings are still not complied. You are requested' to comply the shortcomings within 03 months from the date of issuance of this letter.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Enclosed: - As Above

Yours faithfully,

Copy to: -

- 1. Joint Director, DDA, Vikas Sadhan INA, New Delhi
- 2. Sh. K.K Sinha & Associates Chamber No 537, Dwarka ourt Complex, New Delhi -110075 < surendersingh.adv@gmail.com>

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELIH FIRE SERVICE: NEW DELIH - 110001 No. F6/DES/MS/CGHS/2019/SZ/ 26/2/19 1837

To.

Sh. Shiy Dayal (Hony Secretary). Shree Badrinath CGHS Ltd., Plot No.18, Sector-4, Dwarka,

New Delhi-110078.

Subject: - Renewal of Fire Safety Certificate in r/o Shree Badrinath CGHS Ltd., Plot No.18, Sector-4, Dwarka, New Delhi- 110078.

Sir.

This is in reference to your letter no. SBDCGHS/BSES dated 6.8.2019 on the subject cited above. In this connection it is to inform you that the above said residential building has been inspected by the officers concerned of this department on 3.9.2019 in presence of Sh. Shiv Dayal (Secretary) & Sh. M K Gupta (Treasurer) to check the workability of fire safety systems provided therein.

During the course of inspection the following points have been noticed as shortcomings:-

- 1. Fire Check Door in basement found removed.
- 2. Sprinkler system in basement found nonfunctional.
- 3. Fire pump 450 LPM at terrace level is provided but found nonfunctional.
- 4. Exit signs found removed.

In view of the above shortcomings fire safety Certificate cannot be renewed at this stage. You are advised to rectify the above said shortcomings under intimation to this department for taking further necessary action.

) ABOUT

Copy to:-

1. The Joint Director (Buildg.) (L&I), Vikas Sadan, DDA, INA, New Delhi.