GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2022 / 878

Dated: 22/04/2022

To

Sh. Laxman Singh Chauhan (Estate Manager), B-08, GDITL Tower, NSP, Pitampura, Delhi-110034.

Sub: - Inspection report in r/o B-08, GDITL Tower, Located at NSP, Pitampura, Delhi-110034.

Sir,

Please refer to letter dated 08/03/2022 on the subject cited above. In this connection, it is to inform you that the premises/ Building was inspected by the officers concerned by this department on 05/04/2022 in the presence of Sh. Laxman Singh Chauhan (Estate Manager) to check the functioning of Fire Safety arrangements provided in he building.

During inspection, it has been observed that the premise was comprised of basement + Ground +13 upper floors. Fire safety arrangements such as fire Extinguishers, First-Aid Hose reels, Terrace pumps, Over Head water storage tank & Exit Signage's are provided. However the following shortcomings were observed:-

- 1. Fire Check Doors are found removed at some places.
- 2. Automatic fire Detection and alarming system are removed at some places.
- 3. Main fire pump of capacity 2400 lpm is provided but not on automode.
- 4. Pressurization of lift lobby are found removed.
- 5. Access road is one side blocked by MCD for Parking.
- 6. Fire Check Doors installed in building are very old one, insulation of doors are to repaired/changed.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/ Occupier. The Licensing authority/ statutory authority may take suitable necessary action as deemed fit.

Yours faithfully

Delhi Fire Service