

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/WZ/School/2022/204

Dated: 04/05/2022

To

The Principal,  
Nigam Pratibha Balika Vidyalaya,  
No.1 (I), Nithari (Rohini Zone),  
Delhi- 110086.,

Subject: Issuance of Fire Safety Certificate in r/o Nigam Pratibha Balika Vidyalaya, No.1 (I),  
Nithari (Rohini Zone) Delhi- 110086.  
Sir,

This is in reference to your letter No. nil dated 27.02.2022 received through outdoor diary no. 6949 dated 28.02.2022 on the subject cited above. In this connection submitted the building was visited by officer on dated 06.04.2022 however, it has been observed that the shortcoming already issued by this department letter of even No. 1668 dated 24.04.2018 (Copy enclosed). Therefore, he may be advised to submit point-wise compliance of shortcomings already issued vide this department letter dated 25.04.2018 for further consideration in this matter.

Yours Faithfully

  
(Dhrampal Bhardwaj)  
Dy.Chief Fire Officer  
Tel;-01123414250

HC  
04

C-20

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F-6/DFS/MS/ 2018/ School/ 1668

Dated 25/01/2018

To

The Principal  
Nigam Pratibha Balika Vidyalaya,  
Nithari No-1, Delhi-110086.

**Sub: - Regarding issuance of fire safety certificate in r/o Nigam Pratibha Balika Vidyalaya, Nithari No-1, Delhi-110086.**

Sir,

Please refer to your letter no. Nil dated 31.01.2018 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department to verify the fire safety measures issued vide Director of Education circular dated 01.03.2011/ NBC Part 4 and observed that the building was comprised of 02 blocks, A- block ground plus one and b- block ground plus two upper floor only. At the time of inspection Sh. Ashok Kumar Tawar was also present at site. During the course of inspection observations/ shortcomings made are as under:-

1. Hose reel hose provided but not functional.
2. Terrace level fire pump capacity 450 lpm found removed.
3. Overhead tank capacity of 10,000 ltr. found empty.
4. Exit signage's not provided at strategic location in the building.

Keeping in view of above, fire safety certificate cannot be considered at this stage

Yours faithfully

(Atul Garg)

Chief Fire Officer  
Ph: 011-23414250

*Atul*