

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/2022/SZ/School/253

Dated: 27/05/2022

To,
The Principal, <adminmanager@gdgoenkadwarka.com>
G.D Goenka Public School,
Sector-10, Dwarka,
New Delhi – 110075.

Subject: Renewal of Fire Safety Certificate in r/o G.D Goenka Public School Located at Sector-10, Dwarka, New Delhi – 110075.

Sir,

Please refer to Email dated 25/04/2022 on the subject mentioned above. In this connection it is to inform you that the above said premises was visited by the team of officers concerned of this department on 09/05/2022 in the presence of Major Reenu Ohlan (Retd.) to see the compliance of the shortcomings communicated vide this office letter no. F6/DFS/MS/SZ/2022/School/68 dated 14/02/2022 & found that the shortcomings are still not complied. You are requested to comply the shortcomings under intimation to this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

(Ajay Garg)
Director,
Delhi Fire Service.

Copy to: - Directorate of Education Old Secretariat Delhi – 110054

10 dt
26/5/22

C-71

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/SZ/2021/School | 68

Dated: 14/02/2022

To,
The Principal, <adminmanager@gdgoenkadwarka.com>
G.D Goenka Public School,
Sector-10, Dwarka,
New Delhi – 110075.

Subject: Renewal of Fire Safety Certificate in r/o G.D Goenka Public School Located at Sector-10, Dwarka, New Delhi – 110075.

Sir,
Please refer to your Email Dated 31/12/2021 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by the officer concerned from this department on 01/02/2022

During the course of inspection following shortcomings are observed.

1. Six meter wide internal road found encroached at corner.
2. Fire Check Doors found removed at some places.
3. Pressurization system found removed in staircases.
4. Smoke exhaust system found nonfunctional in basement & upper floors.
5. Smoke detectors are found removed at some places.
6. P A system found nonfunctional.
7. Manual Operated Emergency Fire Alarm System found nonfunctional
8. Lift Lobby found removed.
9. Pressurization System provided for lift shaft found nonfunctional in auto mode.
10. Hose reel hoses & Hydrants found non functional.
11. Terrace Pump found no nonfunctional.
12. School activities are noticed in basement.

You are requested to comply the abovementioned shortcomings under intimation to this department.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,


(Atul Garg)
Director

Delhi Fire Service

Copy to:- Directorate of Education Old Secretariat Delhi – 110054