GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/DFS/MS/BNQT/WZ/2022

Dated: 03 / 06 /2022

168

To,

The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. <u>addlcp.lic-dl@nic.in</u>

Subject: Regarding Renewal of NOC from fire safety point of view in respect of M/s Tivoli Lawrence Road (A Unit of TG SAI HOTELS LLP) Located at B3 Lawrence Road, New Delhi-110035.

Sir,

Please refer to your online application no. 2022041306859 dated 15/04/2022 on the subject mentioned above. In this connection, it is to inform you that the premises was inspected by the officer concerned of this department on 14/05/2022 in the presence of Sh. Shiv Saini (Partner) to check the functioning of fire safety arrangements provided in the building.

During inspection, it has been observed that the building/premises is comprised of 02 Basement + Ground + 02 upper floors was issued FSC vide letter no. F6/DFS/MS/BNQT/2019/1391 dated 05/07/2019 for banquet at Ground + 1^{st} floor & 15 guest rooms at 2^{nd} floor. Fire Safety arrangements such as Fire Extinguishers, First –Aid Hose reel, Terrace pump, overhead water storage tank etc. have been provided in the building. However, the following shortcomings were observed.

- 1. Fire Check Doors are removed at some places.
- 2. Smoke Management system is not working in Basement & Upper floor.
- 3. First Aid Hose Reel is provided but not functional.
- 4. CO (Carbon Monoxide) Detectors shall be provided at guest floor in second floor.
- 5. Automatic fire & detection system is not working.
- 6. MOEFA is provided but not functional.
- 7. P.A. System is provided but not functional.
- 8. Exit signages are found removed.
- 9. Automatic Sprinkler System is provided in basement but not functional.
- 10. Internal Hydrant is provided but not functional.
- 11. Terrace level & Ground level pump is provided but not functional.
- 12. Underground water tank provided but found empty.
- 13. Exit sinages found removed.
- 14. Pressurization of lift shaft found not working.
- 15. Shaft in Basement level shall be closed by bricks wall.

16. Sprinkler & Detectors shall be extended in left out area.

In view of above Shortcomings the application for Issuance of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety Arrangements Shall be at the risk and liabilities of the Owner/occupier. The license issuing authority/statutory authority is requested that premises should not be allowed to run till it provide all necessary fire Safety arrangements.

Yours faithfully,

(Dharampal Bhardwaj) Dy. Chief Fire Officer

West Zone

m