

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/WZ/2022/303

Dated: 10/06/2022

To

Smt. Bimla Bhatia, Manager,
Prabhu Dayal Public School,
Dakshini Block-A,
Shalimar Bagh, Delhi- 110088.


Sub.- Regarding renewal of Fire Safety Certificate in r/o Prabhu Dayal Public School, Dakshini Block-A, Shalimar Bagh, Delhi- 110088..


Sir,

This is in reference to your letter No. PDPS/FS/2022/582 dated 24.05.2022 on the subject cited above. In this connection, it is to inform you that the school building was inspected by the officer concerned of this department in your presence on 07.06.2022 to check the status of the shortcomings issued by this department vide letter No. F6/DFS/MS/School/2022/216 dated 13.05.2022 (copy enclosed for ready reference), but no improvement was observed during the course of inspection.

In view of the above, fire safety certificate cannot be renewed at this stage. You are advised to rectify the shortcomings issued vide letter dated 13.05.2022 under intimation to this department.

Yours faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone


9/6/2022

C 50

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI: 110001

No. F6/DFS/MS/School/2022/216

Dated: 13/05/2022

To,

The Manager,
Prabhu Dayal Public School,
Dakshini Block-A,
Shalimar Bagh, Delhi- 110088.

Sub: Regarding renewal of fire safety certificate in r/o Prabhu Dayal Public School, Dakshini Block-A, Shalimar Bagh, Delhi- 110088.

Sir,


Please refer to your letter No. PDPS/2021-22/FS/485 dated 22.03.2022 received through outdoor diary No. 7509 dated 22.03.2022, on the subject cited above. The above school building was inspected by officer concerned of this department in presence of Sh. Bahadur Singh (I.T. Admin) on 26.04.2022 to check the status of the fire safety arrangements provided in the school building.

During inspection it has been observed that the said building is comprised of ground plus two upper floors. Fire safety arrangements such as overhead water storage tank, fire pumps capacity 900 & 180 LPM, hose reels, down comer, fire extinguishers etc. found provided. However, following shortcomings were observed: -

1. Domestic connection in overhead water storage tank shall be removed.
2. Fire pumps were not in auto mode.
3. Exit signages are not provided.

In view of the above shortcomings, fire safety certificate cannot be renewed at this stage. You are requested to rectify the above mentioned shortcomings and submit point wise compliance for further necessary action in this matter.

Yours faithfully,


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

