GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

NO F.6/DFS/MS/2022/SZ/ 1397

Dated 14 / 06 /2022

То

The Asstt. Engineer (E)-III, Delhi Electrical Division -41, PWD, GPO Complex, New Delhi 110023

Sub: - Regarding issuance of Fire Safety Certificate in r/o M/s General Pool Office Complex, INA, New Delhi -110023

Sir.

In continuation to this department letter of even no 730 dated 01/04/2022, even no 1041 dated 11/05/2022 and subsequent your letter dated 24/05/2022. In this connection, this is to inform you that as per your above mentioned compliance letter, you have addressed only one of the observation listed at point no 02 out of total 06 observations in our earlier observation/ shortcoming letter of dated 17.12.2020.

Hence, you are hereby once again requested to comply the observations/ shortcomings already conveyed with your esteemed office, in toto, for further consideration in the matter.

This is for your information and action at your end please.

Yours faithfu (ATUI ÐŃ **DELHI FIRÉ SERVICE**

<u>GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI</u>

R/DB/MS/201020 1521 3098 No.

Dated: 17/12/2020

To,

A.E. (E), Delhi Electrical Division-41, CPWD, CVC Bhawan, GPO Complex, Block-A, INA New Delhi-110023.

Subject:- Inspection report in r/o M/s General Pool Office Complex, INA, New Delhi-23, from Fire Safety and means of escape point of view.

Sir,

Please refer to your letter No. 23(16)/AE(E)-III/41/244 dated 25/11/2020 on the subject noted above, in this connection, it is to inform you that the said premises was visited by the officers concerned of this department on 04/12/2020 in the presence of Mr. Virender Singh, AE(E) & Subhash Meena, J.E. (E) and observed that the building comprised of Common two tier basements Ground plus four upper floors (one block, ground plus five upper floors (Two Blocks) & ground plus six upper floors (Two Block) All Blocks are interconnected.

However following shortcomings were observed during the time of inspection:-

- \times 1. Mechanical Ventilation is provided in basement but found nonfunctional.
- \smile 2. All blocks are interconnected but found locked / Blocked at each floor v.i.z. access to other blocks of the building are blocked by locking.
- \propto 3. Fire Extinguishers provided but nonfunctional.
- 4. Automatic fire detection and alarming system were provided but found nonfunctional at some \downarrow places.
- \sim 5. Exit Signage & Lift Signage found removed at some places.
- < 6. Pressurization at lift lobby & lift shaft were provided but found nonfunctional.

In view of above NOC/ FSC is rejected under Rule 37 (3) of DFS Act 2007, Rules 2010.

You are requested to rectify above mentioned shortcoming under intimation to this department for further necessary action please.

Yours faithfully,

Copy to:- for information.

1. XEN (E), DED-41, CPWD, Andrews Ganj, New Delhi.

2. Under Secretary (GA), Block-C, NHRC Building, GPO Complex, INA, New Delhi.