



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2022/NDZ/327

Dated 16/06/2022

To,

The Principal,
Rajkiya Sarvodya Vidyalaya No. 01,
Bhola Nath Nagar, Shahdara,
Delhi 110032

Sub:- Regarding Issuance Fire Safety Certificate r/o Rajkiya Sarvodaya Kanya Vidyalaya, No.-01,
Bhola Nath Nagar, Shahdara , Delhi 110032.

Sir,

This is in reference to your letter No. RSKV/No-1/BNN/375 dated 10/05/2022 on the subject cited above. In this connection, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence of Sh. Sunder Singh, Estate Manager of the school on dated 30/05/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2022/134 dated 24/03/2022 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

Copy to:-

The Dy. Director of Education,
B-Block, Yamuna Vihar, Delhi-110053

o/c
2.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. F6/Dfs/ms/school/2022/134

Dated 24/03/2022

To,

The Principal,
Rajkiya Sarvodya Vidyalaya No. 1,
Bhola Nath Nagar, Shahdara,
Delhi 110032

Sub:- Regarding Issuance Fire Safety Certificate r/o Rajkiya Sarvodaya Kanya Vidyalaya,
No.-01, Bhola Nath Nagar, Shahdara , Delhi 110032.

Sir,

This is in reference to your letter No. R/S/K/No.1/BNNS/1073 dated 02/02/22 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view in presence of Mr. Ashutosh Kumar, HOS of the School. The following points / shortcomings were noticed in the building which is comprised of ground plus three upper floors and two bocks of ground plus one and ground plus three are connected to each other at ground and first floor.

1. First-Aid hose reels provided but non functional at the time of inspection.
2. Fire pump having 450 LPM output with 40 meter head provided but non functional at the time of inspection.

In view of above, the building can not be considered for grant of fire safety certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


23/3/22

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

O/c



Copy to:-

The Dy. Director of Education,
B-Block Yamuna Vihar,
Delhi-110053