



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

C-72

No. F6/DFS/MS/2022/NDZ/ 482

Dated: 23/8 /2022

To
The Manager,
Mother Mary's School,
Sahkarita Marg, Mayur Vihar, Ph-1,
Delhi-110091.

Sub.:- Inspection Report in r/o Mother Mary's School, Sahkarita Marg, Mayur Vihar, Ph-1, Delhi-110091.

Sir,

With reference to your Letter No. MM/2022/5363 Dated 15/07/2022 on the subject noted above. In this connection, it is to inform you that the said building premises was inspected by the officer concerned of this department on 08.08.2022 in the presence of Sh. Satish Bhat (Estate Manager).


During the course of inspection it was observed that the building premises is comprised of Basement, Ground & four upper floors only.

Following shortcomings were observed during the time of inspection:-

1. Standby diesel Fire pump having capacity 2280 LPM found removed.
2. Electrical Fire Pumps are not on Auto Mode.
3. Exit Signages found removed.
4. Basement is being used as class rooms.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. Statutory authority may take action as deemed fit at their end please.

Yours faithfully,



(S.K.DUA)

Dy. CHIEF FIRE OFFICER

Copy to:- For information and taking necessary action

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.

a/c 