

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
DIRECTORATE OF DELHI FIRE SERVICE: NEW DELHI – 110001.

NO. F.6/DFS /MS/NDZ/2022/ 2686

Dated: 27/10/2022

To,

The Executive Engineer,
F-13 PWD, Mubarka Chowk,
GT Karnal Road, New Delhi.

Sub: Joint inspection in r/o 02 underground tunnel at Ring Road Pragati Maidan, New Delhi.

Sir,

This has a reference to your letter no. W-U/T/F-13/PWD/2022/188 dated 13.09.2022, on the subject cited above. In this connection it is to inform you that the site was visited by ADO/CC, DO/CD on dated 26.09.2022 in presence of Sh. Shantanu, AE PWD, Sh. Aman Agrawal, MEP In charge and following shortcomings are observed.

1. Sprinklers are not provided in branch tunnel connecting from Bhairo Marg to the basement of parking.
2. Water curtain is not provided at the intersection /junction point / interfacing of tunnel and basement as per guidelines issued vide letter no. 4145 dated 03.10.2018.
3. Separate pump house for under pass-6 as proposed in the guidelines is required with 01 electric pump for water curtain.

In view of above, the case cannot be considered for issuance of Fire Safety Certificate. Therefore, it is requested to rectify the above shortcomings at the earliest for consideration in the matter.

Yours faithfully


(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. The Chief Engineer (flyover), PWD, 4th floor, MSO Building, IP estate, Delhi.
2. The Executive Engineer, (ITPO), Project Division, PWD Bhairo Marg, Delhi.
3. The General Manager, ITPO, Mathura Road, New Delhi.