





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/NDZ/College/ 63

Dated: 0 / 1 /2022

То

Executive Engineer (E), Higher Education Elect. Division P.W.D., D.G.E.R., Complex, Sec.-3, Dwarka, New Delhi-110078.

Sub.:- Inspection Report in r/o School of Architecture (C-Block), East Delhi Campus, Guru Gobind Singh Indraprastha University, Surajmal Vihar, Shahdara, Delhi-32.

Sir,

With reference to your letter No. 23(32)/HEED/(B-141)PWD/2022/759 dated 27/08/2022 on the subject noted above, in this connection, it is to inform you that the said building premises was inspected by the officers of this department on 13/10/2022 in the presence of Sh. Shishir Parida and observed that the building comprised of Lower Basement, Upper Basement, Ground Floor & 8 Upper Floors only.

Following shortcomings were observed during the time of inspection:-

1. Pressurization of Lift Lobby, Lift Shaft & Staircase are provided but not on the auto mode viz system is not integrated.

- 2. Smoke management system viz mechanical ventilation is provided but not on auto mode.
- 3. Smoke / Heat detectors were provided but not working on auto mode.
- 4. Repeater panels are not provided.
- 5. MOEFA provided but found nonfunctional at some floors.
- 6. Exit signage & Lift signage not provided.
- 7. Flow switch panel not provided in Fire Control room.
- 8. Modification of sprinklers in some rooms are required.
- 9. Electrical Panel Protection by clean agent/Co₂ not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected under sub rule (3) of rule 35 of DFS Act 2007 and Rules 2010. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. you are requested to apply after rectification of above mentioned shortcomings under intimation to this department.

Yours faithfully.