



C-19-

<u>GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI</u> <u>HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001</u>

F6 / DFS / ms / SCH002 / 2022 / 02 No.

Dated: 03 / 0) /2029

To

Principal, Loreto Convent School, Parade Road, Delhi Cantt., New Delhi-110010.

Sub.:- Inspection Report of Principal, Loreto Convent School, Parade Road, Delhi Cantt., New Delhi-110010.

Sir,

Please refer to your letter No. LC/Fire Safety/2021/01 dated 22/10/2021 on the subject cited above. In this connection it is to inform you that the you have still not complied the office letter issued by this department vide letter No. F6/DFS/MS/School/2019/SZ/5679 dated 19/09/2021. (Copy Enclosed).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (S.Z).

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI–110001</u>

No. F.6/DFS/MS/School/2019/SZ/

5679

То

The Principal, Loreto Convent School, Parade Road, Delhi Cantt, New Delhi–110010

Sub: Issuance of Fire NOC for Loreto Convent School, Delhi Cantt.-10

Madam,

This is with reference to your letter No. LC/Fire Safety/2019/01 dated 25/03/2019 received in this department outdoor dairy No. 7116 dated 28/03/2019 on the subject cited above. In this connection, the school premise have been visited by the officer concerned of this department on 16/08/2019 in your presence to verify the availability & operability of fire prevention and fire safety measures required under the rules. During the inspection, it was observed that an additional building block comprised of stilt plus two upper floors having an auditorium at upper floor have been constructed. The shortcomings observed are as below.

Old Building Blocks: -

- 1. Interconnection of old blocks found blocked at 2nd floor by erecting bricks wall. Front block is served with single staircase of 1.36m, hence an additional staircase shall be provided.
- 2. Hose-reel hose provided found non-functional i.e. nozzles missing and the length of hose reel pipe found less than 30m.
- 3. Exit signage found removed from some locations as indicated during inspection.

New Building Block: -

1. Sanctioned/ Completion plan of the building or as built drawings of the building from a registered architect showing covered area / section / elevation on a scale of 1: 100 through building authority may be submitted to take necessary action.

In view of above, issuance of Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department along with required document in r/o new building block for further action in the matter.

Yours faithful Chief Fire Officer Ph: 011-23414250

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi–110054 [For taking necessary action as school does not have FSC]