

C-20

C-21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/NDZ/2022/School/40

Dated: 01./02./2022

To

The Incharge,
Navshakti Vidya Mandir Girls Sr. Sec. School,
Arakansha Road, Pahar Ganj,
New Delhi.

Sub: Application for issuance of fire safety certificate in respect of Navshakti Vidya Mandir Girls Sr. Sec. School, Arakashan Road, Pahar Ganj New Delhi.

Sir,

This has reference to your letter no. NVM/2021/59 dated 20.12.2021, on the subject cited above. In this regard, it is to inform you that the site was visited by officer concerned of this department on dated 24.01.2022 in presence of Sh. Jagmohan and observed that shortcomings issued vide letter no. F.6/DFS/MS/school/2013/974 dated 14/03/2013 have not been complied so far.

In view of above, FSC can't be issued till the compliance of all the shortcomings issued vide aforesaid letter.

Yours faithfully,



(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

NO: F6/DPS/ms/school/2013/974 Dated: - 14/03/13

To,

The Principal,
Navshakti Vidya Mandir Girls Sr. Sec. School,
Paharganj, New Delhi.

Sub: - Inspection report in r/o Navshakti Vidya Mandir Girls Sr. Sec. School, Arakashan road, Paharganj, New Delhi -110055 from fire safety & means of escape point of view.

Sir,


With reference to your letter No NVM/12012 dated 24/08/2012 on the above cited subject, this is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Mrs. Chander Prabha, Principal of the School, on 25/02/2013 to verify the fire safety arrangements as per Delhi Fire Service Act-2010.

During inspection, it was observed that the said school building is comprised of ground + three upper floors. One staircase of width 0.80 mts found provided in the building. Second staircase of 1.0 mt width is passing through another School (Bal Mandir Public School) run from adjoining building. Fire Safety arrangements such as down comer, hose reel, overhead tank capacity 4000 liters, MCP, fire pump, fire extinguishers of different types & sizes, electric siren and sand buckets found provided in the building. The following shortcomings were observed:-

- One additional staircase of minimum 1.50 mts width is required.
- Down comer, Hose Reels, MCP, fire pump found provided but not functional.
- One overhead tank of capacity 4000 liters found provided with domestic connection. Separate 10,000 lts overhead water storage tank is required for fire fighting.
- Exit signs are not provided.

In view of the above shortcomings, 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the shortcomings under intimation to this department.

Yours faithfully


Chief Fire Officer
Delhi Fire Service

Copy to:-

The Director of Education,
Govt. of NCT of Delhi,
Old Secretariat, Delhi.

92  2-3-13