

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/NDZ/2022/ 1453

Dated: 23/02/2022

To

Sh. R. Lakhanpal
Manager(Hosp & Admin),
Lok Kalyan Samiti, Sucheta Bhawan,
11-A, Vishnu Digamber Marg,
New Delhi-110002.

Sub:- Regarding of FSC in r/o of Lok Kalyan Samiti, Sucheta Bhawan, 11-A, Vishnu Digamber Marg, New Delhi.


Sir,

This has reference to your letter No. LKS/GEN/HO/Fire/2021-22/71 dated 03/01/2022 on the subject cited above. In this regard, it is to inform that the site was inspected by the officers concerned of this department on 15/01/2022 in the presence of Sh. Bharat Bhushan (Asstt. Manager) and observed that shortcomings issued vide letter no. F6/DFS/MS/NDZ/2019/7114 dated 28.11.2019 (copy enclosed) are not complied in toto. Further, IIIrd floor is under renovation and installation of firefighting system at this floor is under process.

In view of above, you are requested to submit the pointwise compliance of all the shortcomings issued vide aforesaid letter for further consideration the matter. Further, it is also to inform you that the occupancy of the building without valid Fire Safety Certificate (FSC) shall at the risk and liability of the owner or occupier.

Encl: As above.

Yours faithfully


(Atul Garg)
DIRECTOR
Delhi Fire Service

C/38

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/NDZ/2019/ 7114

Dated:- 28/11/19

To

Sh. R. Lakhanpal
Manager(Hosp & Admin),
Lok Kalyan Samiti, Sucheta Bhawan,
11-A, Vishnu Digamber Marg,
New Delhi-110002

Sub:- Regarding of FSC in r/o of Lok Kalyan Samiti, Sucheta Bhawan, 11-A, Vishnu Digamber Marg, New Delhi.

Sir,

This has reference to your letter No. LKS/GEN/2019/52 dated 09/10/2019 on the subject cited above. In this regard, it is to inform that the site was inspected by the officers concerned of this department on 05/11/2019 in the presence of Sh. Bharat Bhushan (Asstt. Manager) and the following shortcomings were observed:-

1. Staircase at upper floor encroached with old furniture & goods.
2. Alternate staircase found locked in front block.
3. Hose reel not functional.
4. Hose reel /hydrant to be extended in front block.
5. MCP not functional.
6. Fire pumps not on auto mode.
7. Exit & lift signages are not provided.

Yours faithfully

Receel
Bhu

Bharat Bhushan
9980137920

27/11/19

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

d/c
m