

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/WZ/2024/ 5-23 To,

Dated: 1 0 / 09 /2024

Sh. Sunil K Jain, Unity Buildwell Ltd., G-3, Aggarwal Corporate Tower, 23, Rajendra Place, Delhi-110008.

Sub: - Inspection report in r/o Plot No. C-4,5,6 Netaji Subhash Place, Pitampura, Delhi-34.

Sir,

This is in reference to your letter no. nil dated 27/08/2024 received via outdoor diary no. 5622 dated 27/08/2024 on the subject cited above. In this connection, it is to inform you that the above said building was inspected by the officer concerned by this department on 05/09/2024 in the presence of Sh. Ajay Chauhan to see the compliance of shortcomings communicated vide this department letter no. F6/DFS/MS/WZ/2024/444 dated 07/08/2024.

The status of the shortcomings observed is as under:-

Shortcomings	Status
Door closers of fire check doors found removed at some places.	Rectified
Smoke ventilation system in basement found removed.	Not Rectified
	Not Rectified
	Not Rectified
	Rectified
Sprinklers and sprinkler above false ceiling found removed at some places.	Not Rectified
Pumping system not found in auto mode.	Rectified
Exit signages found removed at some places.	Rectified
Refuge area found encroached at 9th floors shall be removed.	Rectified
	Door closers of fire check doors found removed at some places. Smoke ventilation system in basement found removed. Open able windows found replaced by fixed glasses at some places. Detectors found removed at some places. MOEFA found not functional at some places. Sprinklers and sprinkler above false ceiling found removed at some

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/ Occupier.

Yours faithfully

Delhi Fire Service