

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2024/SZ/College 290

Dated: | 0/ 09 /2024

To.

Office Registrar, DPSRU, Sector -3, Pushp Vihar M.B Road, New Delhi 110017.

Sub: Regarding renewal of Fire Safety Certificate in r/o Academic Block Dipsar-U, Dipsar, Pushap Vihar, New Delhi 110017.

Sir,

This is in reference with letter no F-20(47)/DPSRU/2016/-2021/5847-5857 dated 14/08/2024on the subject cited above received from Executive Engineer (E) PWD. In this regard, it is informed that the premised have been visited by concerned officer of this department on 04/09/2024 in the presence of Mr. Satbir Singh (PWD) & Dr. Vijender Kumar to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

- 1. Fire check doors found removed at some places in basement/ lift lobby/ staircase, self closing device at FCD's are not in working conditions and need repairing / replacement.
- 2. Smoke management system not working in the basement.
- 3. The First Aid Hose Reel Hose not working.
- 4. Detection systems in basement are partially provided (only in lift lobbies areas) and need to be extended in entire basement.
- 5. MOEFA Not working.
- 6. Automatic sprinkler systems are covered with fall ceiling at some places.
- 7. Internal and yard hydrant not working.
- 8. Fire fighting pumps are not on auto mode.
- 9. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Copy to:

1. The Executive Engineer (E) PWD EMID-M-South, Sukhder-Vihar, Mathura Road, New Delhi 110025