## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2024/ 563 To,

Mr. Ashish Thakur, Dr. Lal Pathlabs Ltd, Block-E, Sector-18, Rohini,

Delhi-110085.

For issuing of Fire Safety Certificate in r/o Dr. Lal Path Labs Ltd. Block-E, Sector-18, Rohini, Delhi-110085. Sir,

Kindly reference to online e-mail dated 23.08.2024, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 23.09.2024, in presence of Mr. Ashish Thakur (GM) ascertain the availability and operability of the fire prevention and fire safety measures. Your request for renewal of FSC is rejected under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Smoke ventilation system of upper floors found non functional, not integrated with detection system duct grills fund permanently blocked.

2. Main hydrant pump not in auto mode.

3. Many nitrogen cylinders found stored in staircase.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under: http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

Yours faithfully

011-23414000