

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

c/62



No. F6/DFS/MS/WZ/2024/SCHOOL/719
To,

Dated: 21/10/2024

Er. Vinod Kumar Parashar,
Executive Engineer (E),
PWD Edu. Elect. Edn. Div. (N),
ITI Campus, Pusa, New Delhi- 110012.

Sub: - Inspection report in r/o M/s. Govt. Co-ed Sr. Sec. School located at Ladpur, Delhi- 110081.
Sir,

This is in reference to your e mail id dated 25/09/2024 on the subject cited above. In this connection, it is to inform you that the above said educational building was inspected by the officer concerned by this department on 11/10/2024 in the presence of Sh. Sh. N.K. Deewan & Sh. Karnail Singh (Electrical Engineer) to see the compliance of shortcomings communicated vide this department letter no. F6/DFS/MS/2024/WZ/School/588 dated 03/09/2024.

The status of shortcomings is as under:-

Sr. No	Shortcomings	Status
1.	Fire Check doors are not provided as marked ob building plans.	Not Rectified
2.	Lift lobbies are not segregated with fire check doors..	Not Rectified
3.	MOEFA not provided as per clause 9.3.9 of UBBL- 2016.	Not Rectified
4.	Terrace level pump not found in auto mode.	Rectified
5.	Overhead tank of 20,000 ltrs capacity shall be made of steel/ RCC.	Not rectified
6.	Standby power supply found not provided.	Rectified
7.	Fire control room not provided.	Not Rectified
8.	Electrical panel of MP Hall shall be removed from the corridor or been segregated with fire check door.	Not Rectified

In view of the above shortcomings, the application for issuance of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,

(Atul Garg)
Director

Delhi Fire Service

16/10