436

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/School/2021/ 209 Dated: 13 /04/2021

To

The Principal,
Sarvodaya Kanya Vidyalaya (Janki Devi),
Mayur Vihar, Pockit-II, Phase-I, Delhi-91.

Sub: Regarding Renewal of FSC in r/o Sarvodaya Kanya Vidyalaya (Janki Devi), Mayur Vihar, Pockit-II, Phase-I, Delhi-91.

Sir,

This has reference to your letter no. SKV(JD)/PKT II/MV-1/2021/173 dated 16/03/2021 on the subject cited above. In this regard, it is to inform you that the premises was re-inspected by the officers concerned of this department on 07/04/2021 in the presence of Mr. Tek Chand Sharma (Principal Evening) and observed that no progress was seen on the observations communicated by this department vide letter no. F6/DFS/MS/School/NDZ/2020/624 dated 10/09/2020 (photo copy enclosed).

Hence, the Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under the intimation to this department for further necessary action in this regard.

Yours faithfully

SKTomar 21/4/21

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Encl:- as above.
Copy to:-
The Joint Director (Education),
Land & Estate,
Directorate of Education, Lucknow Road, Delhi - 110054.

C-31

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001

No.F6/DFS/MS/School/NDZ/2020/ 624 Dated: 10/09/2020

To,

The Principal
Sarvodaya Kanya Vidyalaya,(Janki Devi)
Mayur Vihar, Pocket-II,Phase-I, Delhi-91.

Sub: -Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Sarvodaya Kanya Vidyalaya,(Janki Devi) Mayur Vihar, Pocket-II,Phase-I, Delhi-91.

Madam,

Please refer to your letter Nil Dated 06/08/2020 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the NBC Part-IV. At the time of inspection Mrs. Seema Singh Rathi (Principal) was present and it was observed that the school building is comprised of two blocks ground plus one & two blocks ground plus three upper floors and have following shortcomings:-

1. An alternate staircase of 1.5 m shall be required in new building block or to be connected through ramp as constructed for first floor.
2. Hose reel provided but not functional.
3. Fire pumps provided but not functional.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

The Joint Director of Education (Land & Estate)
Directorate of Education, Lucknow Road, Delhi-110054.