

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI-110 001.

No. F6/DFS/MS/2011/1932

Dated: 10/08/11

FIRE SAFETY CERTIFICATE

Certified that the THE HERITAGE SCHOOL at Sector-23, Plot No-8, Rohini, Delhi-110085 comprised of Ground Floor + First Floor + Second Floor + Third Floor + Basement was issued NOC vide this office letter No. F.6/MS/DFS/2003/2805 dated 23/11/2003. The premises was re-inspected by the Officer concerned of this department on 02/08/2011 in the presence of **Sh. B.L. Nanda, Manager** and observed that all the fire safety and fire prevention arrangement are provided in the premises found in good working condition and there is no additional construction. The premises have therefore deemed complied with the requirement under Rule 33 of the Delhi Fire Service Rules, 2010 and building/premises is fit for occupancy under **Educational Class** with effect from 10/08/11 for a period of **03 (Three) years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule, 2010.

Issued on 10/08/11 at New Delhi by



Chief Fire Officer
Delhi Fire Service

o/c fwh

C.C

1. Shri B.L. Nanda, **Manager**,
Sector-23, Plot No-8,
Rohini, Delhi-110085
2. The Director (Education)
Old Sectt., Civil lines, Delhi

Conditions for the validity of fire safety certificate:-

- a) All the fire safety means of escape facilities shall be maintained in good conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non functional shall be responsibility of the management.
- b) Building sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c) The staff shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.

nil date 27.07.11 for Principal.

The Heritage School, Sector-23, Bahadur

The school was inspected by DO + ADO(R) on 29/7/2011.

The Shastri Camp Communicated

vide letter no. F6/NSC/DO/140/2011/17/16

date 26/07/11 have been complied.

1. The down cone/well near Septic was found functional on Auto mode.
2. The draw off connection has been found on UGWS tank.
3. Sprinkler system in basement has been extended.
4. The music classes have been stopped from the basement.

The report as per 20 point is as under.

Access to building — Available Ground

- (4) Compartmentation: is provided.
- (5) Smoke Management System: Adequate Natural & mechanical (Exhaust fans) also
- (6) Fire Extinguishers: A total of 28 fire extinguishers in combination of WCO_2 , CO_2 and ABC type found provided.
- (7) First Aid Nose Reel: is provided at each floor and found functional.
- (8) Automatic fire detection and alarming system: Not Required
- (9) M.O.E FA: Not Required
- (10) Public Address System: is provided & functional.
1. sprinkler system: is provided in

1620 lpm → Jockey pump 180 lpm
Terrace pump 450 lpm. found
functional.

② Captain water storage for fire fighting
overhead tank cap 25000 ltr
UG WS cap 2,00,000 ltr.

③ Exit Signage - Provided at each
floor.

④ Provision light - No left side.

⑤ Stand by power supply - available but not
required.

⑥ Refuge Area - Not required

⑦ Fire Control Room: Not required.

⑧ Special fire protection system for
machines & special risk. → There are
no special risk.

are having Two exits

School at Rahini. F.T. letter is
put up for consideration W.

~~Signature~~ 2/8

~~DeFO~~ 8/8

CFO 5/8

Rec-ndt
9-8-11

FT
9/8

F.T. letter is put up for signature please

~~C.F.O~~ 5/8

Signature 9/8

MS