GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/OFS/015/EH/2011/1964

Dated: 12/08/11

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name and style of TK'S THE TRI KITCHENS (Voda, Moti Mahal Deluxe, Princess Garden Restaurent at third floor) located at E 31-32, N.D.S.E., Part II Market, New Delhi - 110049 comprised of Basement, ground plus three upper floors was granted NOC by this department vide letter No. F6/MS/DFS/EH/2010/890 dated 23-03-2010. The premises was re-inspected by the officer concerned of this department on 25-07-2011 in the presence of Mr. Satish Kumar and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy with effect from 1.1-1.2-2.1.2-2.1.2011 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire service subject to conditions printed overleaf.

Issued .1.2./.08././. at New Delhi by.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

- The Dy. Health Officer, Health Department, Central Zone, Municipal Corporation of Delhi, Lajpat Nagar, New Delhi
- The Manager, TK'S THE TRI KITCHENS E 31-32, N.D.S.E. Part II Market, New Delhi-110049

May kindly see the above mentioned letter received from Sh. Satish Kumar, Manager, TK'S THE TRI KITCHENS (Voda, Moti Mahal Deluxe, Princess Garden Restaurent at third floor) located at E 31-32, N.D.S.E., Part II Market, New Delhi – 110049 regarding renewal of NOC from fire safety point of view.

In this connection, it is to inform you that the above mentioned restaurant building was granted NOC by this department vide letter No. F6/MS/DFS/EH/2010/890 dated 23-03-2010 and the premises have been inspected by the undersigned on 25-07-2011 to verify the existing fire safety arrangements already provided therein. At the time of inspection Sh. Satish Kumar, Manager was also present with the other staff.

During the course of inspection, it has been observed that the above mentioned restaurant is running at third floor of the building comprised of basement, ground plus three upper floors and approachable for fire service vehicles. Further the following fire safety arrangements required under rule 33 are provided.

- Access to Building: Provided. (Main ring road)
- Number, Width, Type and arrangement of exits: Two Exits (two staircase asses provided)
- Protection of Exits by means of fire check door(s) and or pressurization: Not required.
- Compartmentation : Not required.
- Smoke management system : Provided (Exhaust fans)
- Fire Extinguishers: Provided (Two water Co2 type F.E. having capacity 9 liters & Two Co2 type F.E. having capacity 4.5 kg. all ISI mark)
- First Aid Hose Reels : Provided.
- Automatic Fire Detection and alarming system : Not required.
- 9. MOEFA: (Manually Operated Electric Fire Alarm):
- Public Address System : Not required.
- 11. Automatic sprinkler system : Provided in the entire restaurant.
- Internal Hydrant and yard Hydrant : Provided. (Down comer system)
- Pumping arrangements: Provided (Main pump 450 Lpm. & Jockey pump 225 Lpm.)
- 14. Captive water storage for fire fighting : Provided (OHWST Tank 5,000 ltrs)
- 15. Exit Signage: Provided.
- Provision of Lifts: Provided two lifts with fireman grounding switch.
- Stand by power supply: Provided (D.G. set automatic in operation)
- Refuge Area: Not Required.

The above mentioned fire protection system were checked/tested randomly and found in good working condition at the time of inspection. In view of the above, this department may have no objection for the renewal of N.O.C. from fire safety and means of escape point of view subject to the conditions laid down in the fire safety certificate.

Accordingly fire safety certificate is prepared and put up for perusal and signature if approved please.

Submitted please.

DO (BCP) [1]

DCFO -I

widt y the star com / cexit

list and In ald Com yet

We are not measuring the width of skijous Brit. As MOC Was 14 and the basis of Govk of

NCT circular in which requireds

was for two SXI Independ of

width.

Submitted Steak