

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/2011/1963

Dated : 12/08/11

FIRE SAFETY CERTIFICATE

Certified that the school building in the name and style of Lalit Mahajan SVM School, Vasant Vihar, New Delhi comprised of ground plus three upper floors was granted NOC by this department vide letter No. F.6/DFS/MS/BP/2007/1228 dated 30-04-2007. The premises was re-inspected by the officer concerned of this department on 27-07-2011 in the presence of Mrs. Reeta Pant, Principal of school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy with effect from 12/08/2011 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire subject to conditions printed overleaf.

Issued 12/08/11, at New Delhi by.



CHIEF FIRE OFFICER
DELHI FIRE SERVICE

PCAM

Copy to:-

1. The Principal,
Lalit Mahajan SVM School,
Vasant Vihar, New Delhi-110056
2. Education Officer
Municipal Corporation of Delhi
Education Department, Zone-20/South West,
Vasant Vihar, New Delhi-110052

May kindly see the above mentioned letter received from The Principal, Lalit Mahajan SVM School, Vasant Vihar, New Delhi regarding renewal of NOC from fire safety point of view for the school building.

In this connection, it is to inform you that the school building was granted NOC by this department vide letter No. F.6/DFS/MS/BP/2007/1228 dated 30-04-2007. The school building has been re-inspected by the undersigned on 27-07-2011 to verify the existing fire safety arrangements and shortcomings already communicated vide this office letter No. F.6/DFS/MS/2011/940 dated 20-05-2011. At the time of inspection, Mrs. Recta Pant, Principal of school and the other staff were also present.

During the course of inspection, it was observed that the school building is comprised of ground plus three upper floors. The school building is abutting on main road which is approachable for fire service vehicles. The management of the school has removed all the shortcomings as communicated to them vide letter dated 20-05-2011. Further, the following fire safety arrangements required under rule 33 are provided.

1. **Access to Building** : Provided (Main 20.0 mtr. wide road)
2. **Number, Width, Type and arrangement of exits**: Provided (three staircases : one staircase is leading from ground to terrace having width 1.80 mtr. and two staircase are leading from ground to terrace having width 1.50 mtr. each)
3. **Protection of Exits by means of fire check door(s) and or pressurization** : Not required
4. **Compartmentation** : Not required
5. **Smoke management system** : Not required
6. **Fire Extinguishers** : 2 Nos. CO2 type fire extinguishers having capacity of 4.5 kg. ISI marked and 2 Nos. of Water CO2 type fire extinguishers of 9 liters capacity ISI marked at each floor).
7. **First Aid Hose Reels** : 1 No. first aid fire hose reel provided at each floor of the building.
8. **Automatic Fire Detection and alarming system** : Not required
9. **MOEFA : (Manually Operated Electric Fire Alarm)** : Provided
10. **Public Address System** : Not required.
11. **Automatic sprinkler system** : Not required.
12. **Internal Hydrant and yard Hydrant** : Down-comer system 1 No. hydrant at each floor and 1 No. Yard hydrant provided in the building.
13. **Pumping arrangements** : Provided (Main pump 900 lpm, 40 mtr. head and jockey pump 180 lpm, 40 mtrs. head)
14. **Captive water storage for fire fighting** : Provided (UGWST 50000 ltrs. and OHWST 10000 ltrs.).

15. **Exit Signages** : Exit signs at each floor.
16. **Provision of Lifts** : Not required
17. **Stand by power supply** : Not required
18. **Refuge Area** : Not Required.
19. **Fire Control Room** : Not required.
20. **Special Fire Protection system for protection of Special risks** :
2 Nos. of ABC type fire extinguishers capacity 5 kg. ISI marked,
provided near the electric panel board.

The above mentioned fire protection system were checked/tested randomly and found in good working condition at the time inspection.

In view of the above, this department may have no objection for renewal of N.O.C. from fire safety and means of escape point of view subject to the conditions laid down in the fire safety certificate.

Accordingly fire safety certificate is prepared and put up for perusal and signature if approved please.

Submitted please.

DO (BCP)

[Signature]
8/8

DCFO (I)

[Signature]
8/8

~~CSO~~
[Signature]
8/8

[Signature]
[Signature]
9/8

[Signature]

[Handwritten notes]
27-07-11
A.P. (S)

AS approved, FT letter is put up for your Signature Pl.