FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE [SEE SUB-RULE (1) OF RULE 35] GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/0F5/ans/2012/2030

Dated: 04/06/2012

FIRE SAFETY CERTIFICATE

Campus Narela, Delhi-110040, comprised of ground plus two upper floors only and more than 9 mtr in height but less than 15 mtr (approx. 39 ft), have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concern of Fire Service on 04.04.2012 in presence of Dr. Soni Anand (Prinipal) of the College and that the premises is fit for Educational class occupancy with effect from ... 0.4 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 04/0.6/12 at New Delhi by

Chief Fire Officer Delhi Fire Service

7c Jupa

Copy to:

Dr. Soni Anand (Prinipal)
 KASTURI RAM COLLEGE OF HIGHER EDUCATION
 Campus Narela, Delhi-110040Sh.

Shri Yogesh Aggarwal
 KASTURI RAM COLLEGE OF HIGHER EDUCATIONE
 E-53, Main Outer Ring Road, Prashant Vihar, Delhi-110085.

Note: For general fire safety directives please over leaf.

May kindly see the letter No KRCHE/GGSIP/001/ dated 02.04.2012 received from Shri Yogesh Kumar Aggarwal, Secretary, KASTURI RAM COLLEGE OF HIGHER EDUCATION, E-53, Main Outer Ring Road, Prashant Vihar, Delhi-110 085 from fire safety point of view. Premises was inspected by the ADO (Bawana) on 04.04.2012 & observed that the building is comprised of ground plus two floors only and having plot area 4000 sq meters and covered area is 1360 sq. meters.

The point wise compliance of the safety recommendations as per Delhi Fire Service Act, 2007 & Delhi Fire Service Rules, 2010, are given below:

INSPECTION REPORT

1.	Name &address of the building	:	KASTURI RAM COLLEGE OF HIGHER BOUCATION, NAMEL
2.	Type of Occupancy	:	Educational Blog.
3.	Type of Case	:	New Care
4.	Details of previous NOC	:	NA
5.	Fire Safety directives letter No.	:	APS Act 2007 & DPS Act, 2010
6.	Date of inspection	: .	04.04-2012
7.	Name of the Inspecting Officers	:_	SHRI RAJMAL KHOKHAR
8.	Name and designation of officers	:_	DR SONI AWANG
9.	From the building side	:	PRINCIPAL
10.	Year of Construction	:	2005
11.	Applicant's letter No.	:_	KRCHE/GGSIP/001 St. 02:04.2012

S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			1
	Road width	Accessible	Accessible	ml
	Gate width	-tv		-cle
	Width of internal road	- ,	_	_
2. Number, Width, Type & Arrangement of Exits				
	a. Number of staircases	Two	Two	ma
	Upper Floors	-a-		
	Basement		-	_
	b. Width of staircases	150 Cms each	150 Cus each	mil
	Upper Floors	N	-61	-u
	• Basement	-	-	-
	c. Protection of exits	:-		
	• Fire check door	-		~
	 Pressurization 	_	-	~

	I. No. of continuous staircases to terrace	Two	Two	md		
	e. Width of Corridor	12 Melers 100 Cus CTWOOD	2 Melus 100 Cms (To	-10-		
	f. Door size	100 Cus (Twod	100 Cms (Tw	ma		
3.	Compartmentation.		NB			
	Fire check door		,			
	Sealing of electrical shafts			-		
	Fire Rating of shaft door	_	-			
	Water Curtain	-		_		
	• Fire Dampers	_		-		
4.	4. Smoke Management System.					
	Basements	-		6		
	Upper floors	_	-	-		
5.	Fire Extinguishers					
	Total numbers		15	mn		
	• Types		ABC Type 151 Marled	ml		
	IS marking	ISI marked	151 Marked	m.l.		
6.	First-Aid Hose Rees.					
	Total numbers on each floor	3	3	ml		
	Length of hose reel hose	30 m	30 mbs	ms		
	Nozzle diameter	5 mm	5 mm	ml		
7.	Automatic fire detection and aları	NA				
	Type of detectors	- 	-	1-		
	Location of Main Panel	,)	,		
	Location of Repeater Panel	<u>-</u>	-			
	Alternate source of power	-	-	-		
	Hooter's Location	-		~		
8.	MOEFA	-	· h	~		

Kasturi Ram college of Hister Education, warely

	111 1 1 1 1	Museum fam and of the conserver of		
	ablic Address System.	Repuired	Provided	mn
	Automatic Sprinkler system	-	NA	
1	Basement	-		
	Upper Floor			-
	 Sprinkler above false ceiling 	S))
11.	Internal Hydrants			
	Size of riser/down-comer	NR	Post and A	
	 Number of hydrants per floor 	NR	Provided One at each Horr	F
	Hose Box	NR		-
2.	Yard Hydrants.		NA	
	Total number of hydrants		~	•
	Hose Box		_	_
3.	Pumping Arrangements.			
	Ground Level			
	Discharge of main pump			-
	Head of Main pump	<u>ئ</u>	1	
	Number of main pumps	<u> </u>		•
	Jockey Pump out put		2	
	Jockey pump head	-	-	-
	Standby pump out put		1	•
	Standby pump Head		,	
	Auto Starting/Manual stopping	-	-	
	➤ Pump Hose Access	_	_	
	Terrace level	Repured	Provided	mR
	Discharge of pump	450 Cpm	909 Lpm	-ur
	➤ Head of the pump	40 mhs	40 mbs	
	Power supply		, , , , , , ,	
	11-5	-		

Kasturi Ram college of Hyner Education, were

	aptive Water Storage for fire fig	ghting.	///		
			NA		
	Underground tank capacity	i serre	-	~	
	> Draw -off connection	=	£	-	
	Fire service inlet	7	_	-	
	> Access to tank	<u>,</u>	-	-	
	Overhead Tank Capacity	10000115	Provide	MR -	
15	Exit Signage.	Repured	Provi cled	mil	
16.	Provision of Lifts	•	NA		
	Pressurization of Lift Shaft	•	1	_	
	Pressurization of Lift lobby	-	1	-	
	Communication In lift Car	-	-	C	
	• Fireman's Grounding Switch		-	-	
	Lift Signage		_	-	
17.	Standby power supply	+ -	NA		
18.	Refuge Area	_	AN	_	
	> Total Area		-	-	
	> Location	_	_	_	
19.	Fire Control Room		MA		
				-	
	Detector System Panel		~	_	
	➤ Flow Switch Panel	•		-	
	> PA system Panel	-			
	> Batter backup	-	-		
	Building Floor plans	-	-	_	
20.	Special Fire Protection Systems for				
	Protection of special Risks, if any:	_	_		

he fire protection systems provided in the building were test checked and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial number....

Signature of the Inspection Officer

Officer

Signature of the Inspection

Name SHRI RAJMAL GUOKHAR

Name

Designation ASSTT. DIV. OPPICEL

Disignation

DO (NW)

on perusal of the plan it was found the second.

Shair case in not approachable at every groon. The case.

A is not recommended as such may kindly be seen so that short coming is communicated to be letter.

ADO Bahdana.

Hereddary changes have been made in the plan accordingly fil.

20(N.W)

1 is enommended to