GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/DFS/MS/EH/2012/274/

Dated: 27/07/12

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name and style of Café Bikaner at ground floor located at Bikaner House, (Rajasthan Govt. Bldg.), Pandara Road, New Delhi comprised of ground plus one floor was granted NOC by this department vide letter No. F6/DFS/MS/EH/2008/3444 dated 16-12-2008. The premises was re-inspected by the officer concerned of this department on 18-07-2012 in the presence of Mr. K.S. Ghambir and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for Class D (Assembly) occupancy with effect from .2.7./.27./...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .2.7/.o.7.//... at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- 1. M/s Café Bikaner Restaurant, Bikaner House, (Rajasthan Govt. Bldg.), Pandara Road, New Delhi
- 2. Medical officer of Health, Health Department, Palika Kendra, Sansad Marg, New Delhi-110001

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTIO Cafe	B: Vanes. K	Postaurant, 81	Kanor House
1. 1	Name & address of the building : (Rajas	sthan Gout.	building) Pan	dasa Road,
2.	Type of Occupancy : Ass	embly (Re.	stansant)	Del ti -1/000
3. '	Type of Case : New Case			The state of the s
			4/2008/3444 Dated	
	Fire Safety directives letter No : N.			
	A Mills Sequence Approximate Committee Committ	07-2012		
	Name of the Inspecting Officers: 2ka	em vie sing	A yadav.	
8.	Name and designation of officers		Media (Die	tel
			nbair (Dize	102)
		sting year	1	Til H 22-28 12
S. 10.		,	Provided at site	Remarks
No.	3.7	NBC Requirement	A I UVIUCU AL SILE	MD/MMD
170.	prevention and fire safety U/R 33	Kedim emem		old case
1	Access to building			4
	Road width		More than 12 m	
	Gate width	N. A	N.A	N.A
	Width of internal road	MA	N.A	N.A
2	Number, Width, Type & Arrangement o	f Exits		
	a. Number of staircases	N. A	N.A	N.A
	· Upper Floors (Ground flows	N.A	N.A	N.A
	Basements	N.A	N.A	N.A
	b. Width of staircases			v.
	Upper Floors	N. A	N.A	N.A
	Basements	N.A	w.A	N.A
	c. Protection of exits			
	Fire check door	N.A	N. A	N.A
	 Pressurization 	N. A	NA	N.A
	e. No. of continuous staircases to terrace	N.A	NA	N.A
	g. Width of Corridor	N. A	N.A	NA.
	h. Door Size (Two Exits Provided)	N.A	N.A	N.A
	h. Door Size Two Exils Provided	100		emtol

empl;

cafe Bikanel Restaulant Bikanel House (Ragasthan sat. bailding) Pandala Road
New Delli 110001

	Commonter		Anne anger et saarie Valuabilian den en en ege skalphaliske ongederen sjalen hengelskal skalphaliskele ander en	
	Compartmentation.			
884.	• Fire check door			ment, in contrast trast. Any other desired following to contrast the contrast trast.
	odding of electrical sharts			
	Fire Rating of shaft door		N.A	alatan dia silanggana nyana dia pina anakayay ay an-daya ay amininganin dayab indo-ay aliban
	• Water Curtain			The state of the s
	 Fire Dampers 			enter vill troub development med medicalles. Also my vely colorente del cuestant
•	Smoke Management System.			
	· Basements (Restausant at	30 a/c per hour	N. A	N. A
	• Basements • Upper floors (Restautant at Ground floor only)	12 a/c per hour	N. A Exhaust Fans	M.R
	049)			The state of the s
) .	Fire Extinguishers	*		entral contraction and compared public degrees again again and an entraction again and a second
	Total numbers		ABCType= 2	M.R
	• Types		Total = 4 Nos	m.R
	IS marking	ISI marked	yes	M.R
6	First-Aid Hose Reels.	4		
	Total numbers on each floor	one	one	M-R
	 Length of hose reel hose 	30 m	yes	m.R
	Nozzle diameter	5 mm	yes	M.R
7	Automatic fire detection and alarming	system.		
	• Type of detectors	0.000	1	MORNY TARIS TO A STATE OF THE PROPERTY OF THE
	Location of Main Panel			
	 Location of Repeater Panel 		N. A	
	Alternate source of power	3		
	Hooters' Location			and the second s
8	MOEFA	yes	Provided	N. R
9	Public Address System.	N.A	N. A	N.A
10	Automatic Sprinkler System.			
	• Basement	N.A	N.A	N.A

contal:

cafe Bikanes Restausant, Bikanes House (Rajas than govt building) fundasa Road, wew seldi-1/1000/

	• Upper Floor	N. A	N.A	N.A
	Sprinkler above false ceiling	N.A	N.A	
1	Internal Hydrauts			*
	Size of riser/down-comer			
	 Number of hydrants per floor 	•		
	Hose Box		W.A	
2	Yard Hydrants.			
The second second second second	And descriptions and the second state of the s			7
	Total number of hydrantsHose Box		N.A -	A CONTRACTOR OF THE CONTRACTOR
3	Pumping Arrangements.		N.A _	
-	• Ground Level			
				The second secon
	- to that go of main Pump			
	> Head of Main pump			
	> Number of main pumps			
	> Jockey Pump out put		4 1	And the second s
	> Jockey pump head		N. A	
	> Standby Pump out put	•		
	> Standby Pump Head			
	> Auto Starting/ Manual			
	stopping	\$		<i>CP</i>
	> Pump House Access			
	Terrace level			
	Discharge of pump	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	225 LPM	M.R
	> Head of the pump		30 m teg	m. Pill
	> Power Supply	Electricity	Electricity	M.R.
	> Auto Starting of pump		starting sur tea	m. R
14	Captive Water Storage for fire fighting.		rouded at grow	W. T.
	Underground tank capacity		- N. A _	
	> Draw-off connection	•	NA -	

contd:

Cafe Bikanos Restaurant Bikanos House (Rajasthan goo's building) pandala Road New Delki-1/2001

	The second secon			
	Fire service inletAccess to tank	xes	Provided	M.R
	Overhead Tank capacity	N.A	N.A	N.A
15	A STATE OF THE PROPERTY OF THE	2500 lite		m.R
16	Exit Signage. Provision of Lifts.	yes	Provided	M.R
	Management of the control of the con			
	Pressurization of Lift Shaft			
	Pressurization of Lift lobby	The second		
	* Communication In lift Car		10.0	
	Fireman's Grounding Switch		N. A	
	• Lift Signage			
177		ar usa		and the state of t
17	Standby power supply	yes	D. G. Set	m.R
18	Refuge Area.			
	> Total Area	N. A	N.A	N.A
	> Location .	N.A	NA	N.A
19	Fire Control Room	•		
	Detector System Panel			
	Flow Switch Panel			water are considered to the constant of the co
	• PA System Panel	aller skappen van verste skrive street de kalende skrive skrive skrive skrive skrive skrive skrive skrive skrive	N.A	
	Batter backup			
	Building Floor Plans			
	Squaing Tilon Lights			
20	Special Fire Protection Systems			The state of the s
20	Special Fire Protection Systems for Protection of special Risks, if any:		N. A.	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Cafe Bikanes Restaurant, Bikanes House (Rajasthan givt building) Pandasa Road New beds:-11000 Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dhaem vie singh yadav. Name Designation Assistant Divisional Designation Do. (central)