## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 275/

Dated: 27/07/12

## FIRE SAFETY CERTIFICATE

Certified that the Dada International Guest House, 3339-3968-71, Kaseruwalan, Pahar Ganj, New Delhi-110055 comprised of ground floor (04 guest rooms + reception), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (08 Guest rooms at each floor) and 4<sup>th</sup> floor (02 guest rooms + 01 staff room + 01 servant room and D.G. Set) Total 30 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2035 dated 08-07-2009. The premises was re-inspected by the officer concerned of this department on 19-07-2012 in the presence of Sh. Salahuddin Khan (manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 30 guest rooms with effect from......2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued...at New Delhi by.

CHIEF FIRE ØFFICER DELHI FIRE SERVICE

Copy to :-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony. New Delhi–110049.

2. M/s Dada International Guest House, 3339-3968-71, Kaseruwalan, Pahar Ganj, New Delhi-110055

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTION REPORT							
	1. Name & address of the building: <u>Dada International Guest House</u> , 3330 Kasezuwalan, Pahar Genj, New Dell							
	2	2. Type of Occupancy :	Lodging House		7-1-14eco <u>Pexill</u>			
	3		Revewal					
	4	4. Details of previous NOC : L	etter No F6 Ms L	OFS   GH   2009   20	035 dated 08-67-2009			
	5	Fire Safety directives Letter No.:						
	6	6. Date of inspection :	19-07-2012					
	7	Name of the Inspecting Officer: Sh. D.S. Yadav (A.D.O.)						
	8	Name and designation of Officer						
from the building side Sh. Salahuddin Khan (Manage								
		P. Year of Construction :	2					
	10. Applicantis letter No.: 28357   ADAI. CP/GC (H) dated 11/05/12							
			(		old case			
S No		Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR  P.S.S. AREA			
1.	+	Access of building  • Road width	4					
		Gate width	-06 M tre	6 Mt/8-	mK			
			NA	NA	MA			
		Width of internal road	NA	NA	NA			
2.	_	Number, width, Type & Arrangement	s of exits					
		a. Number of staircases						
		• Upper floors	01	0)	mK			
		Basements	MA	NA	NA			
		b. Width of staircases						
		• Upper floors	125 Cms.	128 Cms.	me			
		• Basements	MA	MA	NA			
		c. Protection of exits		× ×				
		Fire check door	MA	NA	NA			
		<ul><li>Pressurization</li><li>d. No of continuous staircase</li></ul>	NA	NA	NA			
		to terrace	01	01	mR,			

Dada International Dr. Guest House, 3339-3964-71, Kescrusalan, P.G., H.D.

Width Of Corridor Door Size 3. Compartmentation Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers Smoke managements System 4. Basements 30 a/c per hour MA NA Natural ventilation Upper floors 12 a/c per hour MR Fire Extinguishers 5. Total numbers 10 MR Types Water Coz & mil ISI marked A.B.C. IS marking Provided MR 6. First - Aid Hose Reels Total numbers on each floor \_01 MR 01 Length of hose reel hose Provided 30 Mbs MR Nozzle diameter Provided MR 5 M.M. 7. Automatic fire detection and alarming system Type of detectors Location of Main Panel Location of Repeater Panel NA Alternate source of power Hooters' Location 8. **MOEFA** Yes Provided 9. Public Address System Yes Provided 10. Automatic Sprinkler System Basements Upper Floor Sprinkler above false ceiling 11. Internal Hydrants Size of riser/down-comer MA MA NIA

Dada International Guest House, 3339-3969-71, Kesermusalan, P.G., sed care XI.D.

	\$			ded cure /4
19/	<ul> <li>Number of hydrants per floor</li> </ul>	XIA	HA	LIA
/	Hose Box	NA	MA	NA
12.	Yard Hydrants			77.1
-	<ul> <li>Total number of hydrants</li> </ul>	MA	MA	XIA
	Hose Box	NA	NA	MA
13.	Pumping Arrangements		1 7 7 1	7471
	<ul> <li>Ground Level</li> </ul>			
	Discharge of main pump			
	> Head of main pump			
15	Number of main pumps			
	Jockey pump out put		NA	
	Jockey pump head		/	
	Standby Pump out put			
	<ul><li>Standby Pump Head</li><li>Auto Staring/Manual stopping</li></ul>			
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>	/	,	
	<ul><li>Discharge of pump</li></ul>	225ch	225 LPM	MR
	Head of the pump	30 Mts.	30 Mts	MR
	Power supply	Electric	Electric	mx
	Auto starting of pump		Switch Provide	mr
14.	Captive water Storage for fire fighting	a	at G.F.	1.11
	Under ground tank capacity		11.0	A
	<ul><li>Draw of connection</li></ul>	NA	NA	NA
	Fire service inlet	NA		MA
	Access to tank		NA	MA
		MA	NA	NA
1.7	Overhead Tank capacity	2500 Us	2500 Hrs.	MR
15	Exit Signage	Yes	Provided	MR
16.	Provision of Lifts.	9		
	➤ Pressurization of Lift Shaft	HA	NA	NA
	Pressurization of lift lobby	NA	NA	NA
	Communication in lift Car	Yes	Provided	mR

Dada International Guest House, 3334, 3969-71, Kaserywalau, Pahar Gaig, H.D. Fireman's Grounding Provided Yes Switch ' ➤ Lift Signage Provided 17. Standby power supply Yes D. G. Set MR 18. Refuge Area > Total area MA MA > Location MA MA Fire control room 19. > Detector system panel NA RIA > Flow Switch Panel MA NA 1114 PA System Panel NA NA Batter backup

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

XIA

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Signature of the Inspecting Officer

> Building Floor Plans

Special Fire Protection Systems for

Protection of special Risks, if any;

Name

rvanne

20.

Designation

De

Signature of the Inspecting Officer

XIA

Name Dhasm vie singh yadov

Designation Assistant Divisional efficel (centeal)

NIA

XIA

Do. Centers 2 7 01/2