## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 2726

Dated: 26/07/12

## FIRE SAFETY CERTIFICATE

Certified that the New Ringo Guest House, 903, Chandiwalan, Pahar Ganj, New Delhi110055 comprised of ground floor (05 guest rooms + reception), 1<sup>st</sup> to 3<sup>rd</sup> floor (05 guest
rooms at each floor), 4<sup>th</sup> floor (Sealed by MCD) total 20 guest rooms was granted NOC
by this department vide letter No. F6/DFS/MS/GH/2009/2392 dated 31-07-2009. The
premises was re-inspected by the officer concerned of this department on 16-07-2012 in
the presence of Sh. Vikram (manager) and found that the said guest house building have
deemed complied with the fire prevention and fire safety requirements in accordance with
rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of
20 guest rooms with effect from 2.6/.57./...2012 for period of three years in
accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40
and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules,
2010.

Issued 2.6/67/12. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049.
- 2. M/s New Ringo Guest House, 903, Chandiwalan, Pahar Gang, New Delhi-110055.

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECT	TON REPORT	ecti house 9	703			
1	Name & address of the building: Cha	ndiwalan,	Palas Gant,	vea velle			
2							
3	Type of Co						
4	1 Details 6						
5	Fire Safety directions letter 1						
6	Date of inner it						
7	Name of the Inspecting Officers: Drawn with singh yadow.  Name and desired:						
8	Name and designation of officers	phasm vis si	ingh yadau.				
	C						
9	Year of Construction	to the san	m (managel 2001				
	). Applicant's letter No.						
S.	Minimum Standards on fire	NIL dei	1	9/2			
No.	prevention and fire safety U/R 33	NBC	Provided at site	Remarks			
1	The second secon	Requirement	*	MR/NMR			
<u> </u>	Access to building PSS AS						
	<ul> <li>Road width</li> </ul>	MA	N. A	N.A			
	• Gate width	N.A	N.A	Complete, springs and strangers and transfer and advantage of the design of the security of th			
	<ul> <li>Width of internal road</li> </ul>	N.A	MA	N.A N.A			
2	Number, Width, Type & Arrangement of			N.H			
	a. Number of staircases	77 358163					
	<ul> <li>Upper Floors</li> </ul>						
	Basements	N. A	one	m·R			
100 miles	b. Width of staircases	N.A	N. A	N.A			
	• Upper Floors						
	* Basements		109 cms to	m.R			
		N.A	N.A	N.A			
	c. Protection of exits	9					
	• Fire check door	N-A	N.A	N.A			
	• Pressurization	N. A	N.A	N.A			
	e. No. of continuous staircases to terrace		one	M·R			
	g. Width of Corridor	·N.A	N.A	N.A			
	h. Door Size	N.A	N.O	NA			
		A monattra a supplement manuscription and manuscription and manuscription of the supplementary and sup	- I amount of the second of th	contal.			

contal.

New Ringo Greet Horace, 903, chandiwalan, palar Grans, New Della HOSS

Compartmentation. Fire check door Sealing of electrical shafts N.A Fire Rating of shaft door Water Curtain Fire Dampers Smoke Management System. 4 Basements 30 a/c per hour 12 a/c per hour ratural ventilation Upper floors Fire Extinguishers 5 Total numbers M.K Types M.R IS marking ISI marked m.R 6 First-Aid Hose Reels. Total numbers on each floor one one m.R Length of hose reel hose 30 m Ves M.R Nozzle diameter 5 mm Ves M.R Automatic fire detection and alarming system. 7 Type of detectors Location of Main Panel Location of Repeater Panel \*. Alternate source of power Hooters' Location 8. MOEFA N. A 9 Public Address System. yes Automatic Sprinkler System. 10 Basement N.A

contd:

New Ringo Quest House 903, chandinalan, fahak Gant, New Dellar 110015

1	The same of the sa			1/0055
	• Upper Floor		1/. 0	old ca
	Sprinkler above false ceiling		N.A -	P3:
11	Internal Hydrants		N.A -	
	Size of riser/down-comer			7
	<ul> <li>Number of hydrants per floor</li> </ul>			
	• Hose Box		N. A	
2	37			
-	Yard Hydrants.			
	<ul> <li>Total number of hydrants</li> </ul>		2 46 0	
3	Hose Box		N.A -	
3	Pumping Arrangements.		N.A -	
	Ground Level			
	Discharge of main Pump			
	Head of Main pump		.5	
	Number of main pumps			
	> Jockey Pump out put		N.A	
	> Jockey pump head	9		
	> Standby Pump out put			
	Standby Pump Head			
	Auto Starting/ Manual			
	stopping			17
				par .
	➤ Pump House Access  Terrace level			
	> Discharge of pump		(0. (0.	
	Head of the pump	•	180 LPM	W-Y
	Power Supply	90-to.1	30 NTS	M.R.
-	Auto Starting of pump	reclicity	chotics on to	MANIE
(	Captive Water Storage for fire fighting.	- Pa	vided at ground	flag - M.R
	The state of the s			
1	Underground tank capacity		N.A	
	> Draw-off connection		- N.A	

contal:

New Ringo Guest House, 903 chandiwalan, Pahak Gang New Delli-1/055

		* * * * * * * * * * * * * * * * * * * *	** at	old case
	> Fire service inlet	N.A	N.A	ps.s pera
	Access to tank	N.A	N.A N.A	NA.
5	Overhead Tank capacity	2500 lite	2500 Lites Provided	m.R
6	Exit Signage.  Provision of Lifts.	yer	Provided	m·R
7	Pressurization of Lift Shaft  Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage  Standby power supply		N.A D.G. set	m. R
8	Refuge Area.			
	<ul><li>Total Area</li><li>Location</li></ul>		N. A -	
9.	Fire Control Room		N. A	
	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>		N. A	
20	Special Fire Protection Systems for	-		
	Protection of special Risks, if any:		N. A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

New Ringo Guest House, 903 chandiwalan factor Gant, New Delli-11055.

Signature of the Inspecting Officer

Name

Designation

Do. (cented) 10/07/12

Signature of the Inspecting Officer

Name Dhaem vis singh yadow

Designation Agistant Divisional officel (central)