GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001**

No. F6/MS/DFS/GH/2012/ 3 2 54

25

Dated: 07/09/12_

FIRE SAFETY CERTIFICATE

Certified that the Star Plaza Guest House, 5158, Main Bazar, Pahar Ganj, New Delhi-110055 comprised of basement {lower GF} (storage) ground floor (reception + office) 1st floor to 3rd floor (08 Guest rooms at each floor) and terrace floor (generator room and staff kitchen), total 24 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1533 dated 29-05-2009. The premises was re-inspected by the officer concerned of this department on 27-08-2012 in the presence of Sh. Sohan Lal Mittal (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 24 guest rooms with effect from .57/...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Issued .07./0.8.//2. at New Delhi by.

> CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 990 16-09-12 po (cd) 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049: w. r. t. letter No. 28324-25/Addl/ C.P./ Lic (H) New Dlehi dated 11-05-2012.
- 2. M/s Star Plaza Guest House, 5158, Main Bazar, Pahar Ganj, New Delhi-110055.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION	ON REPORT	to House, 5158	, main Be			
Name & address of the building Lakes						
	ng house	2				
Type of Case : New Case/ Renewal						
Details of previous NOC : Letter No. F6/DFS/MS/GM/2009/Dated: 29-05-200						
Fire Safety directives letter No: -N.A-						
6. Date of inspection	27-08-2012					
7. Name of the Inspecting Officers: 20	hasm vie sing	ch yadav.				
8. Name and designation of officers						
from the building side	es sohan La	l mittal.	The state of the s			
9. Year of Construction	esting year 2	009.	Mark of Ministration and continuous and property and property of the continuous and the c			
10. Applicant's letter No.	NIL	dt. 11-06-2	0/2			
Minimum Standards on fire	NBC/884	Provided at site	Remarks			
o. prevention and fire safety U/R 33	Requirement		MR/NMR			
Access to building			Pea			
 Road width 	-N.A-	more than	m.R			
• Gate width	-N.A-	- N-A-	-N.A-			
Width of internal road	-N.A -	-N.A.	-N.A-			
Number, Width, Type & Arrangement of	of Exits					
a. Number of staircases	9					
Upper Floors	one	one	M.R			
• Basements (L. G.F)	one	one	n.R			
b. Width of staircases	A CONTRACTOR OF THE CONTRACTOR					
 Upper Floors 	0.80 mts	01.25 MZ	ES M.R			
• Basements (1.G-F)	0.80 MT88					
c. Protection of exits			Was an acceptance between the state of the s			
• Fire check door	N-A	N.A	N.D			
Pressurization	N.A.	N-A	N-A			
e. No. of continuous staircases to terrace	ene	one	m-R			
g. Width of Corridor	N. A	N-8	N.A			
	10	N. A	NA			

contd:

N.A

N.A

h. Door Size

Star plaza quest mouse 5158, main Bazos.

old case

Cor	mpartmentation.						
	Fire check door						
	• Sealing of electrical shafts		N-A	The second secon			
and the second second	• Fire Rating of shaft door						
	Water Curtain	:					
	• Fire Dampors	,					
Smoke Management System.							
	 Basements 	30 a/c per hour	- N.A -	NA.			
	• Upper floors	12 a/c per hour	ratusal ventiles	too Mil			
F	Fire Extinguishers						
	 Total numbers 	Ten	Ten	M.R.			
	• Types		Ten cortyped w.cor Type yes.	M.R			
	IS marking	ISI marked	yes.	M.R			
6 F	First-Aid Hose Reels.						
ļ	• Total numbers on each floor	one	one	m·R			
	 Length of hose reel hose 	30 m	provided provided	m. R			
	Nozzle diameter	5 mm	Psovided.	m. R			
7	Automatic fire detection and alarming system.						
	• Type of detectors						
	• Location of Main Panel						
	• Location of Repeater Panel		N.A				
	Alternate source of power			and the second second section of the second			
	 Hooters' Location 						
8	MOERA	het	Provided.	m.R			
9	Public Address Systém.	yes	Provided.	n. R			
10	and the second s						
	• Basement	N. A	N.A	N. A			

contal:

Stor plaga quest house, 5/58 main Bagas pahar Gang, New Delli-1/055

 Upper Floor Sprinkler above false ceiling Internal Hydrants 11 Size of riser/down-comer Number of hydrants per floor Hose Box Vard Hydrants. Total number of hydrants * Hose Box Pumping Arrangements. Ground Level > Discharge of main Pump > Head of Main pump Number of main pumps > Jockey Pump out put > Jockey pump head > Standby Pump out put > Standby Pump Head > Auto Starting/ Manual stopping > Pump House Access Terra e level > Lischarge of pump > Head of the pump > Power Supply > Auto Starting of pump 14 Captive Water Storage for fire fighting. Underground tank capacity > Draw-off connection

conta:

State Plaga such house, 5158, main Bazor Paras Gang.

old case

-	The same of the sa			Old Colo
	Fire service inlet	-N.A -		
	> Access to tank	-N-A-		Commence of the second
·	 Overhead Tank capacity 		e sour lite	e m.e
15	Exit Signage.	yes	Provided	m.R.
16	Provision of Lifts.	700	Prividea	M. X
	* Pressurization of Lift Shaft	XIA-		
	Pressurization of Lift lobby	74.		To the first the second
	* Communication In lift Car	-N.A-		
	Fireman's Grounding Switch	Yes	Provided	mR
	Lift Signage	Yes	Provided	MR
177		Yes	Provided	MR
17	Standby power supply	Electricity	Electricita	M·R
18	Refuge Area.		7	
	> Total Area	- N.A -		
	> Location	- N.A -		
10	Fire Control Room			
(c) Depolers	Detector System Panel	- N-A -	а .	
	* Flow Switch Panel	N-A		
	PAl System Panel	- N-A -		
	Batter backup	- W:A -		
-	Building Floor Plans	N.A.		
20	Special Fire Protection Systems for	" " "		
Victoria de la constante de la	Protection of special Risks, if any:	- NA -		,
was it is				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi are Service Rules 2010/ issue shortcomings as noted at serial numbers.

Stor playa quest laise (158, mais Bajar Palar Gans, New Delhi - //055 gg-08-12 Signature of the Inspecting Officer Signature of the Inspecting Officer Name Design vil singly yater Name Designation peristant sivisione Designation Submitted for approval placese.