GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001**

No. F6/MS/DFS/GH/2012/ 3264

Dated: 67/09/12

FIRE SAFETY CERTIFICATE

Certified that the White House Tourist Lodge, 8177-78, Arakashan Road, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + office + STD cabin) 1st floor to 3rd floor (10 guest rooms at each floor), terrace (big hall and kitchen for staff), total 30 granted NOC this department rooms, was by F6/DFS/MS/GH/2009/2267 dated 27-07-2009. The premises was re-inspected by the officer concerned of this department on 04-09-2012 in the presence of Sh. Vijay Kumar Vij (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 30 guest rooms with effect from $\Omega \lambda = 0.12$ for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 97/98./12... at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- geme 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049 wrt.47785-86/Addl.C.P./Lic.(H)New Delhi dated 31-07-12
- 2. M/s White House Tourist Lodge, 8177-78, Arakashan Road, Pahar Ganj, New Delhi- 110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTI	ON REPORT W	hite house To Kashan Road	urist Lodge		
1. Name & address of the building pakes Gant new Della-110055					
2. Type of Occupancy : Lodging house.					
3. Type of Case : New Case/ Renewal					
4. Details of previous NOC : Letter No $\frac{F6}{DFS} \frac{M \cdot S}{M \cdot S} \frac{S}{S} \frac{M \cdot S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} \frac{M \cdot S}{S} \frac{S}{S} \frac{M \cdot S}{S} M \cdot $					
5. Fire Safety directives letter No : NIL					
5. Date of inspection	The state of the s				
7. Name of the Inspecting Officers: Z	harm vir si	izh yadov.	Section 20		
8. Name and designation of officers					
from the building side	Lei vijay	Kumaz VIJ			
9. Year of Construction	1981 starting	year			
10. Applicant's letter No.		1 21-08-2012	2.		
. Minimum Standards on fire	NBC	Provided at site	Remarks		
prevention and fire safety U/R 33	Requirement	(P.S.S. Area)	MR/NMR		
Access to building	Access to building old case				
 Road width 	N.A	06 Mtes Apple	or M.R		
• Gate width	N.A	NA	NA		
Width of internal road	N.A	N.A	N.A		
2 Number, Width, Type & Arrangement	h	and the second s			
a. Number of staircases					
Upper Floors	one	TWO	M.R		
Basements	N.A	N.A	N.A		
b. Width of staircases					
 Upper Floors 	0.80 Mts	(2) 83 cms to 105	CMS M.R		
Basements	N.A	N: A	N.A		
c. Protection of exits			The second second second second second		
Fire check door	N. A	N-A	N.A		
Pressurization	N.A	N.A	N.A		
e. No. of continuous staircases to terrace		02	MR		
g. Width of Corridor	N.A	N.A	N.A		
h. Door Size	N.A	N.A	N.A		

White house Tourist Lodge, 8/17-78,
ARDRASLAN Road, Pakor Grand,
New Delli-110055.

old case

	Compartmentation.	-			
	 Fire check door 				
	 Sealing of electrical shafts 		N.A	and the second regards and the second regards	
The state of the s	 Fire Rating of shaft door 		1		
1	 Water Curtain 			managan (alaka dan kacamatan arawa dan 19 - 19 at 19 a	
	• Fire Dampers	5-			
	Smoke Management System.				
	 Basements 	30 a/c per hour	N. A Natural ventilat	N.A	
	• Upper floors	12 a/c per hour	Natural ventilat	ion M.R	
5	Fire Extinguishers				
	• Total numbers	10 (Ten)		M.R	
	Types	- '	CO2 Type & W. Co2 Type. Provided.	M.R	
	IS marking	ISI marked	Provided.	M.R.	
5	First-Aid Hose Reels.				
	• Total numbers on each floor	one	one	M.R	
	 Length of hose reel hose 	30 m	Provided.	M.R	
	Nozzle diameter	5 mm	Provided.	M.R	
7	Automatic fire detection and alarming system.				
	 Type of detectors 			3	
	Location of Main Panel				
	• Location of Repeater Panel			And the second s	
			N.A		
	Alternate source of power				
	 Hooters' Location 				
8	MOEFA	- N. A-	N.A	N.A	
9	Public Address System.	yes	Provided		
10	Automatic Sprinkler System.	<u> </u>			
	Basement	N. A	N. A	N. A conta	

White Louse toulist lodge, 8177-78, Alanaslan Road, palae Gang, New Delli 21/0055.

old case

				Ola Cose
School of States	Upper FloorSprinkler above false ceiling	-N.A -		<i>y</i> .
11	Manus and the department of the contract of th	-NA -		
	Internal Hydrants		A second	· W
	Size of riser/down-comer Number of the desired services and the services are the services and the services are the services	- N.A -		The second section of the second section is a second section of the second section sec
To the desired to the contract of the contract	Number of hydrants per floor Hose Box	-N.A -		managed and the second
		-N.A -		3
12.	Yard Hydrauts.	A CARLON CONTRACTOR OF THE CARLON CONTRACTOR O		
	 Total number of hydrants 	- N.A -		The second secon
	* Hose Box	- N.A -		
13	Pumping Arrangements.	Annual section of the		The state of the s
	* Ground Level	- N.A -		
	Discharge of main Pump	-NA-	29	
	> Head of Main pump	-NA-		
	Number of main pumps	- N.A -		
	> Jockey Pump out put	- N.A -		
	> Jockey pump head	-NA-		
	> Standby Pump out put	- N. A -		
	Standby Pump Head	-N.A -		
	Auto Starting/ Manual			1
	stopping	- N.A -	3	\$*
	Pump House Access	-N.A.		
	* Terra e level	1050 1000	1 - 10	
	Elischarge of pump	450 LPM		N.R
	· Head of the pump	30 M teg	30 NTES	M. R. Wills
	Power Supply	Electricity	Electricity	MA
	> Auto Starting of pump		gwitch provided	at M.R
14	Captive Water Storage for fire fighting.			
	Underground tank capacity	-N.A -		
	> Draw-off connection	-N.A -		
	The state of the s	Belleville from the series were street to the contract of the	The second secon	

contd: -

White house Tourist Lodge, 8/77-78 Alakashan Road, pakel Gong New Delli-1/0055

old cose

1			* * · · · · · · · · · · · · · · · · · ·		
	Fire service inlet	- N.A-		Secretary Secret	
	> Access to tank	-NA -		The state of the s	\
	 Overhead Tank capacity 	2500 Ditse	s 2500 lite	P M.R	
15	Exit Signage.	yes	8 2500 lites Provided	M·R	
16	Provision of Lists. (one lift provided but not in use)				
	* Pressurization of Lift Shaft				-
	Pressurization of Lift lobby	/	TO ST. Name of the party of the same of		
	* Communication In lift Car	W. A			
	Fireman's Grounding Switch			a hadan — manafasi hala sa sirana managa mar ku bi i yan minagani kula s	
	* Lift Signage				
	084				
17	Standby power supply	yel.	A. G. get	m.R	
18	Refuge Area.			and independent programs of the second state of the second	1
	> Total Area	-N.A-			-
	➢ Location	- N.A -			
10	Fire Control Room				
:	Detector System Panel	- N.A -		*	
	* Flow Switch Panel	- N.A - - N.A -	and the second s		
	PAi System Panel	-N.A	THE SE, ISS. ARREST Substanting or examples their Security and Employ in Environment A sec.) we		
	Batter backup	- N.A -			
-	Building Floor Plans	- N.A -			
20	Special Fire Protection Systems for Protection of special Risks, if any:	- N.A -			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi safety Service Rules 2010/ issue shortcomings as noted at serial numbers.

X

white house torreist lodge, 8177-78, Alakaskan Road, pahas Gang New Delhi-1/0055 Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dhasm vis singh yadan Name Designation Assistant Divisional Designation officel (central) Forwarded for approval please.