GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 3 5 27

Dated: 25/08/12

FIRE SAFETY CERTIFICATE

Certified that the Shailey Guest House, 4256. Tel Mandi, Pahar Ganj, New Delhi-110055 comprised of ground floor (01 guest room + reception + office), mezzanine and 1st floor (03 guest rooms at each floor), 2nd floor and 3rd floor (04 guest rooms at each floor), total 15 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1978 dated 06-07-2009. The premises was re-inspected by the officer concerned of this department on 12-09-2012 in the presence of Sh. Chhotey Singh (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 15 guest rooms with effect from .25./.03./...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .2.5./0.8.//2_ at New Delhi.

Chief Fire Officer Delhi Fire Service

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049 w.r.t. letter No. 44163/Addl. C.P./(H) dated 12-07-2012.
- 2. M/s Shailey Guest House, 4256, Tel Mandi, Pahar Gang, New Delhi-110055.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

Name & address of the building Shaila	y Guest Hous	Della -1/005	ince,			
	odging house					
Type of Case : New Case/ Renewal /						
Details of previous NOC : Letter No $FG/DFS/M-S/GH/2009/1978$ Dated: $06-07-20$						
5. Fire Safety directives letter No :	-N.A -	11978	The second series are series where			
5. Date of inspection	12-09-12					
7. Name of the Inspecting Officers	Dharm vie.	singh yadar. (A.	20)			
8 Name and designation of officers		V				
from the building side	chhotey sin	gh (owned)				
9. Year of Construction	1982 Start	ish (owner) teng year				
10. Applicant's letter No.	NIL date	d 26-07-2	0/2			
Minimum Standards on fire	NBC	Provided at site	Remarks			
prevention and fire safety U/R 33	Requirement		2 MINNIR			
Access to building			i caje			
 Road width 	-N.A-	6 Mbs. Approx.	M.R.			
Gate width						
 Width of internal road 	-N.A-					
Number, Width, Type & Arrangement o	The state of the s		Comments of the second control of the comments of the control of t			
a. Number of staircases		2 / 1	CONTROL OF THE CONTRO			
 Upper Floors 	01 NO	6/ NO.	M.R			
• Basements	0/ NO -N.A-					
b. Width of staircases						
 Upper Floors 	80 Cms.	100 Cms	me -			
Basements	- N.A-					
c. Protection of exits						
Fire check door	- N/ W -	_	And the second s			
· Pressurization	- 14. 17		The second of th			
e. No. of continuous staircases to terrace		01	MR			
g. Width of Corridor	01		111/			
h. Door Size	- N.A-		and a second of the second sec			
II. DUOL SIZO	_ M, A -		Contd. +			

Shailey Gruest House, 4256, Tel Mandi, Pahar Gain, New Delli -110055

	9 N N			
Con	upartmentation.			
	• Fire check door	-N.A-		
	• Sealing of electrical shafts	-N: A-		
	• Fire Rating of shaft door	-N, A -		MANAGEMENT CONTROL OF
	Water Curtain	- N, A -		manufacture from the control of the
	• Fire Dampors	-N.A-		
Sn	noke Management System.			
	 Basements 	30 a/c per hour	- X.A-	- M, A-
	 Upper floors 	12 a/c per hour	Matural Ventilation	m MR
	.\			THE RESIDENCE OF THE PROPERTY
5 Fi	ire Extinguishers	,		
	 Total numbers 	16	10	mR
1	* Types		Water Coz & A.B.C.	MR
	IS marking	ISI marked	Provided	MR
6 J	First-Aid Hose Reels.			The state of the s
pp pp and pp	 Total numbers on each floor 	01	01	mR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	ig system.	and an arrangement of the second of the seco	1
	• Type of detectors	- H, A -	ol 5	
	• Location of Main Panel	- N. A -		
	• Location of Repeater Panel	-NA -		
	Alternate source of power	- N.A -		
	• Hooters' Location	-N.A -		
8	MOEFA	-N.A-		
9	Public Address Systém.	408	Provided	MR
10	Automatic Sprinkler System.			
	Basement	-N.A-		

contd:-

Shailay Grest House, 4256, Telmandi, Pakar Grant, New Delhi -110055

			e e ₁₀ ,	
	Fire service inlet	-N.A-		The second secon
	> Access to tank	-N.A-		
	Overhead Tank capacity	2500 lites	2506 littles	M.R V
15	Exit Signage.	yes.	Provided-	M.R.
16	Provision of Lifts.			The same of the sa
	* Pressurization of Lift Shaft	-N.A-		- Control of the Cont
	Pressurization of Lift lobby	-N. A-		
	* Communication In lift Car	_ N, A _		
	Fireman's Grounding Switch	- N. A -		
	* Lift Signage	_ N. A -		
17	Standby power supply	yes.	D.G. Set	ns-R
13	Refuge Area.			And with the second sec
of dead, one objective.	> Total Area	-N.A-		
	> Location	-N.A-		
10	Fire Control Room			
	Detector System Panel	-N.A-		
	Flow Switch Panel	-N.A -		
1000	PAl System Panel	-N.A.		The second secon
	Batter backup	- N.A -		
-	Building Floor Plans	- N.A.		
20	Special Fire Protection Systems for Protection of special Risks, if any:	-N-A		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi see Service Rules 2010/ issue shortcomings as noted at serial numbers.

Shailay Guest House, 4286, Telmande fahalGant, New Delli-110055 Signature of the Inspecting Officer Signature of the Inspecting Officer Name Plasm vil sigh yelow. Name Designation Assistant Divisional Designation Do. (C.D)
Submitted please