GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 3795

t.

Dated: 15/10/12

FIRE SAFETY CERTIFICATE

Certified that the Mother Palace Guest House, 1454, Sangatrashan, Pahar Ganj, New Delhi-110055 comprised of ground floor (01 guest rooms + reception + 01 store), 1st floor to 3rd floor (04 Guest rooms at each floor) and 4th floor (rooms sealed by MCD), total 13 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2460 dated 10-08-2009. The premises was re-inspected by the officer concerned of this department on 27-09-2012 in the presence of Sh. Ram Pratap (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 13 guest rooms with effect from 1.1.1.2.1....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued ... 7./10./1.2. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi–110049 wrt. No.41256-57/Addl.C.P./Lic.(H) New Delhi dated 27-06-2012
- 2. M/S Mother Palace Guest House, 1454, Sangatrashan, Pahar Ganj, New Delhi-110055
- 3. Dy. Commissioner, MCD, Sadar Pahar Ganj Zone, Idgah Road, Delhi with a request to get height of the building measured and send intimation to Delhi Fire Service.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTI	ON REPORT Me	other Palace G	quest house,		
Î	1454	sangaties.	Ther Palace G	Gant		
1.	The out and out the outfords	NEW Dellas	-110055			
2.		ing house.	The second secon	1		
j.		e/Renewal				
4.	Details of previous NOC : Letter No		Dated	A CONTRACTOR OF THE PARTY AND ADDRESS.		
5.	Fire Safety directives letter No FG/DFS	e Safety directives letter No FG/DFS/MS/G-H/2009/2460 dated 10-08-2007				
٠ <u>.</u>	A Property of the Contract of	27-09-12.				
7.	Name of the Inspecting Officers : Dha	alm vil sin	sh yadar (A.	80)		
8.	Name and designation of officers					
	from the building side Shei Ram platap (owner) 9. Year of Construction 10. Applicant's letter No. 11. Applicant's letter No. 12. Shei Ram platap (owner) 13. Applicant's letter No. 14. 256-57/Addl-cP/Lic(ii) dold new Dollate 27-12.					
9,						
10	Applicant's letter No. 41256	-57/Addl-CP	Lic (i) dated we w	· Dollitte 27-00		
	Minimum Standards on fire					
¥0.	prevention and fire safety U/R 33	Requirement		MR/NMR		
	Access to building			The second secon		
A CONTRACTOR OF THE PARTY OF TH	 Road width 	- N.A -	102.5 Mtgs wide	e M.R		
	• Gate width	-N.A-				
	Width of internal road	-NA-		AMERICAN AME		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	0-80 Mtz	01-25 MES	M.R V		
	Basements	- N.A -				
	b Width of staircases					
	Upper Floors	one	one	m·R		
	Basements	- N.A -				
	c. Protection of exits					
	• Fire check door	- N.A -	a market de apparent de apparent de apparent de apparent de la companya de la companya de apparent de la companya de apparent			
	Pressurization	-N.A -				
	e. No. of continuous staircases to terrace	one	one	M.R		
	g. Width of Corridor	-N.A-				
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	h. Door Size	- N.A -				
Ĭ	The second secon	Adjusting a state of the second state of the s	and the set of the representative of the research of the research of the set	contd:		

Mother Palace Guest house, 1454, sangetrashan, palace Gant New Delli - Moss.

10	compartmentation.			
1	Fire check door	- N.A -		
	• Sealing of electrical shafts	- NA -		
	Fire Rating of shaft door	-N-A -		
	Water Curtain	-NA -		
man (12) (mild) - Ally (Mil)	• Fire Dampers	- N.A -		ender som eller som det som eller som eller som eller som eller som eller som eller eller eller eller eller el
	Smoke Management System.	A CONTRACTOR OF THE PARTY OF TH		
	 Basements 	30 a/c per hour	- N.A -	M.R
an endergegen com Constitute	Upper floors	12 a/c per hour	Natural ventere	to M-R
	\			and the second s
5	Fire Extinguishers	3	The second secon	or an about the letter of a second and the letter of the l
-	 Total numbers 	08 NOZ	ABC Type &	M-R
	• Types		ABC Type &	M.R.
Special section of the section of th	IS marking	ISI marked	· · · · · · · · · · · · · · · · · · ·	Management of the second of th
6 First-Aid Hose Reels.				
and a definition and profession of the	Total numbers on each floor	one	Provided Provided	m·R
	 Length of hose reel hose 	30 m	Provided	M.R
	Nozzle diameter	5 mm	Provided.	M.R
7	Automatic fire detection and alarmin	ig system.		1
	Type of detectors	-N.A -		
	Location of Main Panel	-MA-		
	• Location of Repeater Panel	-N.A -		
The state of the s	Alternate source of power	-NA -		
and the second s	Hooters' Location	- N.A -		
8	MOERA	- N.A -		
9	Public Address System.	-N.A -	Provided	M·R
15				
	Basement	-N.A -		

Mother Palace Guest House, 1454, sangoldushan, Pahal Gran, New Delli-11005.

	Upper FloorSprinkler above false ceiling	-N.A-			
		- N.H -			
	Internal Hydrants				
	• Size of riser/down-comer	- N.A -			
	 Number of hydrants per floor Hose box 	- N.A-			
	* Hose Box	- N.A - - N.A - - N.A -	· ·		
. 1	Vard Hydrants.				
40.000	 Total number of hydrants 	-N.A -			
	* Hose Box	-N.A -			
	Pumping Arrangements.	Commence in the manager of the second section of the second second section of the second second second section second sec			
and the second second	 Ground Level 				
1	Discharge of main Pump	-NA-			
	Head of Main pump	-N.A -			
	Number of main pumps	- N.A -			
	> Jockey Pump out put	-NA -		of PT-12 (1997)	
	Jockey pump head	-N.A -			
	> Standby Pump out put	- N.A -		the state of the same transportation and the state of the same transportation and transportation	
	Standby Pump Head	- N.A -			
	Auto Starting/ Manual			1 34	
	stopping	- N.A -		0	
	Pump House Access	-N.A -	• \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	• Terra e level	2			
	> Lischarge of pump				
	· > Head of the pump	30 Mtl	30 MTL8	MR	
	Power Supply	flecticity	Heaterity Drawing	M.R.	
	> Auto Starting of pump		at ground flow	M.R.	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	-NA-		an annu turingan dalam mana terapah agamanan sami sari sari saketah m	
	> Draw-off connection	-N.A -		e e consideración de la co	

mother Palace Guest house, 1454, sangat Eashan, Pahar Gang, wew selfer

			2 w s s s		
	Fire service inlet Access to tank	-N.A -			
i	research to think	-N.A -		i	
	 Overhead Tank capacity 	2500 littes	2500 liters Provided.	M.R.	
	Exit Signage,	Yes	Provided.	M.K	
16	Provision of Lifts.				
	* Pressurization of Lift Shaft	- N.A -	y x		
	Pressurization of Lift lobby	- N.A -			
	* Communication In lift Car	-N-A -		The second secon	
	Fireman's Grounding Switch	-N:A -			
	* Lift Signage	-N.A -			
	Standby power supply	yes	D.G. set		
1.3	Refuge Area.				
	> Total Area	-NA -			
	> Location	-N.A -			
10	Fire Control Room				
	Detector System Panel	- N.A -			
	 Flow Switch Panel 	- N.A -	The same of the sa		
	PAl System Panel	- N.A -			
	Batter backup	-M.A			
2-2	Building Floor Plans	-NA			
20	Special Fire Protection Systems for Protection of special Risks, if any:	-N-A-			
				The second secon	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi standards on fire prevention and fire safety

re Service Rules 2010/ issue shortcomings as noted at serial numbers....

contdo-

Mother Palace Greet house, 1454, sangateaschan, Palace Grand, New Decki-11005F Signature of the Inspecting Officer Signature of the Inspecting Officer Name (DAARM WR SINGH YADAU) Name Designation Assistant Divisional Office (central) Designation

1