GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001**

No. F6/MS/DFS/GH/2012/ 39 05

Dated: | 9 | | 0 | 12_

FIRE SAFETY CERTIFICATE

Certified that the Sidhartha Tourist Lodge, 3428, Desh Bandu Gupta Road, Pahar Ganj, New Delhi-110055 comprised of ground floor (02 guest rooms + reception) 1st floor (03 guest rooms), 2nd floor (03 guest rooms + 01 store), 3rd floor (03 guest rooms), 4th floor 03 guest rooms), total 14 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2340 dated 29-07-2009. The premises was re-inspected by the officer concerned of this department on 09-10-2012 in the presence of Sh. Inder Nath Chopra (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 14 guest rooms unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .).9.1.2. at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony New Delhi-110049 w.r.t .letter No. 28609/Addl.C.P./Lic.(H)New Delhi dated 14-05-12
- 2. M/s Sidhartha Tourist Lodge, 3428, Desh Bandu Gupta Road, Pahar Ganj, New Delhi- 110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECT	TON REPORT	t Lodge 34	28.		
i.	Name & address of the building	Bandher gup	t Lodge, 34	Ras GanJ,		
7.	Type of Occupancy Lodg	ing House	110055.			
3	Town	Ise/ Renewal	Standard and Maley Standard and Maley and Advanced and Ad			
4	Details of previous NOC					
5	5. Fire Safety directives letter No. 1 - N. A - Dated 29-07-200					
5	6. Date of inspection $09 - 10 - 2012$					
7	7. Name of the Inspecting Officers : Dhasm vie singh yadav.					
8	Name and designation of officers			**************************************		
	from the building side Sk	le Inder Na	the chopsa.			
	Year of Construction : 2	00/ starting	2 glas "	200		
1			Lico(H) New Dell	B'At. 14-5-12		
S.	Minimum Standards on fire	NBC/BBL	Provided at site	Remarks		
No.	prevention and fire safety U/R 33	Requirement		MR/NMR		
1	Access to building			old case		
	 Road width 	-NA-	18 Mts 8 appear	ix M.R.		
	• Gate width	- N.A -	10.7	777(
	 Width of internal road 	-N.A -				
7	The second section of the section of the section of the second section of the section o	The state of the s				
	Number, Width, Type & Arrangement of a. Number of staircases	of Exits				
			600			
	• Upper Floors	one	one	M.K.		
	Basements	-N.A-				
	b Width of staircases					
	Upper Floors	0.80 M ts	0.82 Mts.	M.R		
	Basements	-N.A -	American respective and a contract of the cont			
	c. Protection of exits					
The second second	• Fire check door	- N.A -				
	Pressurization	-N.A-				
i i	e. No. of continuous staircases to terrace	one	one	M.R		
1	g. Width of Corridor	-N.A -				
	h. Deor Size	-N.A -				
*				contdi-		

Sidholtha Tolllist lodge, 3428, Desh Bandhel Gufta Road, Paral Gans, New Delli 110055

	Compartmentation.				
-	• Fire check door	-N.A			
	 Sealing of electrical shafts 	- N.A -			
	 Fire Rating of shaft door 	-N.A -N.A -			
	Water Curtain	-NA-		The second secon	
	• Fire Dampors	NA -			
	Smoke Management System.				
	• Basements	30 a/c per hour	-N.A - Natural ventilai	1. M.R.	
	 Upper floors 	12 a/c per hour	Natrical ventilal	(ON	
				galled again, year o'connisse i assent on Politic on A. (Sec). Sec. (Addis, 1971)	
	Fire Extinguishers				
l.	 Total numbers 	08 NOS	08 NO8 ABCTYPE & COS Type	M.R.	
	Types			m.R	
	IS marking	ISI marked	yes.	M.R.	
)	First-Aid Hose Reels.				
	Total numbers on each floor	one	one	MR	
	• Length of hose reel hose	30 m		mR	
	Nozzle diameter	5 mm	Provided.	MR	
7	Automatic fire detection and alarming	system.			
	Type of detectors	-NA-		35	
	Location of Main Panel	- N.A -		9	
2.7	• Location of Repeater Panel	- N.A -	¥ *		
×	Alternate source of power	-N.A -			
	Hooters' Location	- N.A -			
8	MOERA	- N.A -			
9	Public Address System.	-N.A -	Peovida	M.A	
10	Automatic Sprinkler System.				
	 Basement 	_ N.A -		contd:	

Sidhartha Tourist Lodge, 3428, Desh Bandhel gupta Road, New Della - 1/055

	 Upper Floor 			
	Sprinkler above false ceiling	-N.A -		
11		-NA -		
	Internal Hydrants			
	• Size of riser/down-comer	-N.A -		
	 Number of hydrants per floor Hose box 	-N.A -		
7		-N-A-	The second secon	
-	Yard Hydrants.			and the second s
	Total number of hydrants	-N:A-		
7.4	* Hose Box	-NA-		
of self-one on colong.	Pumping Arrangements.			
	Oroding Level	-N.A-		
	Discharge of main Pump	-N.A -	.,	
	road of Main pump	-NA-		-
į	ramoer of main pumps	-NA -		
	> Jockey Pump out put	- NA -		
	> Jockey pump head	-N.A -	* 10	
111111111111111111111111111111111111111	> Standby Pump out put	-N.A -		
-	Standby Pump Head	-N.A -		
	Auto Starting/ Manual			
1	stopping	- N.A -		7.
And the second second	> Pump House Access	-N.A -	,	
-	• Terra e level	7.//		
-[.	> Lischarge of pump	180 LPM	180 LPM	M.R ~
	Head of the pump	30 Mtgg	180 LPM 30 M tsg	M. Resign
	Power Supply	Dectricity	Electricity	MA
-	Auto Starting of pump		Switch Prove	led MR
	Captive Water Storage for fire fighting.	A change of the	al ground fle	8
	 Underground tank capacity 	- N.A -		
	> Draw-off connection	- N.A -		

contd:

Sidhartha Tourist Lodge, 3428, Desh Bandhu gupta Road, Parar Gang, New Dolla-110255

Water China China a page	The same of the sa		1 a v.X		
	Fire service inletAccess to tank	- N.A -			
	 Overhead Tank capacity 		e 2500 lite	8 M.RV	
15	Exit Signage.	Yes	Provided.	M.R.	
16	Provision of Lifts.				
	* Pressurization of Lift Shaft	-N.A-		The state of the s	
	Pressurization of Lift lobby	-N.A-		3.	
	* Communication In lift Car	- N.A -		3	
	Fireman's Grounding Switch	-NA -	(3)		
	 Lift Signage 	· NA			
17	Standby power supply	Jeg.	D.G. Set	M·R	
13	Refuge Area.				
	> Total Area	-N.A-			
of the state of th	> Location	-N.A -			
10	Fire Control Room				
	Detector System Panel	-N.A-		1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	* Flow Switch Panel	- N.A			
	PAl System Panel	- N.A -	2	7	
	Batter backup	-NA-		2	
	Building Floor Plans	- N.A.			
20	Special Fire Protection Systems for Protection of special Risks, if any:	- N.A -			
		99			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi

sidhartha Tourist Lodge, 3428, Desh Bandhu gupta Road, pahar Gang New Delli-11015 Pof 09-10-12 Signature of the Inspecting Officer Signature of the Inspecting Officer Name D.S. yadav.

Designation ADO (ED)

Submitted please.

Name

Designation