GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/GH/2012/ 3 999

Dated: 25/10/12

FIRE SAFETY CERTIFICATE

Issued on 251012 at New Delhi by.

Chief Fire Officer Delhi fire service

Copy to: -

- 1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi w.r.t. your letter No.53848 /Addl.C.P/Lic(H) dated 13-09-2012
- 2. The Manager, M/s Shyam Palace guest house, 8228 & 8230, Arakashan road, Paharganj, New Delhi

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

	20		- 0				
1	1. Name & address of the building: Shyam palace, 8228 f 8230, A.K. Road, 2. Type of Occupancy : Lodging house Paharganj, New Delly,						
2	. Type of Occupancy : Lodging house Pahargany, New Delly,						
3	Type of Case : New Case/ Renewal						
4	Details of previous NOC : Letter No. Fo D & ms GH/2009 2133 Dated: 16 7 2009						
5	. Fire Safety directives letter No :						
6		12/10/2012					
7	. Name of the Inspecting Officers:	DO M. K.C	hallopadhyay				
8	À I	\mathcal{N}	P 1	10000			
	from the building side : $\underline{\mathcal{M}}$		ler Rawat, N	ranagos			
	. Year of Construction :	1990	01. (11)	12/2/2			
			·P/4·c(H) deled	13 9 2012			
S.	Minimum Standards on fire	NBC	Provided at site	Remarks			
No.	prevention and fire safety U/R 33	Requirement		MR/NMR			
1	Access to building	8 -	T				
	Road width	Spl area	9 ont approx.	MR			
	• Gate width	_	Directly accordible	MR			
	Width of internal road	MA	n) 4				
2	Number, Width, Type & Arrangement of	of Exits					
	a. Number of staircases	-	- 49				
	Upper Floors	01	01	MR			
	 Basements 	N) A	NF/A	-			
	b. Width of staircases	-	-	-			
	Upper Floors	0.80mt.	1,30m+	MR -			
	Basements	MA	7 4	-			
	c. Protection of exits	MA	m) 4	MA			
	Fire check door	MA	74	MA			
	 Pressurization 	MA	MA	MA			
	e. No. of continuous staircases to terrace	01	01	MR			
	g. Width of Corridor	MA	MA	MA			
	h. Door Size	MA	MA	n r			
		_					
3	Compartmentation.	MA	MA	MA			

19

	• Fire check door	MA	MA	75
	• Sealing of electrical shafts	MA	MA	MA
	 Fire Rating of shaft door 	MA		The same of the sa
	Water Curtain	MA	7/4	MA
	Fire Dampers	MA	74	N/A
4	Smoke Management System.		MA	MA
	• Basements	30 a/c per hour	0	
	 Upper floors 	12 a/c per hour	174	MA
			N A	MA
5	Fire Extinguishers			
	• Total numbers 8		provided	04.0
	· Types valir Co, Co, DCP	,	provided	MR
	• IS marking ABC	ISI marked	provided	me
	First-Aid Hose Reels.			
	 Total numbers on each floor 	01	provided	MR
	 Length of hose reel hose 	30 m	provided	MR
-	Nozzle diameter	5 mm	bosn.gen	MIZ
	Automatic fire detection and alarming	system.	* **	
	Type of detectors	MA	MA	MA
	 Location of Main Panel 	NA	MA	
	 Location of Repeater Panel 	DD 0		MA
The state of the s	 Alternate source of power 	MA	MA	MA
To the second second	 Hooters' Location 	MA	MA	Mr
+		MA	MA	MA
+	MOEFA	Required	provided	me
+	Public Address System.	Required	poovided	MR
+	Automatic Sprinkler System.			
- Production of the Party of th	Basement	MA	MA	b 0 .
-	 Upper Floor 	b 0		MA
-	 Sprinkler above false ceiling 	/'1	Mr	MA
	Internal Hydrants	MA	mn	MA
	• Size of riser/down-comer	MA	MA	MA

9

	 Number of hydrants per floor 	MA	MA	MA	
	• Hose Box	MA	MA	71	
12	Yard Hydrants.				
	 Total number of hydrants 	MA	MA	7)A	
	Hose Box	MA	MA	MA	
13	Pumping Arrangements.	,		/	
	Ground Level	MA	MA	MA	
	Discharge of main Pump	MA	Ma	MA	
	Head of Main pump	MA	WA	MA	
	Number of main pumps	50	MA	MA	
	Jockey Pump out put	N A	60	n/l	
	Jockey pump head	W a	MA	17	
	Standby Pump out put) 'T	M	MA	and the contract of the contra
	Standby Pump Head	MA	A	MA	
	Auto Starting/ Manual	MA	MA	nga	
	stopping	~) A	n) A	MA	
	Pump House Access	74	Mr	MA	
	Terrace level	_	Salaman.		
	Discharge of pump	225 LPM	275 LPM	MR	
a	Head of the pump	15 mt	V5 mr	MR	
	Power Supply	· ·	10 KUA	MR	
	Auto Starting of pump	-	provided near reception	n MR	
14	Captive Water Storage for fire fighting	5.		3	
	 Underground tank capacity 	MA	m a	MA	
	Draw-off connection	N/ A	ŊA	MA	
	Fire service inlet	JA	MA	MA	
	Access to tank	MA	MA	72	
	Overhead Tank capacity	25 n 1 k.	2500 lh.	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.		-	2000	
The state of the s	Pressurization of Lift Shaft	MA	MA	2x	
	T. Company of the Com				

is	7	
7	4	
r	71	
L	12_	
	MA	
,	MA	
	V°	

	Communication In lift Car	MA.	MA	74		
	Fireman's Grounding Switch	MA	MA	7A		
	Lift Signage	MA	MA	MA		
17	Standby power supply	Required	10 KUA	MR		
18	Refuge Area.					
	> Total Area	MA	MA	MA		
	Location	MA	m 4	MA		
19	Fire Control Room					
	Detector System Panel	N) A	MA	M/r		
	 Flow Switch Panel 	MA	77 4	MA		
	 PA System Panel 	MA	N/A	W/A		
	Batter backup	MA	7) 4	MA		
	Building Floor Plans	NA	NA	MA		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	One ABC life Jui extensione pourded hear Elect pance	MR		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew/grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

Name M.K. CHATTO PADHYAY
Designation ADO (HQ)

Submitted please.
Why