GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No.

F6 10 F3 | Ms | Gn | 2012 | 4067

Dated:

30/12/2012

FIRE SAFETY CERTIFICATE

Certified that the Mall Bank Hotel located at E-2/14, East Patel Nagar, New Delhi-110008 comprised of Basement, Ground floor plus two upper floors, using basement as Hall/Storage, ground floor as reception & four guest rooms, first & second floor each having eight guest rooms respectively (Total Twenty guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/09/2793 dated 14.09.2009 owned/occupied by Sh. Inder Pal Singh. The guest house building was re inspected by the officers concerned of this department on 24.09.2012 in the presence of Sh. Harash (Asstt. Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010, there is no additional construction and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 20/12/2012 at New Delhi.

Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.41249-50/Addl. C.P./Lic.(H), Dated 27.06.2012)

oh

2. Sh. Inder Pal Singh (Owner)
Mall Bank Hotel,
E-2/14, East Patel Nagar,
New Delhi-110008.

CIPY

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPEC	TION REPORT					
	1. Name & address of the building:	Name & address of the building: Mall Bank Hotel, E-2116 Fort Padel 1840					
	2 Type of Occupancy :	Residential (Gruest House)					
	A Dotale (D	: New Case/Renewal : Letter No. F.6 DFS/ms GH 09 2793 Date 14 . 09 . 200 9					
	A CEGUS OF LIEATORS MAC						
	5. Fire Safety directives letter No :6. Date of inspection	College Section 1 and a section of the section of t	NIA				
	7 Name of Inspecting Officer :	24.09.2012					
	8. Name and designation of officers	D.O H.L. Ane	ja & A. D.O 1	P.S. Dahiya			
	From the building side :	}					
	9. Year of Construction	Batan ga	(ASSH. Mange				
	10. Applicant's letter No. Minimum Standards on fire Before 2007 41349-Sol Add1. C.P. Lic (H) dafed 27/06						
5.	Minimum Standards on fire	NBC/BBL	Provided at				
No.	prevention and fire safety U/R 33	Requirement		Remarks			
1.	Access to building	requirement	316	MR/NMR			
	 Road width 	Accessible	30mts	MR			
	 Gate width 		320 cm \$				
	 Width of internal road 		Jack	MR			
2.	Number, Width, Type & Arrangement	of Exits					
	a. Number of staircases						
	• Upper Floors	Two					
	• Basements	One	Two	MR			
	b. Width of staircases	VII	One	MR			
	 Upper Floor 		19 Com Com				
	Basements	· ·	100 Chas	MR, Being Old case			
	c. Protection of exits		TOUCMS	-do-			
	 Fire check door 	MA					
	• pressurization	NIA					
	d. No. of continuous staircases to			American Control of the Control of t			
	terrace e. Width of Corridor		One				
	f. Door Size	•	200 cm 8, 135 cm 8				
	350. 3726	According to the second	the second second second second	The state of the s			
3.	Compartmentation	•	87cms x 235cms				
	Fire check door						
	 Sealing of electrical shafts 	NIA		PATE NAME OF TAXABLE PATE NAME			
	 Fire Rating of shaft door 		Sealed				
	Water Curtain	NIA	VCCICA				
	• Fire Dampers	NIA					
1		NIA					
4.	Smoke Management System						
	Basements	30 a/c per	Exhaust fans				
	 Upper flctors 	hour	are Provided	MR			
			Natural Ventilati	on MR			

		12 a/c per				
		hour				
j.	Eiro Call		i	~		
	Fire Extinguishers			1		
	 Total numbers 	Two at each flo	Provided	5-0		
	 Types 	Co2, W Co2	-do-	me		
j.	IS marking	ISI marked	-clo-	MR		
) 	First-Aid Hose Reels		- 00 -	MR		
	 Total numbers on each floor 	One	Provided			
	 Length of hose reel hose 	30 m		MR		
	 Nozzle diameter 	5 mm	- do -	MR		
7 .	Automatic fire detection and alarming	svstem	-do-	MR		
	 Type of detectors 	NIA				
	 Location of Main Panel 	MIA		+		
	 Location of Repeater Panel 	NIA				
	 Alternate source of power 	747 77		1		
	Hooters' Location		D. G. Set of 125 KVA	+		
	MOEFA	NIA				
	Public Address System	Required	Provided	MR		
0.	Automatic Sprinkler System	- do -	- do -	MR		
	Basement	7		,		
	 Upper Floor 	Required	Provided	MR		
	 Sprinkler above false ceiling 	MIA		l'a		
1.	Internal Hydrants	MA		-		
	 Size of riser/down-comer 					
	Number of hydrapta and fi	NIA				
	Number of hydrants per floorHose Box	NIA				
2.	Yard Hydrants	NIA				
	and the second s		J			
	Total number of hydrantsHose Box		One			
3.	AND AND ADDRESS OF THE PARTY OF		One			
	Pumping Arrangements • Ground Level					
	Discharge of main Pump	MIA	-	The second secon		
	Head of Main pumpNumber of main pumps	NIA		the area of the second		
	> Jockey Pump out put	NIA	-	Service and the service of the servi		
	> Jockey pump head	MA		The second secon		
	Standby Pump out put	MIA	Comments	The second secon		
	Standby Pump Head	NIA				
	Auto Starting/Manual	NIA				
	stopping	NIA		The service and the interest of the service and the service an		
	bhmg	MIN				

E-2/14, East Patel Norgar, New Delli

		rica Der					
	Pump House Access	NIA					
	 Terrace level 						
	Discharge of pump	450 LPM	450LPM	N 0			
	Head of the pump		The same of the sa	MR			
	Power Supply	20 M Required	20 M Provided	MR			
	Auto Starting of pump			7.77			
14.	Captive Water Storage for fire fighting						
	 Underground tank capacity 	NIA	1				
	Draw-off connection	NIA	5				
	Fire service inletAccess to tank		Provided				
		NIA	70007424				
	 Overhead Tank capacity 		Socottr	MR Being No			
15.	Exit Signage.	Required	Provided	MR, Being Old MR			
16.	Provision of Lifts.						
	Pressurization of Lift Shaft	1110					
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch 	NIA	permittee.				
		NIA	-				
			Provided	MR			
	 Lift Signage 	Required	-do-	MR			
		-do-	- do -	MR			
17.	Standby power supply	Required - do - Required	Provided	mR			
18.	Refuge Area.						
	> Total Area						
	Location	MA	No. of the last of	~			
	-(MIN					
19.	Fire Control Room						
	 Detector System Panel 	NIA					
	 Flow Switch Panel 		Para and a second secon	Same			
	 PA System Panel 	NIA	- Carlo				
	Batter backup	NIA	0	^			
	 Building Floor Plans 	Required	Provided	MR			
		AIA	-	•			
20.	Special Fire Protection System for Protection of special Risks, if any:	MIA					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Name H.L. Aneja
Designation Divisional Officer

Name P.S. Dahiya

Designation Asstt. Divisional Officer.