GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 4062

Dated: 30/10/12

FIRE SAFETY CERTIFICATE

Certified that the Prince Polonia Guest House, 2325-26, Tilak Gali, Chuna Mandi, Pahar Ganj, New Delhi-110055 comprised of basement (storage), ground floor (reception + travel counter and show room), 1st floor (06 guest rooms + 06 rooms used by owner as residence), 2nd floor (13 guest rooms), 3rd floor (10 guest rooms) and 4th floor (rooms sealed by MCD), total 29 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2512 dated 12-08-2009. The premises was re-inspected by the officer concerned of this department on 19-10-2012 in the presence of Sh. Brij Mohan Sethi (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 29 guest rooms with effect from 3 s 1 s2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .3.9. 1.9.11.2. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi–110049 w.r.t. No.82514-15/Addl.C.P./Lic.(H) New Delhi dated 06-09-2012
- 2. M/s Prince Polonia Guest House, 2325-26, Tilak Gali, Chuna Mandi, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTI	ON REPORT	, 2325-26	. Tilak gali			
1	Name & address of the building : Char	na mandi	Pahas Ga	ent april polt			
7	1/0050						
3.							
4	The state of the s						
Ĵ,	125/2						
6.							
7.	And the second section of the section of the second section of the section of the second section of the section of th	Commence of the Commence of the Section Commence of the Commen	man of the control of the second section of the second section of the second section of the second section of				
8.	Name of the Inspecting Officers: Dhasm vis singh yadav. Name and designation of officers						
		Pai Bait	notion Sethe				
9.		tarting year	THE RESIDENCE OF THE PARTY OF T				
			Lico(N) dated N.	DU the 06-09-12			
S.	Minimum Standards on fire		Provided at site	Remarks			
No	prevention and fire safety U/R 33	Requirement		MR/NMR			
	Access to building	Of the control of the public of the control of the		PSS ABOA.			
1	Road width	- N.A-	06 Mtrs Approx.	m·R			
	Gate width	-N.A-					
	• Width of internal road	- N.A -					
2	Number, Width, Type & Arrangement of Exits						
aller or or service and or or service and or or other parts of the contract of	a. Number of staircases	And the second s					
	Upper Floors	01	01	M.R.			
1	Basements	0	02	M-R			
and the same of	b Width of staircases						
	Upper Floors	80 Cm8,	122 Cms. to 129 Cms	M.R			
	Basements	80 Cms.	(1) ISE CMS.	MR.			
100	c. Protection of exits		(11) LIS (ms.				
and and a second	Fire check door	-N-A -					
Martin Address	Pressurization	-NA -					
Î	e. No. of continuous staircases to terrace	01	0	MR			
	g. Width of Corridor	-MA-					
1	h. Door Size	NA-					
super to				contd=			

Prince Polonia, quest House, 2325-26, Tilak gali, chuna mandi, palar Gaus, new Delli-110005

Ci	ompartmentation.				
material distribution of	 Fire check door 	- M.A -			
) y (manufacture)	 Sealing of electrical shafts 	- N.A-			
, y care y care y	 Fire Rating of shaft door 	- N.A -			
	Water Curtain	- MA -			
	 Fire Dampors 	_ N.A-			
5	Smoke Management System.				
Acceptance of a second con-	• Basements	30 a/c per hour	Exhaust fans Natural westelatie	M.R	
many and specimen and designation	• Upper floors	12 a/c per hour	national ventilation	n M.K	
	Fire Extinguishers				
AND ASSESSED.	• Total numbers	12 NO8.	12 NO8.	M.R	
-	• Types	-	12 NOS. ABC TYPE & CO. Type YES.	M·R	
	 IS marking 	ISI marked	yes.		
-	First-Aid Hose Reels.				
and the second	 Total numbers on each floor 	01	01	M.R	
	 Length of hose reel hose 	30 m	Provided	m.R	
	Nozzle diameter	5 mm	Provided	M.R.	
	Automatic fire detection and alarming system.				
,	 Type of detectors 	- N.A -		# 	
	Location of Main Panel	-N.A -			
	• Location of Repeater Panel	-N.A -			
,	Alternate source of power	-N.A-			
	Hooters' Location	-N.A -			
8	MOERA	ye8	fsovided.	M.R	
9	Public Address System.	YEE	Provided.	M.R	
10	Automatic Sprinkler System.				
A 1988 NO. 10	 Basement 	Yes	Provided	MR	

Prince Polonia guest Horse, 2325-26, Tilak gali, chuna mandi, palar Grand, new Delli-1/0055.

	The controlled and indicated to the explication of the control or the control of			
	 Upper Floor 	-N.A-		
and the second second second	 Sprinkler above false ceiling 	-N.A -		FANCE F. de Caración Calendar Calendar Company Company Company Company Company Company Company Company Company
11	Internal Hydrants		:	
	Size of riser/down-comer	- N.A -		
	 Number of hydrants per floor 	-N.A-		
	• Hose box	- N.A -		
	Vard Hydrauts.	1-10-41		
	• Total number of hydrants	1 1		
	Hose Box	-N.A -		an a a a
1.1	Pumping Arrangements.			depth file and pro-
	Ground Level	-NA -		Comparison of the colonial state and colonial to the colonial state of the colonial stat
	Discharge of main Pump	-NA-		
	➢ Head of Main pump	-N.A-		The second secon
	> Number of main pumps	-N.A -		
	> Jockey Pump out put			
	Jockey pump head	-N.A -		
	> Standby Pump out put	-N.A-		
	Standby Pump Head	- N.A -		
	> Auto Starting/ Manual	-NA-		
	stopping	-NA-		and the same of th
	> Pump House Access			
	• Terra e level	-NA-		
	> Lischarge of pump	450 LAM	450 LPM.	MR
	Head of the pump	30 Mars.	30 Mtrs.	m.R.
	> Power Supply	Electric	Electric	VN W
	> Auto Starting of pump		switch Provided	M.R.
14	Captive Water Storage for fire fighting	ng.	a grand fell	
	Underground tank capacity			
	> Draw-off connection	-N.A-		

frênce Polonia quest House, 2325-26, Tilak gali, chuna mandê, Palaq Gans, New Delle -1/0055

William Company	The state of the s	A commence of the contract of	
	Yes	frovided	M.R
	- N.A-		The second secon
• Overhead Tank capacity	5000 lites	8 5000 lites	MR
Exit Signage.	yes	Provided.	MR
Provision of Lifts.			and the state of t
Pressurization of Lift Shaft	- H.A -		The second secon
 Pressurization of Lift lobby 	- N.A -		
* Communication In lift Car	and the state of t	0 - 11 1	-A A
 Fireman's Grounding Switch 	The state of the s	Provided	M.R
* Lift Signage	Yes	Provided	M.R
	Yes	Poorided	M.R
The state of the s	JE8.	D. G. Set	M.R
Refuge Area.	The state of the s		A beaution of the beautiful the conference from a 1 of 20 of the property of the
Total Area	-N.A -		The second section is an experience of the second second section of
> Location	-NA-		that the set distinguish an extra the second to the second
Fire Control Room			The state of the s
Detector System Panel	-NA-		31
 Flow Switch Panel 	-NA-		
PA System Panel	- N.A -		
Batter backup	-N-A -		
Building Floor Plans	-N.A.		
	-NA-		AND THE RESERVE AND THE PROPERTY OF THE PROPER
Protection of special Risks, if any:			
	g	e e	
	Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel Flow Switch Panel PAI System Panel Batter backup	Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Pire Control Room Detector System Panel PASystem Panel PASystem Panel Batter backup Building Floor Plans Special Fire:Protection Systems for NA- Special Fire:Protection Systems for	* Access to tank Overhead Tank capacity * Overhead Tank capacity * Exit Signage. Provision of Lifts. * Pressurization of Lift Shaft * Pressurization of Lift lobby * Communication In lift Car * Fireman's Grounding Switch * Lift Signage * Standby power supply * Refuge Area. * Total Area * Location * Detector System Panel * Flow Switch Panel * PA System Panel * Building Floor Plans * Special Fire: Protection Systems for * A. A. * Soco littles * Soco littles * Soco littles * Soco littles * Rowided * PA A. * Poorided * Poorided * Parvided * Panilding Floor Plans * Poorided * Panilding Floor Plans * Special Fire: Protection Systems for * A. A. * A. A. * A. A. * A. A. * Building Floor Plans * Special Fire: Protection Systems for * A. A. * Building Floor Plans * Special Fire: Protection Systems for * A. A. * A. A. * A. A. * A. A. * Building Floor Plans * Special Fire: Protection Systems for * A. A. *

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi safety Service Rules 2010/ issue shortcomings as noted at serial numbers.

Prince Polonia quest mouse, 2325-26, Pilak gali, Arina mandi, Palar Gans, New Delli-110055 Signature of the Enspecting Officer Signature of the Inspecting Officer Name Dhazm vis singh yadou Name Designation pesistant Divisional office (certeal) Do Genteal) Submitted please.

N