GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/OFS/MS/EH/2013/205

Dated 11 01/13

FIRE SAFETY CERTIFICATE

Chief Fire Officer
Delhi Fire Service

Copy to-

- The Deputy Health Officer,
 Shahdara (South) Zone, EDMC,
 Health Department, Shahdara South Zone,
 Karkardooma, Delhi
- Mr. Devender Thapa
 Pind Balluchi Reataurant,
 410, Karkardooma Village, Delhi 96.

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This NOC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. Basement shall be used as per BBL 1983.

INSPECTION REPORT

1. Name & address of the building : Pind Balluchi Restaurant, 410, Karkardooma Village, Vikash Marg,

Delhi-96

2. Building is comprised of

: Basement, G+2

3. Type of Occupancy

: Assembly

4. Type of Case

: Renewal

5. Details of Previous NOC

: F6/DFS/MS/EH/09/1866 Dated 25.06.09

6. Fire Safety directives No

: Old Circular

7. Date of Inspection

: 22.12.12

8. Name of the Inspecting Officer: ADO Suresh Singh

9. Name of the designation of Officer

From the building side

: Mr. Devender Thapa (Manager)

10. Year of Construction

: 2000

11. .Applicant's letter No

: Nil

11A	Minimum Standards on fire prevention and	Requirement	Provided at Site	Remarks		
S.No	fire	Requirement	Provided at Site	MR/NMR		
3.110	safety U/R33			IVIIV/IVIVIIV		
1.	Access to building			1		
	Road width	6 m	24 m	MR		
	Gate width Width of internal road					
		***************************************		20 at		
2.	Number, Width, Type and Arrangement of Ex	cits	1	L		
San 1	a. Number of Staircases	2 no.	2 no.	MR		
	Upper Floor	other special	1 no.	MR		
	Basement	1 no.	1 no.	Old Accepted		
	B. Width of Staircases		1.1 & 1.2 m	Old Accepted		
	Upper Floor			ata dan and and also die and and also die and and		
	Basement			Old Accepted		
	c. Protection of exits					
	Fire check door					
	Pressurization					
	e. No. of continuous staircases to terrace		and was high sale under outst other order control and other time time.	alle vite des sois vite dell'est des des ses que vite		
	g. Width of Corridor	ver dat selt selt das des son des	was not not not not one one one of the star of the sta			
	h. Door Size	******		0.0		
	11. Door size	1 m		Old Accepted		
3.	Compartmentation. Required Provided					
	Fire check door	1 m 1 m & 1.5 m	AND			
	Sealing of electrical shafts	user man	rans need deep seels seels seels need need need need need need need nee	ero con con son con con con con con con con con		
	Fire rating of shaft door					
	Water curtain	******		***********		
	Fire Dampers	atur ann ann agur atur agus ann ann ann ann ann ann ain aine atur ann ann ann ann	une das une das une cas une das une mis des une mis des une des une	way lays was dies date that had had have been dies date		
4.	Smoke Management System. Provided					
	Basement		Provided	Old Accepted		
	Upper for	acter case report dept responses report report dept report acter acter dept responses report dept responses	provided	Old Accepted		
5.	Fire Extinguisher					
	Total numbers	10 no.	10 no.	MR		
	T types	ABC & Co2	ABC & Co2	MR		
	IS marking	ISI marked	ISI marked	MR		

Pind Balluchi Restaurant, 410, Karkardooma Village, Vikash Marg,

6	First-aid-Hose Reels.						
	Total numbers of each floor	1no.	Provided	MR			
	Length of hose reel hose Nozzle diameter	30 m	Provided	MR			
	1102216 diameter	5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	Heat	Provided	MR			
	Location of main panel Location of repeater panel Alternate source of power	***************************************		*************			
		*******		224 24 24 27 27 20 20 2			
			Provided				
	Hooters's location		***************************************	***************************************			
8	MOEFA	Required	Provided .	MR			
9	Public address System.	***************************************	************	************			
10	Automatic Sprinkler System.						
	basement	Required	Provided	MR			
	upper floor	Required	Provided	MR			
	sprinkler above false ceiling	Required	Provided	MR			
11	Internal Hydrants						
	size of riser/down-comer	100 mm	100 mm	MR			
	Number of hydrants per floor	1 no.	1 no.	MR			
OTTO TO TO THE PARTY AND THE P	Hose Box	1 no.	1 no.	MR			
12	Yard Hydrants N/A						
	Total number of hydrants			*******			
	Hose Box		******				
13	Pumping Arrangements.						
	Ground Level	***************************************	******************	***************			
*	Discharge of main Pump	506000000000000000000000000000000000000	*******	0 0 5 0 7 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
	Head of Main Pump		*************	************			
	Number of main pumps	**********	***************	************			
	Jockey pump out put	180 LPM	180 LPM	Old Accepted			
	Jockey pump head	***********	000000000000000000000000000000000000000				
	Standby pump out put	***********	******	************			
	Standby pump Head		******	************			
	Auto Starting /Manual stopping	**********					
	Pump House Access	**********	>*******				
	Terrace Level		0				
	Discharge of pump	450 LPM	450 LPM	Old Accepted			
	Head of the Pump	40 m	40 m	Old Accepted			
	Power supply	***********	0.01.020.020.020.020	20200040204420			
	Auto Starting of pump						

Pind Balluchi Restaurant, 410, Karkardooma Village, Vikash Marg,

1RN-6

Pind Balluchi Restaurant, 410, Karkardooma Village, Vikash Marg,

Captive Water Storage for Fire Fighting.				
Underground tank capacity	************	***************************************	***************************************	
Draw-off connection	******			
Fire service inlet	***********	******************	*********	
Access to tank	******	6040404040460444	*******	
Overhead Tank capacity	5,000 Liters	5,000 Liters	Old Accepted	
Exit Signage.	Required	Provided	MR	
Provision of Lifts.				
Pressurization of Lift Shaft	AND SET AND ENT THE THE WAS AND THE WAS THE WAS AND THE SET AND THE SET AND THE SET AND THE	we see you was not see out out out the see out out out out out of the see out of	UNITED THE COLUMN TO SERVICE OF THE COLUMN T	
Pressurization of Lift lobby	Judy der Alla aler inter dels des des des des des des des des des de	NATE THE NEW YORK COST THAT THEN THEN THEN THEN THEN THEN THEN AND THEN COST COST.	uper toda sala tala sizer alam alam alam alam sala sala salar sala salar sala	
Communication in lift car	The line was this little littl	that willier data state state.	little face often side date one can east was pain side. The last side	
Firemen's grounding switch	pin die vier der der der der der de de en vier vier de de en de de der der der der der der der der d			
Lift Signage				
Standby power supply		Provided	*******	
Refuge Area N/A				
Total area	There was not not also that the last the last the last the	one win one old for the last last one day to the sale that the	der der von der der der der der sen	
Location	where the most field was about the law size that	with some real state of the sta	The pile can up any con and other can can day	
Fire Control Room	N/A	**************************************		
Detector system panel		444 440 560 600 800 500 600 650 50	************	
Flow switch panel	*****	****************	*****	
PA system panel	*******	**************	***********	
Batter backup	************	***************************************		
Building Floor Plans	*********	*************	**********	
Special Fire Protection systems for	gaer sper rido-ridor cero ridor para labor para baso papa	one are not one and not suit our not one off the late one too one our	Julio bala- Julio ballo Jator deri selen sept mello papi.	
protection of special Risks, if any:				
	Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage Standby power supply Refuge Area Total area Location Fire Control Room Detector system panel Flow switch panel PA system panel Batter backup Building Floor Plans Special Fire Protection systems for	Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage Standby power supply Refuge Area Location Fire Control Room N/A Detector system panel PA system panel Batter backup Building Floor Plans Special Fire Protection systems for	Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage Standby power supply Refuge Area Location Fire Control Room N/A Detector system panel Flow switch panel PA system panel Batter backup Building Floor Plans Special Fire Protection systems for	

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name Suresh Singh

Designation Apo

Do (Hast) Mugh