GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F6/DFS/OS/EH/2013/502

FIRE SAFETY CERTIFICATE

Manglam place, Sector-3 Rohini, Delhi-110085 was granted NOC by this department vide letter no F-6/MS/DFS/EH/2008/3251 Dated 25/11/2008. The premises was re-inspected by the officers concerned of this department on 15/01/2013 in the presence of Sh. D. N.Thakur and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and premises is fit for Assembly occupancy with effect from 05/02/13 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of Delhi Fire Service Rules, 2010.

- 1. Means of escape shall not be kept locked or bolted from outside and shall be easily open able by guests in an event of emergency.
- 2. All employees shall be acquainted with the use and maintenance of all the fire fighting installation/equipments.
- 3. The fire suppression / protection arrangements provided in the restaurant are to minimize losses, if maintained in good working condition. These systems cannot give any guarantee that there will be no fire or losses in the event of one.
- 4. Any loss of life and property due to non-functional of fire safety arrangements and other installations shall be the responsibility of the licensee.
- 5. This report may not in any way be treated as regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>

Issued on 05/02//3 at New Delhi by

Chief Fire Officer Delhi Fire Service

de 9

Dated: 05/02/2013

Copy to:

- The Additional Commissioner of Police (Lic), 1st floor, Police Station, Defense Colony, New Delhi for information
- 2. M/s Mc- Donald's family Restaurant at M2K Manglam place, Sect.3 Rohini, Delhi-110085

	_]	INSPECTION REPORT
1.	Name & address of the building	: Mc Donalds, M2k, Manglam Place, Robin
	Type of Occupancy	: Ascembly
3.	Type of Case	: New Case/ Renewal
4.	Details of previous NOC	: Letter No. F6 075/ms EH 2008 3251 Dated: 23/11/2008
5.	Fire Safety directives letter No	:
6.	Date of inspection	: 15012013
7.	Name of the Inspecting Officers	s: DO(NW)
8.	Name and designation of officer	rs
	from the building side	: Sh. D. N. Thaker Sh. Sahil Thamb
9.	Year of Construction	: 2007
10.	Applicant's letter No.	: Nil dated 17/10/2012

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building		3 5 ⁷ k	r
	Road width	6 mts.	Provided -	MR
	Gate width	old case	Provided "	MR
	 Width of internal road 	NR	NP	

2	Number, Width, Type & Arrangemen	of Exits	1
	a. Number of staircasesUpper FloorsBasements	NIA -	
	b. Width of staircasesUpper FloorsBasements	N/A -	
	c. Protection of exits • Fire check door	A)A	
	 Pressurization e. No. of continuous staircases to terrace g. Width of Corridor h. Door Size 	NIA - NIA -	
	Compartmentation.	Old Case 135290 cms.	MIR
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	Not Required	
	Smoke Management System.		
-	BasementsUpper floors	30 a/c per hour 12 a/c per hour	MR

(在)对一次

5	Fire Extinguishers			
	Total numbers	04	Provided	MIR
	• Types 1-Co2	ISI marked	Borided	MIR
	IS marking		Bonidad	MR
6	First-Aid Hose Reels.	mided wit	to Shopping o	rall)
	Total numbers on each floor	01	Bonded	MIR
	 Length of hose reel hose 	30 m	Provided	MIR
	Nozzle diameter	5 mm	Borrded /	MIR
7	Automatic fire detection and alarming system.			
	Type of detectors	Smoke	Borided	MIR
	 Location of Main Panel 	On Ground Floor	Prided	MIR
	 Location of Repeater Panel 	NR	NP 1	-
	• Alternate source of power	Required	Provided uith s[mall	MIR
	 Hooters' Location 	on G. Floor	Provided	MIR
8	MOEFA	Reprined	Brownded 1	MIR
9	Public Address System.	NR	NP ,	, _
10	Automatic Sprinkler System.			
	• Basement	NIA	NIA	
	• Upper Floor	Required	Provided	MIR
	Sprinkler above false ceiling	NR	NP	/ -

11	Internal Hydrants Provided	with Shoppi	
	Size of riser/down-comer	150 mm	Provided / MR
	 Number of hydrants per floor 	01	Provided mk
	Hose Box	01	Provided MR
12	Yard Hydrants. Availa	usle with sl	ropping Mall
	Total number of hydrants	NR	browided MIR
	Hose Box	NR	Provided MIR
13	Pumping Arrangements. Avail	able with sl	whating mall'
	Ground Level		V
	Discharge of main Pump	2850 LPM)	bonded MR
	Head of Main pump	60 mts.	Provided (M)R
	> Number of main pumps	02	brounded on R
	Jockey Pump out put	180 CM	formided MIR
	> Jockey pump head	60 mm.	Bronded MR
	Standby Pump out put	2850 LPM	Bronded MR
	Standby Pump Head	60 mitrs.	Bronded MR
	Auto Starting/ Manual stopping	Reprined	Provided MR
	> Pump House Access	Required,	Provided MR
	Terrace level	3	9 1
	Discharge of pump	i .	
	> Head of the pump		2 2
:	Power Supply		× 2 32
	> Auto Starting of pump		

			1		
714	Captive Water Storage for fire fighting.	· prailable	with sleepping	mall	
7	Underground tank capacity N	60,000	Provided	MIR	
	➤ Draw-off connection	R	Provided	MIR	
	Fire service inlet	NIR	Provided	MIR	
	> Access to tank	MR	Burided	MIR	
	Overhead Tank capacity	20,000 Us.	Bonded	MR	
15	Exit Signage.	Repuired	Forded	mle	
16	Provision of Lifts.				
	Pressurization of Lift Shaft				
	Pressurization of Lift lobby				
	Communication In lift Car		Required	,	
	Fireman's Grounding Switch	7	Jot Required		
	Lift Signage		d		
17	Standby power supply	Repuised	Provided with	MR	
18	Refuge Area.				
	> Total Area		1 0 and		
	> Location	R	lot Kephis		
19	Fire Control Room				
	Detector System Panel	on G/floor	Prided	MIR	
°	• Flow Switch Panel	MIR	NP		
	PA System Panel	NIR	NP	_	
	Batter backup	Required	Provided	MIR	
	 Building Floor Plans 	NIR	NP		
20	Special Fire Protection Systems for Protection of special Risks, if any:	No		-	
		1			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Name

Designation

Name

Name

Designation

Signature of the Inspecting Officer

Designation