

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.

No. F.6/DFS/MS/EH/2013/ 565

Dated: 12/2/13

FIRE SAFETY CERTIFICATE

Certified that the **McDonalds Family Restaurant** located at 5/76, WEA, Karol Bagh, New Delhi-110005 comprised of ground floor plus one and half upper floors. The restaurant having two exits was issued NOC by this department vide letter No.F.6/DFS/MS/EH/09/2019 dated 08.07.2009 owned/occupied by M/s Connaught Plaza Restaurants Pvt. Ltd. The Restaurant building was re- inspected by the officers concerned of this department on 28.01.2013 in the presence of Sh. Sanjay Mamjaie (Manager) and found that the M/s Connaught Plaza Restaurants Pvt. Ltd have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class Group D assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on..... 12/2/13at New Delhi.



CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

- 1 Sh. Harish Sharma,
M/s Connaught Plaza Restaurants Pvt. Ltd,
13A, Jor Bagh Market, New Delhi-110003.

Following fire safety directives must be adhered to –

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in


8/1/03

N/7 Ground Floor plus One & half upper floor.

INSPECTION REPORT

1. Name & address of the building : McDonald's Family Restaurant, 5776, WEA, Karol Bagh, N.D.O.S.
2. Type of Occupancy : Assembly Building
3. Type of Case : New Case/Renewal
4. Details of Previous NOC : Letter No. F.6/DFS/MS/EH/09/2019 Date 08.07.2009
5. Fire Safety directives letter No. : _____
6. Date of inspection : 28.01.2013
7. Name of Inspecting Officer : D.O H.L. Aneja & A.D.O P.S. Dahiya
8. Name and designation of officers
From the building side : Sh. Sanjay Manjaria (Manager)
9. Year of Construction : Before 2007
10. Applicant's letter No. : MIL dated 13.12.2012

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	• Road width	Accessible	18 mtr	MR
	• Gate width	-	115cms, 175cms	MR
	• Width of internal road	-	-	-
2.	Number, Width, Type & Arrangement of Exits			
a.	Number of staircases			
	• Upper Floors	Two	Two	MR
	• Basements	-	-	No Basement
b.	Width of staircases			
	• Upper Floor	-	110cms to 125cms, 90cms	MR, Being Old Case
	• Basements	-	-	No Basement
c.	Protection of exits			
	• Fire check door	N/A	-	-
	• pressurization	N/A	-	-
d.	No. of continuous staircases to terrace	-	One	-
e.	Width of Corridor	-	102cms	-
f.	Door Size	-	86cms x 205cms	MR, Being Old Case
3.	Compartmentation			
	• Fire check door	N/A	-	-
	• Sealing of electrical shafts	-	Sealed	-
	• Fire Rating of shaft door	N/A	-	-
	• Water Curtain	N/A	-	-
	• Fire Dampers	N/A	-	-
4.	Smoke Management System			
	• Basements	30 a/c per hour	-	No Basement
	• Upper floors	-	Exhaust Ducts are Provided	MR

N/8

		12 a/c per hour	-	-
5.	Fire Extinguishers			
	• Total numbers	12 Nos	Provided	MR
	• Types	CO ₂ , ABC, DCP	- do -	MR
	• IS marking	ISI marked	ISI Marked	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor	One	Provided	MR
	• Length of hose reel hose	30 m	- do -	MR
	• Nozzle diameter	5 mm	- do -	MR
7.	Automatic fire detection and alarming system			
	• Type of detectors	-	Heat & Smoke	-
	• Location of Main Panel	-	Near Reception	-
	• Location of Repeater Panel	-	-	-
	• Alternate source of power	-	D.G. Set of 125 KVA	-
	• Hooters' Location	-	Near Staircase	-
8.	MOEFA	Required	Provided	MR
9.	Public Address System	- do -	- do -	MR
10.	Automatic Sprinkler System			
	• Basement	-	-	NO Basement
	• Upper Floor	Required	Provided	MR, G.F & F.F only
	• Sprinkler above false ceiling	-	-	-
11.	Internal Hydrants			
	• Size of riser/down-comer	100 M.M	100 M.M	MR
	• Number of hydrants per floor	One	One	MR
	• Hose Box	- do -	- do -	MR
12.	Yard Hydrants			
	• Total number of hydrants	One	One	MR
	• Hose Box	- do -	- do -	MR
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	-	-
	➤ Head of Main pump	N/A	-	-
	➤ Number of main pumps	N/A	-	-
	➤ Jockey Pump out put	N/A	-	-
	➤ Jockey pump head	N/A	-	-
	➤ Standby Pump out put	N/A	-	-
	➤ Standby Pump Head	N/A	-	-
	➤ Auto Starting/Manual stopping	N/A	-	-

M/9 5/76, WEA, Karol Bagh,
New Delhi - 110005.


	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	N/A	-	-
		450 LPM	450 LPM, 444 LPM	MR (02 Pumps)
		30M	38M, 30M	MR - do -
		Required	Provided	MR
		-	Both	-
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	N/A	-	-
	➤ Draw-off connection	N/A	-	-
	➤ Fire service inlet	-	Provided	MR
	➤ Access to tank	N/A	-	-
	• Overhead Tank capacity	-	5000 Ltr	MR, Being old Case
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of Lift Shaft	-	-	No Lift
	• Pressurization of Lift lobby	-	-	- do -
	• Communication In lift Car	-	-	- do -
	• Fireman's Grounding Switch	-	-	- do -
	• Lift Signage	-	-	- do -
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	➤ Total Area	N/A	-	-
	➤ Location	N/A	-	-
19.	Fire Control Room			
	• Detector System Panel	N/A	-	-
	• Flow Switch Panel	N/A	-	-
	• PA System Panel	N/A	-	-
	• Batter backup	Required	Provided	MR
	• Building Floor Plans	N/A	-	-
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	-	-

M/10.

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to ^{Renewal} grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ ~~issue shortcomings as noted at serial numbers.....~~

Note:- The Restaurant Building comprised of Ground floor plus one & half upper floors. The first floor is served by two staircases of width 110cms to 125cms and 90cms respectively. The second floor is served by a single staircase. The management has rectify all the shortcomings which is communicated vide our letter No. F.6/MS/DFS/2012/EH/4416 dated 29.11.2012.



Signature of Inspecting Officer

Name H.L. Aneja

Designation Divisional Officer



Signature of Inspecting Officer

Name P.S. Dahiya

Designation Asstt. Divisional Officer.