GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No: F6./DFS/MS/GH/2013/ 265

Dated:

06/05/2017

FIRE SAFETY CERTIFICATE

Certified that the Mumbai Palace Guest House located at 774, Gali Imam Wali, Motor Market, Jama Masjid, Delhi-110006 comprised of ground floor (reception + 03 guest rooms), mezzanine floor (store), 1st floor (04 guest rooms), 2nd floor (04 guest rooms) and 3rd floor (04 guest rooms), owned / occupied by M/s Mumbai Palace guest house have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 22-04-2013 in the presence of Mr. Altaf Hussain (owner) and that the building / premises, is fit for occupancy class Group A Sub Division A-I Lodging or Rooming Houses for 15 guest rooms with effect from -06/crs-4-3--2013 for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .0.6/05/12 at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service Tel:- 011-23414333

Copy to:

E-Mail: cfohq.dlfire@nic.on The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049 w.r.t. No. 1171-73/Addl.C.P./Lic.(H) New Delhi dated 07-1-2013

M/s Mumbai Palace Guest House, 774, Gali Imam Wali, Motor Marketm, Jama 2. Masjid, Delhi-110006

The Dy. Health Officer, NDMC, City Zone, Car Parking, Asaf Ali Road, New 3. Delhi-110002

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Mumbai Palace Guest House, 774, Gali Imam Wali, Motor Marketm, Jama Masjid, Delhi-110006

INSPECTION REPORT

Mumbai Palace Guest House, 774, Gali Imam Wali, 1. Name & address of the building

Motor Market , Jama Masjid, Delhi-110006

2. Type of Occupancy

Lodging House

3. Type of Case

New Case

4. Details of previous NOC

N/A

5. Fire Safety directives Letter No.

N/A

6. Date of inspection

22-04-2013

7. Name of the Inspecting Officer

M.K. Chattopadhyay (A.D.O.), D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side

Mr. Altaf Hussain (owner)

9. Year of Construction

2007

10. Applicant's letter No.

1171-73/Addl.C.P./Lic.(H) dated New Delhi the 07-01-2013

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site (PSS Area)	Remarks MR/NMR (P.S.S Area)	
1.	Access of building Road width	Spl. area	Approx 10 mtrs away		
	 Gate width Width of internal road		Directly Accessible from Road.	MR	
		N/A	N/A	N/A	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircasesUpper floorsBasementsb. Width of staircases	01	01	MR	
		N/A	N/A	N/A	
		80 cms	90 cms.	MR	
	Upper floorsBasements	N/A	N/A	N/A	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	d. No of continuous staircase to terrace	01	01	MR	
	e. Width Of Corridor		125 cms	N/A	
	f. Door Size		200 cms X 80 cms	N/A	
3.	Compartmentation		21/4	N/A	
	Fire check door	N/A	N/A	N/A N/A	
	Sealing of electrical shaftsFire Rating of shaft doorWater Curtain	N/A	N/A	N/A N/A	
		N/A	N/A	IN/A	
		N/A	N/A	N/A	

Mumbai Palace Guest House, 774, Gali Imam Wali, Motor Marketm, Jama Masjid, Delhi-110006

	Fire Dampers	N/A	N/A	N/A		
4.	Smoke managements System	1977	14/74	14/71		
۱.		30 a/c per hour	N/A	N/A		
	BasementsUpper floors	12 a/c per hour	Natural ventilation	MR		
		12 a/c pci floui	Ivatural ventuation	IVIIX		
j.	Fire Extinguishers	10	10	MR		
	• Total numbers	Water Co2 &	10	MR		
	• Types	A.B.C. type	Provided	IVIK		
	IS marking	, and the state of the	11011404	MR		
	13 marking	ISI marked	Provided			
Ó.	First – Aid Hose Reels					
	Total numbers on each floor	01	01	MR		
	 Length of hose reel hose 	30 M	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7.	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	Location of Main Failer Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
3.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	M/R		
10.	Automatic Sprinkler System	Required	TTOVICC	171/1		
10.	Basements	N/A	N/A	N/A		
	• Upper Floor	N/A	N/A	N/A		
	1 1	N/A	N/A	N/A		
11.	Sprinkler above false ceiling Internal Hydrouts	1 1/73	14/74	11/11		
11.	Internal Hydrants	N/A	N/A	N/A		
	Size of riser/down- comer	N/A N/A	N/A N/A	N/A N/A		
	Number of hydrants per floor	N/A N/A	N/A N/A	N/A N/A		
1.0	Hose Box	IN/A	IN/A	IN/A		
12.	Yard Hydrants	NI/A	N.1/A	NI/A		
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level	5.7/1				
	Discharge of main pump	N/A	N/A	N/A		
	Head of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Standby Pump Headauto Staring/Manual stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	Terrace levelDischarge of pump	450 2 22 2				
	Head of the pump	450 LPM	Provided	MR		
	Power supply	40 Mtrs.	Provided.	MR		
	I ower suppry	Required	Provided	MR		
	E.		Syvitab provided at	MR		
	Auto starting of pump		Switch provided at G.F	IVIIX		

N	Aumbai Palace Guest House, 774, Gali	Imam Wali, Mo	otor Marketm, Jama Ma	asjid, Delhi-110006			
	 Under ground tank capacity 	N/A	N/A	N/A			
	Draw of connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	2500 Ltrs.	Provided.(5000 lt)	MR			
15	Exit Signage	Required	Provided	MR			
16.		Provision of Lifts					
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	Communication in lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	> Lift Signage	N/A	N/A	N/A			
17.	Standby power supply	required	D.G. Set provided	MR			
18.	Refuge Area		Aug.				
	Total area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19.	Fire control room						
	Detector system panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Required	One co2 type fire extinguisher provided near electric panel	N/A			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name:- M.K. Chattopadhyay Designation:- ADO (HQ) Name:- Dharamvir Singh Yadav Designation:- D.O. (C.D.)