

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001
Email: cfowz. dlfire@nic.in Tel :- 011-23414250


No.F6/DFS/MS/EH/2013/ 447

Dated : 14/06/13

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name and style of **Starbucks Coffee - Tata Alliance** located at 1-A, Ground Floor, Hamilton House, Connaught Place, New Delhi-110001 owned / occupied by M/s. Starbucks Coffee-Tata Alliance, (A unit of Tata Starbucks Ltd.) the building comprised of ground floor (restaurant), mezzanine plus two upper floors have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service rules, 2010 and verified by the officer concerned of fire service on 27-05-2013 in the presence of Mr. Harpreet Singh Kalsi manager of Restaurant and building is fit for occupancy for restaurant with effect from...14/06/13. for a period of three years in accordance with rule 36 unless renewed under rule 37 of sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 14/06/13. at New Delhi.


(Santokh Singh)
Chief Fire Officer
Delhi Fire Service

Copy to :-

1. M/s **Starbucks Coffee** at ground floor located at 1-A, Ground Floor, Hamilton House, Connaught Place, New Delhi-110001
2. The Medical Officer of Health, Health Department, NDMC, Palika Kendra, New Delhi

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

1. Name & address of the building : **Starbucks Coffee-Tata Alliance, 1-A, Ground Floor, Hamilton House, Connaught Place, New Delhi-110001**
2. Type of Occupancy : Eating House
3. Type of Case : New Case
4. Details of previous NOC : Letter No. N/A dated N/A
5. Fire Safety directives Letter No. : N/A
6. Date of inspection : 27-05-2013
7. Name of the Inspecting Officer : Sh. D.S. Yadav (D.O.)
8. Name and designation of Officer from the building side : Mr. Harpreet Singh Kalsi (manager)
9. Year of Construction : N/A
10. Applicant's letter No. : D-1472/MOH/CSI(Lic)SI-I dated:- 06-03-2013

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	accessible	18 mtrs. Approx.	MR
	• Gate width	N/A	Directly accessible from main road	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	(1) 2 mtrs. Main gate (2) 80 cms. back gate	provided	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	30 a/c per hour	N/A	N/A
	• Upper floors	12 a/c per hour	N/A	N/A

Starbucks Coffee-Tata Alliance, 1-A, Ground Floor, Hamilton House, Connaught Place, New Delhi-110001

5.	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	05 ISI marked	05 Co2 & A.B.C. type. Provided	MR MR MR
6.	First – Aid Hose Reels			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01 30 M 5 mm	01at ground floor Provided Provided	MR MR MR
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A N/A N/A yes Near gate	Smoke/heat Ground floor N/A U.P.S. (15KVA) Near gate	MR MR N/A MR MR
8.	MOEFA	Yes	Provided	MR
9.	Public Address System/Intercom	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basements Upper Floor Sprinkler above false ceiling 	N/A N/A N/A	N/A Provided at ground floor N/A	MR MR N/A
11.	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down- comer Number of hydrants per floor Hose Box 	100 mm. One One	provided At ground floor provided	MR MR MR
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	N/A N/A	N/A N/A
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level Discharge of main pump Head of main pump Number of main pumps Jockey pump out put Jockey pump head Standby Pump out put Standby Pump Head auto Staring/Manual stopping Pump House Access Terrace level Discharge of pump Head of the pump Power supply Auto starting of pump 	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A 450 LPM & 180 LPM 35 Mtrs. Each Electric Yes	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A Provided Provided Electric Provided	N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A MR MR MR MR
14.	Captive water Storage for fire fighting			
	<ul style="list-style-type: none"> Under ground tank capacity Draw of connection Fire service inlet Access to tank Overhead Tank capacity 	N/A N/A N/A N/A 10000 ltrs.	N/A N/A N/A N/A 10000 ltrs	N/A N/A N/A N/A MR
15	Exit Signage	Yes	Provided	MR

Starbucks Coffee-Tata Alliance, 1-A, Ground Floor, Hamilton House, Connaught Place, New Delhi-110001

16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	YES	D.G. Set	MR
18.	Refuge Area			
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Batter backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Designation

Deputy Commr

Signature of the Inspecting Officer

Name

Designation

Yadav
11-06-13

Dheeraj Singh Yadav
Divisional Officer (Central)