GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2013/ SZ/476

Dated: 25/06/13

FIRE SAFETY CERTIFICATE

Certified that the Hotel Dakha International located at 974/01, 975/01 & 976/01, Arya Samaj Road, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus three upper floors, using basement as Hall/Storage (Others property), ground floor as reception, offices, one staff room, shop and 05 guest rooms, first & second floor each having 11 guest rooms respectively, third floor having 09 guest rooms, one hall & pantry for staff (Total 36 guest rooms), A D.G Set and temporary shed on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/2213 dated 27.07.2010 owned/occupied by Sh. Ishwar Singh. The guest house building was reinspected by the officer concerned of this department on 13.06.2013 in the presence of Sh. Amit Kumar (General Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.24626/Addl. C.P./Lic.(H), Dated 25.05.2013)
- 2. Sh. Ishwar Singh (Owner), Hotel Dakha International, 974/01, 975/01 & 976/01, Arya Samaj Road, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPEC	TION REPORT				
	Type of O	Hotel Dakha In	ternational, 974.	976/1, Arya Samai		
	Type of Occupancy Type of Case	CHON REPORT Hotel Dakha International, 974-976/1, Arya Somaj R Residential (Guest House) Korol Bagh, N.S. o.S.				
	· · · · · · · · · · · · · · · · · · ·	New Case/Rebewal				
	. Actors of Lightnes MAC :	Letter No. F.6/DF	S/MS/GH/2010/22/	2/3 Date 27.07.16		
	Our centrez lettel MO :		_	Name and Address of the Address of t		
	Date of inspection Name of Inspecting Officer	13.06.2013 A.D.O P.S. Dahiya				
	in a peculia officer					
	and designation of officers	5	0	Manhandry of Continue Williams (Mr. of St. 1987)		
	From the building side	Sh. Amit Kumar (General Manager) Before 2008				
	9. Year of Construction					
9.	10. Applicant's letter No.	24626/ Add1.	C.P./LIC. (H). da	ted 25.05.2013		
Vo.	Minimum Standards on fire	NBC/BBL	Provided at	Remarks		
	prevention and fire safety U/R 33	Requirement	site	MR/NMR		
	Access to building					
	 Road width 	Accessible	18 mtr	MR		
	 Gate width 	b	190 cms	MR		
	 Width of internal road 	10 to				
"	Number, Width, Type & Arrangement	t of Exits	Section 1997 and 1997			
	a. Number of staircases					
	* Upper Floors	One				
	* Basements	The state of the s	One	MR, Being a Old Cal		
	b. Width of staircases	- do -	-do-	-d6 -		
	 Upper Floor 					
	Basements		123cms to 130cms	MR, Being a Old Cas		
	c Protection of exits		122 Cms	-do -		
	Fire check door		- 10.000			
	 pressurization 					
	d. No. of continuous staircases to					
	terrace					
	e. Width of Corridor		One	-		
	f. Door Size		285cms, 140 cms			
3	Company		87cms x 205cmp			
Act	Compartmentation					
	 Fire check door 	V		A STANDARD CONTRACTOR OF THE STANDARD CO.		
	 Sealing of electrical shafts 		0			
	 Fire Rating of shaft door 		Sealed			
	 Water Curtain 		Box.			
	 Fire Dampers 		-	-		
1.	Smoke Management System			-		
	P. Parameri					
	BasementsUpper floors	30 a/c per hour	are Provided	MR		
			Natural Ventilation	b MR		

	N/6,		and the second	
	V.	12 a/c per		dis.
		hour	-	
	Fire Extinguishers			
	 Total numbers 	Three at each Abo		
	• Types	Co, WCo, ABC	Povided	NOR
	 IS marking 	ISI marked	-do-	MR
	First-Aid Hose Reels	is, marked	151 Marked	MR
	 Total numbers on each floor 	One	0	
	Length of hose reel hose	30 m	Provided	MR
	 Nozzle diameter 	5 mm	-do-	MR
7	Automatic fire detection and alarming	system	-do:	MR
	• Type of detectors	System		
	 Location of Main Panel 		•	
	 Location of Repeater Panel 			+
	 Alternate source of power 		N 0 0 1 1	+ +
	 Hooters' Location 		D.G. Set of 185 KVA	NOR
8.	MOEFA	Roads 1	0	
9,	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	1 - 40 -	-do-	MIR
	• Basement	Required	Partition	
	 Upper Floor 	required.	Provided	MR
	 Sprinkler above false ceiling 			
11.	Internal Hydrants			
	 Size of riser/down-comer 	Carry.	100 m·m	
	 Number of hydrants per floor 		One	-
	 Hose Box 		-do-	
12.	Yard Hydrants		1	
	 Total number of hydrants 	-		
= =	 Hose Box 	_		
13.	Pumping Arrangements			
	 Ground Level 			
	Discharge of main Pump			
	Head of Main pump			
	Number of main pumps			
	> Jockey Pump out put			
	Jockey pump headStandby Pump out put		-	
	Standby Pump Head			
	Auto Starting/Manual			
	stopping		1	

NIZ

97411 - 976/1, Arya Samaj Road, Karol Bagh, New Delli-05.

	/					
	Pump House Access	4	•			
	 Terrace level 					
	Discharge of pump	450 LPM	450LPM	MR		
	Head of the pump	30 M		MR		
	Power Supply	Required	30 M Provided	MIR		
	Auto Starting of pump		*	-		
14.	Captive Water Storage for fire fighting					
	 Underground tank capacity 	-	***			
	Draw-off connection		-	-		
	Fire service inlet	_	-			
	Access to tank	-				
-	 Overhead Tank capacity 	p	5000 CAT	MR. Being a Bld C		
15.	Exit Signage.	Required	Provided	MR, Being a old a		
16.	Provision of Lifts.					
	 Pressurization of Lift Shaft 	-	•			
	 Pressurization of Lift lobby 		PM.			
	 Communication In lift Car 		P	h = 0		
	Fireman's Grounding SwitchLift Signage	0	Provided	MR		
		Required - do -	- do -	MR		
		- 010 -	-do-	MR		
17.	Standby power supply	Required	Provided	MR		
18.						
3	> Total Area					
	Location	4-				
		-				
19.	Fire Control Room					
	 Detector System Panel 	•	-			
	 Flow Switch Panel 			-		
	 PA System Panel 					
	Batter backupBuilding Floor Plans	Rosein	Panille	Dag		
		Kequired	Provided	MR		
			-			
20.	Special Fire Protection System for Protection of special Risks, if any:		-	_		

1

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Name P.S. Dahiyee
Designation Asstt. Divisional Officer.

Signature of Inspecting Officer

Name

Designation