## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No. F6/MS/DFS/GH/2013/ MD2/514

Dated: 04/07/13

## FIRE SAFETY CERTIFICATE

Certified that the **Roma Villa Guest House**, 4055, Kaseruwalan, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 01 guest room), 1<sup>st</sup> floor to 3<sup>rd</sup> floor (02 guest rooms at each floor) and 4<sup>th</sup> floor (01 staff room) total 07 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2010/593 dated 26-02-2010. The premises was reinspected by the officer concerned of this department on 26-06-2013 in the presence of Mr. Sanjay Duggal (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 07 guest rooms with effect from  $\frac{104}{1000} \frac{100}{1000} \frac{1000}{1000} \frac{1000}{1000}$ 

Issued ... 9.4/. 0.7/./3 at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony New Delhi–110049 w.r.t. letter No.21695 Addl.C.P./Lic.(H) New Delhi dated 09-05-13.
- 2. M/s Roma Villa Guest House, 4055, Kaseruwalan, Pahar Ganj, New Delhi-110055 Condition for the validity of fire safety certificate
  - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
  - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
  - 3. The trained fire fighting staff should be available round the clock.
  - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
  - 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Roma Villa Guest House, 4055, Kaseruwalan, Pahar Ganj, New Delhi-110055

**INSPECTION REPORT** 

1. Name & address of the building : Roma Villa Guest House, 4055, Kaseruwalan, Pahar Ganj,

New Delhi-110055

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. F6/DFS/MS/GH/2010/593 dated 26-02-2010

5. Fire Safety directives Letter No. : N/A

6. Date of inspection : 26-06-2013

7. Name of the Inspecting Officer : Sh. M.K. Sharma (A.D.O.)

8. Name and designation of Officer

from the building side : Mr. Sanajay Duggal (owner)

9. Year of Construction : 2010 Starting Year

10. Applicant's letter No. : 21695/Addl.C.P./Lic.(H) dated New Delhi the 09-05-2013

S No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR		
1	and fire safety U/R 33	Requirements	(PSS Area)	(Old Case)		
1.	Access of building	T 3.7//				
	Road width	N/A	6 mtrs.	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	<ul> <li>Upper floors</li> </ul>	01	01	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	b. Width of staircases		L			
	<ul> <li>Upper floors</li> </ul>	80 cms	125 cms.	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	c. Protection of exits			1,1,1		
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	d. No of continuous staircase to	01	01	MR		
	terrace					
	e. Width Of Corridor	N/A	N/A	N/A		
	f. Door Size	N/A	N/A	N/A		
3.	Compartmentation	1071	14/71	IV/A		
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
4.	Smoke managements System	1 11/4 4	11111	1 1/ /1		
1.	Basements	30 a/c per hour	N/A	N/A		
	Upper floors	12 a/c per hour	Natural ventilation			
5.	Fire Extinguishers	12 a/c per nour	ivaturar ventriation	MR		
٥.	THE Extinguishers					

MLY

Roma Villa Guest House, 4055, Kaseruwalan, Pahar Ganj, New Delhi-110055 MR 10 Total numbers MR Water Co2 & **Types** A.B.C. type. MR ISI marked Provided IS marking First – Aid Hose Reels 6. MR 01 01 Total numbers on each floor MR Provided 30 M Length of hose reel hose MR Provided 5 mm Nozzle diameter Automatic fire detection and alarming system 7. N/A N/A N/A Type of detectors N/A N/A N/A Location of Main Panel N/A N/A N/A Location of Repeater Panel N/A N/A N/A Alternate source of power N/A N/A N/A Hooters' Location N/A N/A N/A **MOEFA** 8. N/A N/A N/A Public Address System/Intercom 9. 10. Automatic Sprinkler System N/A N/A N/A Basements N/A N/A N/A Upper Floor N/A N/A N/A Sprinkler above false ceiling Internal Hydrants 11. N/A N/A N/A Size of riser/down-comer N/A N/A N/A Number of hydrants per floor N/A N/A N/A Hose Box 12. Yard Hydrants N/A N/A N/A Total number of hydrants N/A N/A N/A Hose Box **Pumping Arrangements** 13. Ground Level N/A N/A N/A Discharge of main pump N/A N/A N/A Head of main pump N/A Number of main pumps N/A N/A N/A N/A > Jockey pump out put N/A N/A Jockey pump head N/A N/A Standby Pump out put N/A N/A N/A Standby Pump Head N/A N/A N/A auto Staring/Manual stopping N/A N/A N/A > Pump House Access N/A N/A N/A Terrace level > Discharge of pump MR 225 LPM Provided > Head of the pump 30 Mtrs. Provided MR Power supply MR Provided Required Auto starting of pump Switch provided at MR . . . . . . . . . . . . . reception Captive water Storage for fire fighting 14. N/A N/A N/A Under ground tank capacity N/A N/A Draw of connection N/A > Fire service inlet N/A N/A N/A Access to tank N/A N/A N/A Overhead Tank capacity MR 2500 ltrs. Provided Exit Signage MR Provided 15 Required Provision of Lifts 16. Pressurization of Lift Shaft N/A N/A N/A N/A Pressurization of lift lobby N/A N/A

NIS

Roma Villa Guest House, 4055, Kaseruwalan, Pahar Gani, New Delhi-110055

L.	dina vina duest House, 4033, itasere	ivididity i dildi odi	3, 11011 2 01111	
7	Communication in lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	D.G. Set	MR
18.	Refuge Area			
	> Total area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire control room			
	Detector system panel	N/A	N/A	N/A
	> Flow Switch Panel	N/A	N/A	N/A
*	PA System Panel	N/A	N/A	N/A
	> Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were test, checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name

Designation

(M. K. SHARMA

Assit. Drv. Of

Egiptor 6-18

9