GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO. F6/DFS/MS/GH/2013/ NDZ/587

Dated: 19/7/13

FIRE SAFETY CERTIFICATE

Certified that Bombay Orient, 941-943 and 945 to 949, Gali Shyam Lal, Matia Mahahl, Zama Maszid, Delhi-6, comprised of Ground floor (Reception + 16 rooms + Office), first floor (19 rooms), second floor (14 rooms + 2 store & 2 staff room), third floor ((11 rooms + 4 store & 3 staff rooms), and terrace floor (DG set + 2 staff rooms + Water tank) Total 60 guest rooms, was granted NOC by this department vide letter No. F.6/MS/DFS/GH/2010/1740, dated 15-06-10. The premises was re-inspected by the officer concerned of this department on 13-07-13 in the presence of Sh. Raizzuddin of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy of 79 guest rooms i.e. Ground floor (Reception + 17 rooms), first floor (20 rooms), second floor (21 rooms), third floor ((21 rooms), and terrace floor (DG set + 2 staff rooms + Water tank) Total 79 Guest rooms with effect from 19/7/13 for a period of -9--- years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on _____at New Delhi by.

(Dr. G.C. Misra) **CHIEF FIRE OFFICER** 9 DELHI FIRE SERVICE

Copy to: -

- 1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
- 2. M/s Bombay Orient, 941-943 and 945 to 949, Matia ahal, Zama Maszid, Delhi-6

Conditions for the validity of fire safety certificate

a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time.

b. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.

The trained fire fighting staff shall be available round the clock.

e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Bombay Orient, 941-943 and 945 to 949, Matia Mahal, Zama Maszid, Delhi-6

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F.6/MS/DFS/GH/2010/1740, dated 15-06-10

5. Fire Safety directives letter No: Nil

6. Date of inspection

: 13-07-2013

7. Name of the Inspecting Officers: Sanjay Kumar Tomar, ADO (SPM)

8. Name and designation of officers

from the building side

:Mr. Raizzuddin

9. Year of Construction

: 1992

10. Applicant's letter No.

:12486-88/Addl C.P./Lic(H) dated 13/03/13

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	 Road width 	Accessible	6 mtr (Aprox)	MR		
	• Gate width	N/A	N/A	N/A		
	• Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	• Upper Floors	One	Two	MR		
	• Basements	N/A	N/A	N/A		
	b. Width of staircases		* ,			
	• Upper Floors	1.25 mtr	1.25 mtr	MR		
	• Basements	N/A	N/A	N/A		
	c. Protection of exits	N/A	N/A	N/A		
	• Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	Required	Provided	MR		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	N/A	N/A	N/A		

	£	
	4	
0		
1		

				.1
2		N/A	N/A	N/A
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	 Sealing of electrical shafts 	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.		11/11	IVA
	• Basements	30 a/c per hour	N/A	27/4
	• Upper floors	12 a/c per hour	IN/A	N/A
		1	N/A	N/A
5	Fire Extinguishers			11/11
	 Total numbers 	32	Provided	MR
	• Types	Water Co2, Co2 & ABC	Provided	MR
	IS marking	ISI marked	Provided	MR
5	First-Aid Hose Reels			IVIIX
	 Total numbers on each floor 	Two	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming	g system.		
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
	MOEFA	Required	Provided	MR
	Public Address System.	Required	Provided	MR
	Automatic Sprinkler System.			
	Basement Unper Flore	N/A	N/A	N/A
	 Upper Floor Sprinkler above false ceiling	N/A*	N/A	N/A
	and to raise centing	N/A	N/A	N/A

Bombay Orient, 941-943 & 9 45-949, Matia Mahal, Jama Maszid 11 **Internal Hydrants** Size of down-comer 100 mm Provided MR Number of hydrants per floor One Provided MR Hose Box One Provided MR 12 Yard Hydrants. Total number of hydrants N/A N/A N/A Hose Box N/A N/A N/A 13 **Pumping Arrangements.** Ground Level N/A N/A N/A Discharge of main Pump N/A N/A N/A ➤ Head of Main pump N/A N/A N/A Number of main pumps N/A N/A N/A Jockey Pump out put N/A N/A N/A Jockey pump head N/A N/A N/A Standby Pump out put N/A N/A N/A Standby Pump Head N/A N/A N/A Auto Starting/ Manual N/A N/A N/A stopping N/A N/A N/A Pump House Access N/A Terrace level N/A N/A Discharge of pump 450 LPM Provided MR Head of the pump 40 M Provided MR Power Supply Required Provided MR Auto Starting of pump N/A Switch Provided MR 14 Captive Water Storage for fire fighting. Underground tank capacity N/A N/A N/A Draw-off connection N/A N/A N/A Fire service inlet N/A N/A N/A Access to tank N/A N/A N/A Overhead Tank capacity 10,000 Ltrs Provided MR 15 Exit Signage. Required Provided MR

Pressurization of Lift ShaftPressurization of Lift lobby	N/A	N/A	N/A			
Pressurization of Lift lobby	DI/A					
	N/A	N/A	N/A			
Communication In lift Car	N/A	N/A	N/A			
Fireman's Grounding Switch	Required	Provided	MR			
Lift Signage	N/A	N/A	N/A			
Standby power supply	Required	DG Set 40 KVA Provided	MR			
Refuge Area.						
Total Area	N/A	N/A	N/A			
Location	N/A	N/A	N/A			
Fire Control Room						
 Detector System Panel 	N/A	N/A	N/A			
• Flow Switch Panel	N/A	N/A	N/A			
 PA System Panel 	N/A	N/A	N/A			
Batter backup	N/A	N/A	N/A			
 Building Floor Plans 	N/A	N/A	N/A			
Special Fire Protection Systems for	Required	Provided one Co2	MR			
Protection of special Risks, if any:		fire extinguisher near				
	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans Special Fire Protection Systems for 	 Fireman's Grounding Switch Lift Signage N/A Standby power supply Required Refuge Area. ➤ Total Area ➤ Location N/A Fire Control Room Detector System Panel Flow Switch Panel PA System Panel N/A PA System Panel Batter backup Building Floor Plans Special Fire Protection Systems for Required 	 Fireman's Grounding Switch Lift Signage N/A Required N/A N/A Standby power supply Required DG Set 40 KVA Provided Refuge Area. ➤ Total Area ➤ Location N/A N/A N/A N/A Fire Control Room Plow Switch Panel Flow Switch Panel PA System Panel N/A Provided one Co2 			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name: SANJAY KUMAR TOMAR

Designation :- Asstt. Div. Officer (SPM)

DO((D) Submitted please.